



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OCD Received
7/21/2020

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/17/20 Operator Logos Operating, LLC API # 3004506808

Property Name RICHARDSON COM 003 Location: Unit N Section 2 Township 27 Range 13
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 163 Intermediate N/A Casing 171 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	173	N/A			Steady Flow	N/A
10 minutes	0	174				Surges	
15 minutes	0	175				Down to Nothing	
20 minutes	0	176				No Flow	X
25 minutes	0	177				Gas	
30 minutes	0	178				Gas and Water	
5 minute SI	1	179				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 1 Intermediate N/A

REMARKS:

By Justin Martinez [Signature] Witness _____
Lease Operator
(Position)