

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTOCD Received
6/24/2020FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well ☐ Oil Well ☒ Gas Well ☐ Other		8. Well Name and No. E W MUDGE 8
2. Name of Operator DJR OPERATING LLC		9. API Well No. 30-045-26217-00-S1
3a. Address 1600 BROADWAY SUITE 1960 DENVER, CO 80202	3b. Phone No. (include area code) Ph: 505-632-3476	10. Field and Pool or Exploratory Area BISTI LOWER GALLUP
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 16 T25N R11W NWSE 1980FSL 1770FEL 36.399090 N Lat, 108.005770 W Lon		11. County or Parish, State SAN JUAN COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	ShutIn Notice
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

DJR Operating LLC is requesting approval to shut-in the subject well pursuant to IM No. NM-2016-017 due to economics resulting from the low price of oil. No equipment will be removed which could affect the capability of the well to produce. The estimated date when the well will be returned to production is dependent on oil prices; therefore, a specific time frame when the well will be returned to production is unknown.

Pursuant to a telecon with Dave Mankiewicz and Joe Killins on May 6, 2020, DJR will schedule a meeting with the BLM on or before February of 2021 to discuss specifics associated with conducting the production verification test required in IM-2016-017 if the well will be shut-in for 12 consecutive months.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #518932 verified by the BLM Well Information System For DJR OPERATING LLC, sent to the Farmington Committed to AFMSS for processing by JOE KILLINS on 06/19/2020 (20JK0637SE)	
Name (Printed/Typed) SHAW-MARIE FORD	Title REGULATORY SPECIALIST
Signature (Electronic Submission)	Date 06/15/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By <u>JOE KILLINS</u>	Title <u>ENGINEER</u>	Date <u>06/19/2020</u>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office <u>Farmington</u>

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Revisions to Operator-Submitted EC Data for Sundry Notice #518932

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	SHUTIN NOI	SHUTIN NOI
Lease:	NMNM036253	NMNM036253
Agreement:		
Operator:	DJR OPERATING LLC 1 ROAD 3263 AZTEC, NM 87410 Ph: 505-632-3476	DJR OPERATING LLC 1600 BROADWAY SUITE 1960 DENVER, CO 80202 Ph: 303-595-7433
Admin Contact:	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476
Tech Contact:	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476	SHAW-MARIE FORD REGULATORY SPECIALIST E-Mail: sford@djrlc.com Ph: 505-632-3476
Location: State: County:	NM SAN JUAN	NM SAN JUAN
Field/Pool:	BISTI LOWER GALLUP	BISTI LOWER GALLUP
Well/Facility:	E W MUDGE 8 Sec 16 T25N R11W NWSE 1980FSL 1770FEL 36.399180 N Lat, 108.006340 W Lon	E W MUDGE 8 Sec 16 T25N R11W NWSE 1980FSL 1770FEL 36.399090 N Lat, 108.005770 W Lon