District I.

1625 N French Dr , Hobbs, NM 88240
District II

1301 W Grand Avenue, Artesia, NM 88210
District III

1000 Rio Biazos Road, Aztec, NM 87410
District IV

1220 S St Francis Di , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office

District Office
7/50 Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application
Type of action: Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the nvironment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances
Operator Williams Operating Co, LLC OGRID #: 120782
Address PO Box 640 / 721 S Main Aztec, NM 87410
Facility or well name Cox Canyon #001B
API Number3004530791 OCD Permit Number
U/L or Qtr/Qtr L Section 16 Township 32N Range 11W County San Juan
Center of Proposed Design: Latitude 36.98200 Longitude -108.00047 NAD □1927 □ 1983
Surface Owner State Private Tribal Trust or Indian Allotment
Temporary Drilling Workover Permanent Emergency Cavitation P&A Lined Unlined Liner type: Thicknessmil LLDPE HDPE PVC Other String-Reinforced Liner Seams Welded Factory Other Volumebbl L x W x D
3
☐ Closed-loop System: Subsection H of 19 15 17 11 NMAC \(\) Type of Operation ☐ P&A ☐ Drilling a new well ☐ Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent)
☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other
Lined Unlined Liner type. Thicknessmil LLDPE HDPE PVC Other
Liner Seams: Welded Factory Other Other
Secondary containment with leak detection Visible sidewalls only Other
S Alternative Method:

Submittal of an exception request is required Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval

6	
Fencing: Subsection D of 19 15.17 11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)	
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church)	hospital,
Four foot height, four strands of barbed wire evenly spaced between one and four feet	
Alternate Please specify BLM Specifications	
7.	
Netting: Subsection E of 19 15 17 11 NMAC (Applies to permanent pits and permanent open top tanks)	
Screen ☐ Netting ☐ Other	
Monthly inspections (If netting or screening is not physically feasible)	
Signs: Subsection C of 19 15 17 11 NMAC	
☐ 12"x 24", 2" lettering. providing Operator's name, site location, and emergency telephone numbers	
_	
Signed in compliance with 19 15 3 103 NMAC	
9	
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required Please refer to 19 15.17 NMAC for guidance	
Please check a box if one or more of the following is requested, if not leave blank:	
Administrative approval(s) Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau	office for
consideration of approval Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval	
10	
Siting Criteria (regarding permitting): 19 15 17 10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the approoffice or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a	priate district pproval.
Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dryi above-grade tanks associated with a closed-loop system.	ing pads or
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank - NM Office of the State Engineer - iWATERS database search, USGS, Data obtained from nearby wells	☐ Yes ⊠ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	☐ Yes ⊠ No
- Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	☐ NA
	☐ Yes ☐ No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	⊠ NA
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock	Yes No
watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application - NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site	
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	☐ Yes ☒ No
adopted pursuant to NMSA 1978, Section 3-27-3, as amended	
- Written confirmation or verification from the municipality; Written approval obtained from the municipality	
Within 500 fect of a wetland - US Fish and Wildlife Wetland Identification map, Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ⊠ No
Within an unstable area - Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources, USGS, NM Geological Society, Topographic map	☐ Yes ⊠ No
Within a 100-year floodplain - FEMA map	☐ Yes ☒ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15 17 9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15.17 9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC Design Plan - based upon the appropriate requirements of 19 15 17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19.15.17 13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number or Permit Number
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15.17 9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19 15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC Previously Approved Design (attach copy of design) API Number. Previously Approved Operating and Maintenance Plan API Number (Applies only to closed-loop system that use above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15 17 9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15 17 10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15 17 11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15 17 11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15 17 11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15 17 11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15 17 12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15 17 11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15 17.13 NMAC
Proposed Closure: 19 15 17 13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19 15.17 13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15 17 13 NMAC

Disposal Facility Name	perations? ial are or may be and/or
Disposal Facility Permit Number Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and of Yes (If yes, please provide the information below) No Required for impacted areas which will not be used for future service and operations Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC 17. Siting Criteria (regarding on-site closure methods only): 19 15.17 10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source material provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications of demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	perations? ial are or may be and/or
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and on the equivalency are required areas which will not be used for future service and operations. Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC. Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC. Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC. Siting Criteria (regarding on-site closure methods only): 19 15.17 10 NMAC. Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source material provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications ademonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	ial are or may be and/or
Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source material provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications of demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	or may be and/or
Siting Criteria (regarding on-site closure methods only): 19 15.17 10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source materi provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	or may be and/or
Ground water is less than 50 feet below the bottom of the buried waste	☐ No
- NM Office of the State Engineer - iWATERS database search, USGS, Data obtained from nearby wells	
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS; Data obtained from nearby wells NA	_
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS, Data obtained from nearby wells □ Yes NA	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) - Topographic map, Visual inspection (certification) of the proposed site	⊠ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application - Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	⊠ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application - NM Office of the State Engineer - iWATERS database, Visual inspection (certification) of the proposed site	⊠ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality, Written approval obtained from the municipality	⊠ No
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map, Topographic map, Visual inspection (certification) of the proposed site	⊠ No
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	⊠ No
Within an unstable area - Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources, USGS, NM Geological Society, Topographic map	⊠ No
Within a 100-year floodplain - FEMA map	No No
On-Site Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19 15 17 11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19 15 17 13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15.17 13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved by the content of the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	NMAC

Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief	
Name (Print): Title	
Signature Date	
e-mail address Telephone	
OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment)	
OCD Representative Signature: Approval Date: 8/5/20[[_
Title: OCD Permit Number:	
Closure Report (required within 60 days of closure completion): Subsection K of 19 15.17 13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.	vort.
☐ Closure Completion Date:6/2/2010	
Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems onl If different from approved plan, please explain	y)
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more two facilities were utilized. Disposal Facility Name Disposal Facility Permit Number Disposal Facility Name Disposal Facility Permit Number Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations?	
Yes (If yes, please demonstrate compliance to the items below) \(\bigcap \) No Required for impacted areas which will not be used for future service and operations \(\bigcap \) Site Reclamation (Photo Documentation) \(\bigcap \) Soil Backfilling and Cover Installation \(\bigcap \) Re-vegetation Application Rates and Seeding Technique	
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a chemark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location Latitude Longitude NAD 1927 1983	eck
Operator Closure Certification:	
I hereby certify that the information and attachments submitted with this closure report is true, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.	
Name (Print)Vanessa Fields TitleEH&S Coordinator	
Signature Date10-14-10	
e-mail address vanessa, fields@williams.com Telephone. 505-634-4209	



Explanation & Production FO Box 640 Aztec NM 81137 505/634 4219 505/634 4214 fax

March 10, 2009

Mr Mark Kelly Bureau of Land Management Farmington Field Office 1235 La Plata Hwy Farmington, NM 87401

Sent via Certified Mail

RE Notification of Production Pit Closure
Rule 19 15 17 13 NMAC
Production Pits associated Natural Gas Development
Operated by Williams Production Co. LLC

Pursuant to Rule 19 15 17 13 NMAC this correspondence is to notify the Bureau of Land Management, Farmington Field Office, of Williams Production LLC's (Williams) intent to clean close all production pits on the attached list of wells operated with the District in San Juan County and Rio Arriba County, New Mexico Closure will follow the plan included with this correspondence

Thank you for your consideration. If there are any questions or additional information is requested, please contact me at (505) 634-4209.

Respectfully submitted.

Holly C Perkins EH&S Specialist

Encl Williams Production Pit Inventory List (Federal wells)

San Juan Basin - New Mexico Assets Below-Grade Tank Closure Plai

cc Environmental Fils

Below-Grade Tank Removal
Closure Flan

in a cordance with Rule 19.15.17.13 NMAC, the following plan describes the general closure requirements of below-grade tanks (BGT) on Williams Production Co. LLC. (WPX) locations in the San Juan Basis of New Mexico. This is WPX's standard closure procedure for all BGTs regulated under Rule 19.15.17 NMAC and operated by WPX. For those closures which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

Fursuant to 19.15.17.13 (A) NMAC. WPX will initiate closure of any BG1 should any one of these conditions occur.

- The Division requires closure because of imminent danger to fresh water, public health or the
 environment.
- The integrity of the BGT fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19-15-17-12 (A)(5) NMAC.
- WPX chooses to take the BG1 out-of service due to operational needs. Closure under these
 conditions will be closed within 60 days of cessation of the BG1's operation.
- BGIs installed prior to June 16, 2008 that do not meet the requirements under 19.15.17.1.1.1(6).
 NMAC, and WPX chooses not to retrofit or upgrade. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

- Prior to initiating any BGT Closure except in the case of an emergency. WPX will review County Tax Records for the current surface owner of record. The surface owner of record will be notified of the intent to close the PGT by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the surface owner of record will be notified as soon as practical.
- 2 Notice of Closure will be given to the Aztec District effice hetween 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following
 - a Operators Name (WPX)
 - b. Well Name and API Number
 - c Location (USTR)
- All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary fractank). The well will be temporarily shut in until the rerouting is completed.
- All produced water will be removed from the BGT following discharge-pipe rerouting Produced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BGT site. Rosa Unit SWD #1 (Order SWD-916. API, 30-039-27055). Rosa Unit #94 (Order SWD-3RP-1003.0. API 30-039-23035), Jillson Fed. SWD #001 (Order R10168/R10168A, API 30-039-25465), Middle Mesa SWD #001 (Order SWD-350.0, API 30-045-27004), and/or Basin Disposal (Permit. NM 01-0005).

Solids and studges will be shoveled and tor vacuumed out for disposal at Envirotech (Permit Nontber NM 01-001)

WP+ will be tain prior approval from NMOCD to dispose recycle rease or reclaim the BGT and provide documentation of the disposition of the BGT in the closure report. Size materials will be recycled or reased as approved by the Division. Fill erglass tanks will be energy cut up or shiedded, and EPA cleaned for disposal as solio waste. Tiner materials will.

be cleaned without solk or contaminated material for disposal as solid waste. Finerglass tanks and liner materials will meet the conditions of paragraph 1 subsection D of 19.15.9.712. NMAC. Disposal will be at a licensed disposal facility, presently San Joan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

- Any equipment associated with the RGT that is no longer required for some other purpose following the closure will be removed from the location.
- 1 Collowing removal of the tank and any liner material, a five point composite sample will be taken of the excavation and tested per 19.15.17.13(F)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is wet, discolored or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Form C-141.

Table 1 Closure Criteria for BGTs

Components	Testing Methods	Closure Limits (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2
BILX	EPA 5W-846 Method 8021B or 8260B	50
TF'H	El A SW-846 Method 418 1(1)	100
Chlorides	EPA SW-846 Method 300 1111	250'71

[&]quot; Method modified for solid woste

- 9 If the Division and/or WPX determine there is a release. WPX will comply with 19.15.3.116 NMAC and 19.15.1.19 NMAC.
- 10 Upon completion of the tank removal, the excavation will be backfilled with non-waste earthen material compacted and covered with a minimum of one foot of top soil or background thickness whichever is greater and to existing grade. The suitace will be re-contoured to match the native grade and prevent ponding.
- For those partions of the formar pit area no longer required for production activities. WEX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un impacted) consisting of at least three native plant species including at least one grass but not including natious weeds and maintained that cover through two successive growing scasons. Repeat seeding or planling will be continued until successful vegetative growth occurs. Note—If a surface owner agreement requires reseeding or other surface restoration that do not meet re-vegetarion requirements at 19.15.17.13 LNMAC then WPX will submit the proposed alternative with written documentation that the surface owner agrees to the ofternative, for Division approval.
- For those portions of the former pit area required for production activities reseeding will be done at well abandonment, and following the procedure noted above

Closure Report

All closure activities will include proper accumentation and will be submitted to OCD within 60 days of the BGI closure and Closure keport using Division Form C 144. The Report will include the totlowing

- Froot of Closure Horice in three owner is NMOCT
- Backhing & Cover installar.
- Site Diogram with conformate.
- Available hispequantepar

- - Continuation Sampling Απαίντις οι κεναίτ
- Exposal facility trainers and Ferrit trimberts.
- Application kate & Seeding technique
- Photo Documentation of Reciphiatics

 $ilde{ ilde{ ilde{}}}$ If background concentration of Chlorides greater than 250 mg/kg, than higher concentration will be used for closure.

WELLS W/FEDERAL SURF MGT	API	FM1	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
	e a per a l'annue de commune de commune de l'annue						
COX CANYON UNIT #001	3004511397	BLANCO MV	16N	32N	11W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mile
COX CANYON UNIT #001A	3004522086	BLANCO MV	16C	3211	11VV	BG1	HDPF SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
COX_CANYON-UNIT_#001B	3004530791	_BLANCO MY	16[35 <i>M</i>	11W		HDPELSECONDARY LINER
COX CANYON UNIT #001C	3004532023	BLANCO MV	16E	3211	11W	BG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
COX CANYON UNIT #003	3004511495	BLANCO MV	91	32N	11VV	BG1	HDPE SECONDARY LINER
COX CANTON UNIT #003A	3004522088	BLANCO MV	9P	32N	1 1 VV	BGI	DBL WALL STEEL
COX CANYON UNIT #003B	3004530871	BLANCO MV	9,1	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #004	3004511368	BLANCO MV	21A	32N	11W	BGT	DBL WALL STEFL
COX CANYON UNIT #004A	3004522093	BLANCO MV	21P	32N	11W	BG1	DBL WALL STEEL
COX CANYON UNIT #004B	3004532186	BLANCO MV	215	32N	11W	BGT	DBL WALL STEEL
COX CANYON UNIT #005	3004511326	BLANCO MV	21K	32N	11VV	BGT	DBL WALL STEFL
COX CANYON UNIT #005A	3004522094	BLANCO MV	21L)	32N	1 1 VV	BGT	DBL WALL STEFL
COX CANYON UNIT #005B	3004532142	BASIN DK / BLANCO MV	2111	3214	11W	BGT	DBL WALL STEEL
COX CANYON UNIT #005C	3004533493	BLANCO MV	21F	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #006	3004511463	BLANCO MV	16A	32N	11W	BG1	DBI WALL STEEL
COX CANYON UNIT #006A	3004522095	BLANCO MV	161	3214	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #006B	3004532693	BLANCO MV	16B	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #006C	3004532733	BLANCO MV	16O	32N	11W	HG1	DBI WALL STEEL
COX CANYON UNIT #007	3004511455	BLANCO MV	17G	32N	11W	FGP	DBL WALL STEEL
COX CANYON UNIT #007A	3004522091	BLANCO MV	170	32N	11W	BGT	DBL WALL STEEL
COX CANYON UNIT #007C	3004533018	BASIN DK	17K	32N	11W	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20-mil
COX CANYON UNIT #008	3004511492	BLANCO MV	81	32N	11W	BG1	HDPE SECONDARY LINER
COX CANYON UNIT #008A	3004522096	BLANCO MV	17H	32N	11W	BGT	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20-mil
COX CANYON UNIT #008B	3004532080	BLANCO MV	8P	32N	11VV	BG1	HDPE SECONDARY LINER
COX CANYON UNIT #008C	3004531187	BLANCO MV	17P	3211	11W		FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
COX CANYON UNIT #009A	3004522092	BLANCO MV	20D	32N	11W	BGT	FIBERGLASS TANK W/BANDED 20-mil HDPE SECONDARY LINER
COM CANYON UNIT #009B	3004533926	BASIN DK / BLANCO MV	20B	32N	11W	BG1	DBL WALL STEEL
COX CANYON UNIT #009C	3003933851	BASIN DK / BLANCO MV	20F	3211	11W	BG1	DBL WALL STEEL
COX CANYON UNIT #013	3004521489	BLANCO PC	20A	32N	11W	BG1	FIBERGLASS TANK WBANDED 20-mil HDPE SECONDARY LINER

WELLS W/FEDERAL	والمرافقة المتحدث المتحرب والمتحدث المتحدث الم	nengam ingawajingmapan, menghamad dawida ng					
SURF MGT	API	FMT	SEC	TWN	RNG	PIT TYPE	
COX CANYON UNIT #023 COM	3004522537	BLANCO PC	17C	32N	11W	BG1	FIBERGLASS TANK W/BANDED 20-mill HDPE SECONDARY LINER
COX CANYON UNIT #025	3004522572	BLANCO PC	9O	32N	111/	BG1	FIBERGLASS TANK WBANDED 20-mil HDPE SECONDARY LINER
COX CANYON UNIT #200	3004527878	BASIN FIC	બ	3214	1100	BGT	FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
COX CANYON UNIT #200A	3004532126	BASINFIC	90	3211	11W	BGI	FIBERGLASS TANK w/BANDED 20-mil HDPE SECONDARY LINER
COX CANYON UNIT #203	3004527872	BASIN FIC	17A	32N	1 IW	BG1	FIBERGLASS TANK W/BANDED 20-mil HDPE SECONDARY LINER
MADDOX #001	3004511487	BLANCO MV	10N	32N	11W	BG1	DBI WALL STEEL
MADDOX #001A	3004523539	BLANCO MV	10P	32N	11W	BGT	DBL WALL STEEL
NM 32-11 #001	3004511309	BLANCO MV BASIN DK /	200	3211	11W	BGT	DBL WALL STEEL
NM 32-11 #001B COM	3004532024	BLANCO MV BASIN DK /	203	32N	1 1 W	BGI	DBL WALL STEEL
NM 32 11 #001C COM	3004532804	BLANCO MV	201.	32N	11W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20-mil
NM 32-11 #002 COM	3004511380	BLANCO MV	19A	32N	1 I W	BG1	HDPE SECONDARY LINER
NM 32 11 #002A COM	3004529017	BLANCO MV	190	3211	11W	BGI	DBI WALL STEEL
NM 32-11 #002B COM	3004532670	BLANCO MV	191	3211	111/	BGT	DBI WALI STEFI
NM 32-11 #002C COM	3004533077	BLANCO MV	19G	32N	11W	BG1	DBI WALL STEEL
ROSA UNIT #001 SWD	3003927055	SWD BASIN DK /	231	31N	06W	BGI	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #001E	3003925411	BLANCO MV BLANCO MV /	11+	31N	06W	BGT	HDPE SECONDARY LINER
ROSA UNIT #005A	3003925407	ROSA PC BASIN DK /	26F	31N	06W	BGT	DBI WALL STEEL
ROSA UNIT #005B	3003926927	BI ANCO MV	26B	3111	06W	BGI	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #005Y	3003926078	BLANCO MV BLANCO MV /	26H	3111	OGW	BG1	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #008	3003907944	ROSA PC BLANCO MV /	26M	31N	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #008	3003907944	ROSA PC BLANCO MV /	26M	31N	06W	BGI	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #008A	3003925430	ROSA PC	26D	31N	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #008C	3003926944	BLANCO MV	26N	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
900# TIMU A2OS	3003907975	BLANCO MV BASIN DK /	11K	31N	06W	BGT	HDPE SECONDARY LINER
ROSA UNIT #009A	3003925584	BLANCO MV	11C	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
8e00# TINU A2O!	3003927042	BI ANCO MV	11E	3111	0677	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
OSA UNIT #010B	3003926556	BLANCO MV	13N	31N	06W	BG1	HDPE SECONDARY LINER
OSA UNIT #010C	3003926918	BLANCO MV	13N	31N	()6W	BGT	DBL WALL STEEL
OSA UNIT #U100	3003926556	BLANCO MV	13N	31N	06W	BG1	DBL WALL STEEL

WELLS W/FEDERAL						and an analysis of the second	
SURF MGT	API	FM1 BLANCO MV /	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
ROSA UNIT #012A	3003925900	ROSA PC BASIN DK /	15J	31N	06W	BGT	DBL WALL STEEL FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #012P	3003926555	BLANCO MV	15P	3111	0617	BGI	HDPE SECONDARY LINER
ROSA UNIT #012C	3003929486	BLANCO MV	15A	31N	0674	SG1	SINGLE WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #013	3003907936	BLANCO MV	31G	3111	05W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #013A	3003926298	BLANCO MV BASIN DK /	31F	31N	05W	BGT	HDPE SECONDARY LINER
ROSA UNIT #013B COM	3003929834	BLANCO MV	31A	31N	05Vv	PGI	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNI1 #014	3003907958	BLANCO MV	23B	31N	06W	BG1	HDPF SECONDARY LINER HBERGLASS TANK WBANDED 20 mil
ROSA UNIT #014A	3003926280	BLANCO MV BASIN DK /	23P	1116	0674	BG1	HDPE SECONDARY LINER
ROSA UNIT #014C	3003930132	BLANCO MV	23H	31N	06W	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #015	3003907946	BLANCO MV	2911	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #016	3003907963	BLANCO MV	14N	3111	06W	BGI	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #016A	3003925496	BLANCO MV	14C	31N	0600	BG1	HOPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #016B	3003926218	BLANCO MV	14M	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #01/A	3003926272	BLANCO MV BASIN DK /	200	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #017B	3003926971	BLANCO MV BLANCO MV /	20J	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #018	3003907960	ROSA PC BLANCO MV /	22H	31N	06W		HDPE SECONDARY LINER
ROSA UNIT #018A	3003925436	ROSA PC	22P	31N	06VV	SGI	DBL WALL STEEL
ROSA UNIT #018B	3003927052	BLANCO MV	220	31N	06W	• • •	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #019	3003907955	BLANCO MV	24K	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #019B	3003926560	BLANCO MV	241	31N	U6W		HDPE SECONDARY LINER
ROSA UNIT #019C	3003929625	BLANCO MV	24D	31N	06Vv	BGT	DBI WALL STEEL
ROSA UNIT #019C	3003929625	BLANCO MV	24D	31N	06VV		DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #020	3003907969	BLANCO MV	14G	31N	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #020A	3003925495	BLANCO MV	14()	31N	06W		HDPE SECONDARY LINER
ROSA UNIT #020B	3003926220	BLANCO MV	14A	31N	06W		DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #020C	3003926221	BLANCO MV	14J	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #021A	3003926121	BLANCO MV	23C	31N	06W		HDPE SECONDARY LINER
ROSA UNIT #021B	3003926554	BLANCO MV	23K	31N	06W		DBL WALL STEEL
ROSA UNIT #02	3003907971	BLANCO MV	18A	31N	05W		FIBERGLASS TANK W/BANDED 20-mill HDPE SECONDARY LINER

WELLS W/FEDERAL							
SURF MGT	API	FMT	SEC	TWN	RNG	PIT TYPE	
							FIBERGI ASS TANK W/BANDED 20 mil
ROSA UNIT #022A	3003926390	BLANCO MY	18C	3114	0574	BGT	HDPE SECONDARY LINER
							FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #023	3003907942	BLANCO MV	29M	31N	05Vv	BGI	HDPE SECONDARY LINER
							FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #023B	3003926553	BLANCO MV	29E	31N	05W	₽G1	HDPE SECONDARY LINER
		BASIN DK /					FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #023C	3003927609	BLANCO MV	29L	31N	05W	BGT	HDPE SECONDARY LINER
1							FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #024	3003907933	BLANCO MV	32M	31N	05W	BGI	HDPE SECONDARY LINER
Į		BASIN DK /					
ROSA UNIT #024A	3003925568	BLANCO MV	32E	31N	05W	SG7	DBL WALL STEEL
		BASIN DK /					FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #024B	3003926630	BLANCO MV	32N	31N	05W	BGT	HDPF SECONDARY LINER
		BASIN DK /					FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #024C	3003926968	BLANCO MV	32C	31N	05W	BG1	HDPE SECONDARY LINER
		BASIN DK /					•
ROSA UNIT #026A	3003925580	BI ANCO MV	32O	31N	05W	SGI	DBL WALL STEEL
	COOK E COOK					-	
ROSA UNIT #026B	3003926788	BASIN DK	32G	31N	05W	SG1	DBL WALL STEEL
	5000020100		020	0,11			FIBERGLASS TANK WIBANDED 20-mil
ROSA UNIT #029	3004511136	BLANCO MV	32H	32N	0674	BG1	HDPE SECONDARY LINER
177,020	5004011100	BASIN DK /	7211	JZIV	(/(/**	(JO)	FIBERGLASS TANK w/BANDED 20-mil
 POSA UNIT #029B	3004530709	BLANCO MV	32B	32N	06W	BGT	HDPE SECONDARY LINER
TOOM ONLY WOZ SE	5004350105	BASIN DK /	JZD	3210	OGVV	ВОТ	THE CE CONSTITUTION
ROSA UNIT #029M	3004529584	BLANCO MV	321	32N	(i6W	BGI	DBL WALL STEEL
TOOM ONLY POZ SBI	2004358504	BASIN DK /	321	3214	CCVV	661	FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #030 COM	2002025670	BLANCO MV	120	214	0677	BG1	HDPE SECONDARY LINER
ROSA ONT #050 COM	3003925570	DEAINGO IVIV	12O	31N	UUVV	DGT	FIBERGLASS TANK wBANDED 20 mil
DCCA LIBIT #0204	20026 20020	121 4415 (2.44)	4044	0.441	04.144	D CO T	HDPE SECONDARY LINER
ROSA UNIT #030A	3003926068	BLANCO MV	12M	31N	06W	BGT	
DOCA HALL NO VAD	0.000.000.000	D) 41/04/4/1/	4611		0.0144	061	FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #030B	3003926601	BLANCO MV	12N	31N	06W	BGT	HDPE SECONDARY LINER
DOO 4 1 1117 40000		51.41.55.14.				r	CONTRACTOR CONTRACTOR
ROSA UNIT #030C	3003929842	BLANCO MV	12P	31N	06W	BGT	DBL WALL STEEL
1						P. 15.5	FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #031	3003926279	BLANCO MV	17C	31N	05Vv	BG1	HDPE SECONDARY LINER
						p.,	FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #031A	3003926346	BLANCO MV	171	31N	05W	BG1	HDPE SECONDARY LINER
		BASIN DK /					FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #031B	3003926579	BLANCO MV	17D	31N	05Vv	BG1	HUPE SECONDARY LINER
							FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #031C	3003926578	BI ANCO MV	17N	3111	05W	BGT	HDPE SECONDARY LINER
		BLANCO MV /					
ROSA UNIT #032	3003925389	ROSA PC	21H	31N	06W	BGI	DBL WALL STEEL
		BLANCO MV /					
ROSA UNIT #032A	3003925417	ROSA PC	21F	31N	06W	BG1	DBL WALL STEEL
		BASIN DK /					FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #032B	3003926771	BLANCO MV	21G	31N	06W	BGT	HDPE SECONDARY LINER
		BASIN DK /					FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #032C	3003927240	BI ANCO MV	21F	31N	0674	BG1	HDPE SECONDARY LINER
							FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #034	3003907984	BLANCO MV	36B	3211	06W	BGT	HDPE SECONDARY LINER
ROSA UNIT #034A	3003926119	BI ANCO MV	361	32N	06W	BGT	DBL WALL STEEL
ROSA UNIT #034A	3003926119	BLANCO MV	36)	32N	06W	SG1	DBL WALL STEEL
							FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #034E	3003926629	BLANCO MV	36J	32N	06W	BGI	HDPE SECONDARY LINER
	3003820023	DETAILOO INIV	000	UEIN			=

ť

WELLS W/FEDERAL SURF MGT	API	FMT	SEC	TWN	DNC	DIT TVDE	CONSTRUCTION MATERIAL
SURF MIG I	API	FIYI I	SEC		KNG	PIT TYPE	FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #034C	3003926969	BLANCO MV	36H	32N	()6W	BG1	HEIPE SECONDARY LINER
ROSA UNIT #035X	3004510996	BLANCO MV	5K	3111	0674	BGT	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #036	3003907977	BLANCO MV	1111	3114	0eW	B(-1	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #036C	3003930182	BLANCO MV	11G	3111	ugW	BGT	HDPF SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #041	3003907981	BLANCO MV BASIN DK /	5K	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDFD 20 mil
ROSA UNIT #041B	3003927014	BLANCO MV	6P	31N	05Vv	BG1	HDPE SECONDARY LINER
ROSA UNIT #044	3003925873	BLANCO MV	35K	32N	W80	BG1	DBI WALL STEEL
ROSA UNIT #044A	3003926161	BLANCO MV	35E	32N	06M	SGI	SINGLE WALL STEEL
ROSA UNIT #044A	3003926161	BLANCO MV	35E	32N	06W	SGI	DBL WALL STEEL FIBERGLASS TANK W/BANDFD 20-mil
ROSA UNIT #044B	3003926685	BLANCO MV	35C	32N	06W	BGT	HDPF SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNII #045	3003923013	BLANCO MV BASIN DK /	Me	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #046A	3003926986	BLANCO MV	80	3111	05W	BG1	HDPE SECONDARY LINER
ROSA UNIT #051	3003920289	BASIN DK	23C	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #053	3003920293	BASIN DK	8B	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-nul
ROSA UNIT #055	3003920923	BASIN DK	341	31N	W30	BGT	HDPE SECONDARY LINER
ROSA UNIT #059 DK	3003923270	BASIN DK	25N	31N	06W		DBL WALL STEEL FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #059 GL	3003923270	UNDES GL	25N	31N	()6W		HDPF SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #060	3004529798	BLANCO MV	41	31N	()6Vv		HDPE SECONDARY LINER
ROSA UNIT #064	3003921703	BASIN DK	29A		05Vv		DBI WALL STEEL
ROSA UNIT #064	3003921703	BASIN DK / BASIN DK /	29A	31N	05W		DBI WALL STEEL
ROSA UNIT #064M	3003925563	BLANCO MV	29F	31N	05W		DBL WALL STEEL FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #065	3003921702	BASIN DK	17A	31N	05W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #066	3003921758	BASIN DK BASIN DK /	13L	31N	06W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #066M	3003925747	BLANCO MV	13F	31N	06W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 2(1-mil
ROSA UNIT #072	3003925509	BI ANCO MV	61	31N	05W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #072A	3003925795	BI ANCO MV	6K	31N	05W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #075	3004529895	BLANCO MV	10l	31N	06W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #075A	3004529854	BLANCO MV DK/UNDES	4C)	31N	06VV		HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #077	3003922538	GL/BLANCO	33L	31N	05W	BG1	HDPE SECONDARY LINER

WELLS W/FEDERAL SURF MGT	API	FMT	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
ROSA UNIT #079	3003922539	BASIN DK / BLANCO MV	22K	3114	06\V	BG1	DBL WALL STEEL
ROSA UNIT #079	3003922539	BASIN DK / BLANCO MV	22K	3114	06W	SGI	OBL WALL SIFEI
ROSA UNIT #079A	3003925412	BLANCO MV / ROSA PC	22E	51N	06W	BG1	DBL WALL STEEL
ROSA UNIT #079B	3003926920	BASIN DK / BLANCO MV	22C	311/	06W	BGT	DBL WALL STEEL
COSA UNIT #079C	3003929902	BLANCO MV	31P	31N	05W	BGT	DBL WALL STEEL
		BASIN DK /					FIBERGLASS TANK W/BANDED 20 B
:OSA UNIT #080	3003922537	BLANCO MV	вĸ	31N	05Vv	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-n
COSA UNIT #080A	3003926413	BLANCO MV	8f	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 n
OSA UNIT #085	3003922778	BASIN DK	20A	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-n
OSA UNIT #085	3003922778	BLANCO MV	20A	31N	0517	BGI	HDPE SECONDARY LINER FIBERGLASS TANK WIBANDED 20-n
ROSA UNIT #085A	3003926314	BLANCO MV	20C	3114	05W	BGT	HDPE SECONDARY LINER
ROSA UNIT #085B	3003930130	BLANCO MV	20D	31#4	05W	BGI	DBI WALL STEEL
880¢ FINU A2OS	30039z2766	UNDES GI	12W	31N	()4Vv	SG1	SINGLE WALL STEEL
OSA UNIT #088	3004525140	BLANCO MV / ROSA PC	8F	31N	()6W	BG1	DBI WALL STEEL
OSA UNIT #059	3003922782	BLANCO MV	34A	32N	06W	BG1	FIBERGLASS TANK WBANDED 20 n HDPE SECONDARY LINER
ROSA UNIT #089A	3003925512	BI ANCO MV	340	32N	06W	EGT	FIBERGLASS TANK WBANDED 20 n HDPE SECONDARY LINER
COSA UNIT #089B	3003926851	PLANCO MV	341	32N	06W	BG1	DBI WALI STEFI
OSA UNIT #089C	3003926674	BLANCO MV	34G	32N	0674	SGI	SINGLE WALL STEEL
OSA UNIT #090 COM	3004525370	BI ANCO MV	33G	32N	06VV	BGT	FIBERGLASS TANK WIBANDED 20-n HDPE SECONDARY LINER
.OSA UNIT #090A COM	3004529259	BLANCO MV	33G	32N	061/7	BG1	DBI WALL STEEL
POSA UNIT #091	3003922780	BLANCO MV	35H	32N	06W		FIBERGLASS TANK WBANDLD 20-n HDPE SECONDARY LINER
OSA UNIT #091A	3003925790	BLANCO MV	35O	32N	06W	SGT	DBL WALL STEEL
OSA UNIT #091B	3003926684	BLANCO MV	35P	32N	06W	BGT	DBL WALL STEEL
OSA UNIT #091C	3003926991	BI ANCO MV	35G	3214	(16W		FIBERGLASS TANK WIBANDED 20-0 HDPE SECONDARY LINER
80% TINU A2O.	3003923265	BASIN DK / GI	231	31N	06W		FIBERGLASS TANK W/BANDED 20-0 HDPF SECONDARY LINER
OSA UNIT #100B	3003929547	BASIN DK / BLANCO MV	210	31N	06W	BGT	DBL WALL STEEL
OSA UNIT #100C	3003929851	BLANCO MV	21K	31N	06VV	BGT	DBL WALL STEEL
OSA UNIT #100F	3003925135	BLANCO MV / ROSA PC	211	31N	06VV		SINGLE WALL STEEL
OSA UNIT #101M	3003925577	BLANCO MV	24F	31N	06W		DBL WALL STEEL
OSA UNIT #108	3003923577	BASIN DK / GL	7G	OHV	05W		FIBERGLASS TANK W/BANDED 20 n HDPE SECONDARY LINER

WELLS W/FEDERAL SURF MGT	API	FM1	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
ROSA UNIT #119	3003925143	BASIN DK	18N	31N	otw	BG1	DBL WALL STEEL FIBERGLASS TANK wBANDED 20-m
ROSA UNIT #125	3003925144	BLANCO MV	13B	3111	06W	BGT	HDPE SECONDARY LINER
ROSA UNIT #125C	3003929843	BLANCO MV BASIN DK /	13G	31N	(16VV	BG1	DBL WALL STEEL FIBERGLASS TANK w.BANDED 20 m
ROSA UNIT #125E	3003925526	BLANCO MV	13.J	31N	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #129	3003926304	BLANCO MV	34E	32N	Wan	5G1	DBL WALL STEFL
ROSA UNIT #129A	3003926297	BI ANCO MV	34k	32N	Wan	BGT	DBI WALL STEEL FIBERGLASS TANK w/BANDED 20-m
ROSA UNIT #137	3003925410	BLANCO MV BLANCO MV /	31K	31N	05W	BG1	HDPE SECONDARY LINER
ROSA UNIT #137A	3003926129	ROSA PC	311	31N	05W	BG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-m
ROSA UNIT #137B	3003927002	BLANCO MV BLANCO MV /	31P	31N	05W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-m
ROSA UNIT #138	3004529147	ROSA PC BLANCO MV /	171	31N	06VV	BG1	HDPE SECONDARY LINER
ROSA UNIT #136A	3004529134	ROSA PC	1711	3111	06W	BGT	DBI WALL STEFI
ROSA UNIT #138B	3004532168	BLANCO MV	1/14	3111	06W	BG1	DBI WALL STEFL
ROSA UNIT #139A	3004529600	BLANCO MV	17M	31N	06W	BGT	DPI WALL STEEL
ROSA UNIT #140	3003925435	ROSA FC	22K	31N	06W	BGT	DBL WALL STEFL
ROSA UNIT #144	3003925421	ROSA FC	26A	3114	06W	BG1	DBI WALL STEEL
ROSA UNIT #145C	3004533086	BLANCO MV	16F	3111	06W	BGT	DBI WALL STEEL
ROSA UNIT #146A	3003925513	BLANCO MV	28N	31N	05W	PG1	FIBERGLASS TANK WBANDED 20 mi HDPE SECONDARY LINER
ROSA UNII #146C	3003930187	BLANCO MV	28B	31N	05W	BG1	DBI WALL STEFI
ROSA UNIT #148	3003925493	BASIN DK	20	31N	06W	BG1	DBI WALL STEEL
ROSA UNIT #148A	3003925776	BLANCO MV	2N	31N	()6W		DBI WALL STEEL
ROSA UNIT #148B	3003926985	BLANCO MV	2P	31N	06W	BG1	FIBERGLASS TANK W/BANDED 20-mi
ROSA UNIT #149	3003925501	BLANCO MV	12G	31N	0644		FIBERGLASS TANK W/BANDED 20 mi HDPE SECONDARY LINER
ROSA UNIT #149A	3003925807	BLANCO MV	12F	3111	0674		DBL WALL STEEL
ROSA UNIT #149B	3003926599	BASIN DK / BLANCO MV	12F	31N	06W		FIBERGLASS TANK W/BANDED 20-m HDPE SECONDARY LINER
ROSA UNIT #150	3004529229	BLANCO MV	32F	32N	06W	BG1	FIBERGLASS TANK W/BANDED 20 m HDPE SECONDARY LINER
ROSA UNIT #150A	3004529592	BLANCO MV	32M	32N	06W	BGI	DBI WALL STEEL
ROSA UNIT #150B	3004530874	BASIN DK / BLANCO MV	32D	32N	06W	BG1	DBL WALL STEEL
ROSA UNIT #150C	3004532157	BLANCO MV	32K	32N	()6W	BGT	DBL WALL STEEL
ROSA UNIT #15	3004529267	BLANCO MV	33C	32N	06W	BG1	DBL WALL STEEL

WELLS W/FEDERAL SURF MGT	API	FMT	SEC	TWN	DAIC:	PIT TYPE	CONSTRUCTION MATERIAL
30KI MOT	AFI	T TY) I	350	IVIN	KNO	PII I I PE	CONSTRUCTION MATERIAL
ROSA UNIT #151A	3004529631	BLANCO MV	33L	32N	06₩	BGT	DBI WALL STEEL
ROSA UNIT #151C	3004532196	BLANCO MV	3311	32N	061/v	EG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #152	3003925494	BLANCO MV	36E	32N	06\V	EG1	HDPE SECONDARY LINER
ROSA UNIT #152A	3003925695	BLANCO MV	36N	3211	06W	BGT	DBI WALL STEEL
ROSA UNIT #152B	3003926631	BI ANCO MV	36C	32N	06W	BGT	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #152C	3003927635	BLANCO MV	361	32N	06VV	EG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #153	3003925524	BLANCO MV	170	31N	05V√	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #153A	3003926329	BLANCO MV BASIN DK /	17A	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #153B	3003927603	BI ANCO MV	171	31N	05W	BG1	HDPE SECONDARY LINER
ROSA UNIT #154	3003925893	BLANCO MV	7N	31N	05V/	BGT	DBL WALL STEEL FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #154A	3003926274	BLANCO MV	7P	311/	05VV	BGI	HOPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mill
ROSA UNIT #156	3004529661	BLANCO MV	9A	3111	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROS7. UNIT #156A	3004529640	BLANCO MV BASIN DK /	91	31N	W80	BGT	HDPE SECONDARY LINER
ROSA UNIT #159 COM	3003925583	BLANCO MV	190	31N	05W	BGT	DBI WALL STEEL FIBERGI ASS TANK w/BANDED 20 mil
ROSA UNIT #159A	3003926273	BLANCO MV	19N	3111	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #15C	3003930111	BLANCO MV BLANCO MV /	29G	31N	05W	RGT	HDPE SECONDARY LINER
ROSA UNIT #160	3003925890	ROSA PC	250	31N	06V7	BG1	DBL WALL STEEL
ROSA UNIT #160A	3003925818	BLANCO MV BASIN DK /	25N	31N	06W		DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #160B	3003926962		251	31N	06W		HDPE SECONDARY LINER
ROSA UNIT #160C	3003929778	BLANCO MV	25J	31N	06W	BGI	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #162	3003926069	BLANCO MV	30K	31N	05W	BG1	HDPE SECONDARY LINER
ROSA UNIT #162B	3003929845	BLANCO MV	30P	31N	05W		DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #163	3003926345	BLANCO MV	74G	31N	06W		HDF'E SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #163A	3003926336	BLANCO MV	240	31N	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #163B	3003929921	BLANCO MV	24B	31N	06W	SG1	DBL WALL STEEL
ROSA UNIT #163C	3003929611	BLANCO MV BASIN DK /	2 4 J	31N	06W		SINGLE WALL STEEL FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #164	3003926151	BLANCO MV	1J	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #164A	3003926080	BLANCO MV BASIN DK /	1.J	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #164E	3003927242	BLANCO MV	1 J	31N	06W		HDPE SECONDARY LINER

WELLS W/FEDERAL SURF MGT	A (7) I	THE	050	70.674.1	0.110	MA AMB	CONCEDUCTION MATERIAL
3011 1101	API	BLANCO MV /	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
ROSA UNIT #165	3003926070	ROSAIC	25F	31N	W80	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 r
ROSA UNIT #165A	3003926150	BLANCO MV BASIN DK /	25B	31N	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #165B	3003926557	BLANCO MV BASIN DK /	25E	3110	06VV	BG1	DBI WALI STEEL
ROSA UNIT #165C	3003926961	BLANCO MV	25G	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20-1
ROSA UNIT #166	3003926275	BLANCO MV	30A	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 (
ROSA UNIT #166A	3003926282	BLANCO MV	30F	31N	05W	BG1	HDFE SECONDARY LINER FIBERGLASS TANK WBANDED 20-1
ROSA UNIT #167A	3004529886	BLANCO MV	A8	31N	06Vv	BGT	HDPF SECONDARY LINER
ROSA UNIT #169	3003926130	BLANCO MV	3J	31N	06W	BG1	DBI WALL STEEL
ROSA UNIT #169A	3003926149	BLANCO MV	31	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20-1
ROSA UNIT #169C	3003927717	BLANCO MV	2M	3111	06Vv	BGT	HDPE SECONDARY LINER
ROSA UNIT #170	3003925851	BLANCO MV	21N	31N	W80	BG1	DBI WALL STEEL
OSA UNIT #171	3003926286	BLANCO MV	/G	3111	05W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20-r
ROSA UNIT #171A	3003926389	BLANCO MV	7G	31N	05W		HDPF SECONDARY LINER FIBERGLASS TANK WBANDED 20-1
ROSA UNIT #171B	3003927013	BLANCO MV	65	31N	05W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-7
OSA UNIT #180	3004529898	BLANCO MV	9N	31N	06W		HDPE SECONDARY LINER
OSA UNIT #180B	3004533134	BLANCO MV	91	3111	06W	BGI	DBL WALL STEEL
OSA UNIT #180C	3004533191	BLANCO MV	9E	31N	06W	BGI	DBI WALL STEEL
OSA UNIT #181	3003926463	BLANCO MV	11K	31N	06VV		DBL WALL STEEL FIBERGLASS TANK W/BANDED 20-n
OSA UNIT #181A OSA UNIT #181C (shared	3003926312	BLANCO MV	15A	31N	W00	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 n
/169C)	3003927714	BLANCO MV	2M	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-n
OSA UNIT #182	3003926283	BLANCO MV	18N	31N	05W		HDPE SECONDARY LINER
OSA UNIT #182A	3003926285	BLANCO MV	18P	31N	05W	BG1	DBL WALL STEFL
OSA UNIT #182C	3003930180	BLANCO MV	18F	31N	05W		SINGLE WALL STEFL FIBERGLASS TANK w/BANDED 20-n
OSA UNIT #183	3003926387	BLANCO MV	19G	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20-n
OSA UNIT #183A	3003926386	BLANCO MV	19F	31N	05W		HDPE SECONDARY LINER
OSA UNIT #183B	3003930087	BLANCO MV BASIN DK /	19B	31N	05W	BGI	DBL WALL STEEL
OSA UNIT #185B	3004532734	BLANCO MV	16F	31N	06W	BG1	DBL WALL STEFL
OSA UNIT #185C	3004534484	BLANCO MV	16F	31N	06W	BG1	DBL WALL STEEL
OSA UNII #18	3003930186	BLANCO MV	21G	31N	05VV	BG1	DBL WALL STEEL

WELLS W/FEDERAL								
SURF MG1	API	FMT	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION N	MATERIAL
ROSA UNIT #231	300 392444 1	RASINTTC	31N	3111	05Vv	SGT S	SINGLE WALL STEEL	
ROSA UNII #335A	3003930222	BASINFIC	053	3111	05Vv	SG1 S	SINGLE WALL STEEL	

t

• •

Meador, Tasha

From: Meador, Tasha

Sent: Wednesday, May 26, 2010 10:41 AM

To: 'Jones, Brad A., EMNRD'

Cc: Lane, Myke; 'Powell, Brandon, EMNRD'; Snyder, Walden

Subject: Request for Review Pit Closure - NM 002A, CC001A, CC001B

Brad:

We need to take the following below grade tanks out of service, and we would like to close/modify these existing BGTs. We request your review and approval to allow closure.

WELLSITE	API	FMT	SEC	TW
New Mexico 32-11				
#002A	3004529017	BLANCO MV	190	32
Cox Canyon 001A	3004522086	BLANCO MV	16C	32
Cox Canyon 001B	3004530791	BLANCO MV	16L	32

Please contact me or Myke Lane if there are any problems or you request additional information. Thanks for your consideration

Tasha Meador

EH&S Coordinator Williams Exploration & Production 721 S Main Aztec, NM

Office: 505-634-4200 Direct:505-634-4241 Fax: 505-634-4205

tasha.meador@williams.com

District I * 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III
1000 Rio Biazos Road, Aztec, NM 87410 District IV 1220 S St Francis Di , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form 1220 South St. Francis Dr. Santa Fe, NM 87505 Release Notification and Corrective Action

			Keid	ease mounic	auvii	and Co	HICCHVE A	CHOII			
						OPERA	ГOR	⊠ Inıtı	al Report [Final Report	
Name of Co	mpany	WILLIAMS	PRODU	CTION, LLC		Contact	Vanessa Fields				
Address				EC, NM 87410	7	Felephone N	No. (505) 634-	4209			
Facility Nan	ne	Cox Canyon	#001B		I	Facılıty Typ	e Well Site		-		
Surface Own	ner: Fede			Minoral Ox	Mineral Owner Lease No.						
Surface Own	nei. Teuc	<u> </u>		Willeral O	WIICI			Lease I	NO.		
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West Line	County		
L	1,7	2221									
	16	32N	11W					L			
Latitude 36.98200 Longitude 108.00047											
				NI A TEI	IIDE A	OF RELI	PACE				
Type of Dalar	nca Na Dal	lease Occurred		NAI	UKL	Volume of		Volume	Recovered		
Source of Rel		case Occurred					our of Occurrence		Hour of Discov	erv	
Was Immedia		Given?			•	If YES, To		<u> </u>	Trour of Blace v	<u></u>	
] Yes □	No 🛛 Not Rec	quired	,					
By Whom?					-	Date and H	our				
Was a Watero	course Rea	iched?					olume Impacting t	he Watercourse			
			Yes 🗵	No		,	, 2				
If a Watercou	irse was In	npacted, Descr	ibe Fully i	* N/Δ							
II a Watercou	iise was iii	inputered, Descr	ioc i uny	14/71							
											
		lem and Reme	dial Actio	n Taken *							
No action req	uirea										
L											
Describe Are	a Affected	and Cleanup	Action Tal	ten *							
N/A											
I IV/A											
				is true and comple							
				nd/or file certain re							
				ce of a C-141 repor							
or the envir	perations	nave raned to a	adequatery	investigate and restance of a C-141 re	mediate enort de	es not reliev	on that pose a thr	eat to ground wate	r, surrace water	numan nearth	
		addition, rvivio		nance of a C-141 is	oport uc	Jes not renev	e the operator or	responsionity for c	omphanee with	any other	
^							OIL CON	SERVATION	DIVISION		
$I = I_{c}$, J.,	>									
Signature \	Signature Constant Leve?										
Printed Name	Vonese	a Fields			1	Approved by District Supervisor					
i inited ivallie	valless	a i icius									
Title EH&S	Coordina	tor				Approval Dat	e:	Expiration	Date.		
E-mail Addre	ss. Vanes	sa fields@will	liams.com		(Conditions of	Approval		Attached [j l	
Date. 10-14	-10		Phon	e. (505) 634-4209	,						

^{*} Attach Additional Sheets If Necessary

Below-Grade Tank Removal Closure Plan

In accordance with Rule 19.15.17.13 NMAC, the following plan describes the general closure requirements of below-grade tanks (BGT) on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard closure procedure for all BGTs regulated under Rule 19.15.17 NMAC and operated by WPX. For those closures which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

Pursuant to 19.15.17.13 (A) NMAC, WPX will initiate closure of any BGT should any one of these conditions occur:

- The Division requires closure because of imminent danger to fresh water, public health or the environment.
- The integrity of the BGT fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19.15.17.12 (A)(5) NMAC.
- WPX chooses to take the BGT out-of-service due to operational needs. Closure
 under these conditions will be closed within 60 days of cessation of the BGT's
 operation.
- BGTs installed prior to June 16, 2008 that do not meet the requirements under 19.15.17.11.1(6) NMAC and WPX chooses not to retrofit or upgrade. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

- 1. Prior to initiating any BGT Closure except in the case of an emergency, WPX will review County Tax Records for the current surface owner of record. The surface owner of record will be notified of the intent to closure the BGT by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the surface owner of record will be notified as soon as practical.
- 2. Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)
- 3. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank, ...). The well will be temporarily shutin until the rerouting is completed.
- 4. All produced water will be removed from the BGT following discharge-pipe rerouting. Produced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BGT site: Rosa Unit SWD #1 (Order: SWD-916, API: 30-039-27055), Rosa Unit #94 (Order: SWD-3RP-1003-0, API: 30-039-23035), Jillson Fed. SWD #001 (Order: R10168/R10168A, API: 30-039-25465), Middle Mesa SWD #001 (Order: SWD-350-0, API: 30-045-27004) and/or Basin Disposal (Permit: NM-01-0005).
- 5. Solids and sludges will be shoveled and /or vacuumed out for disposal at Envirotech (Permit Number NM-01-0011).
- 6. WPX will obtain prior approval from NMOCD to dispose, recycle, reuse, or reclaim the BGT and provide documentation of the disposition of the BGT in the closure report. Steel materials will be recycled or reused as approved by the Division. Fiberglass tanks will be empty, cut up or shredded, and EPA cleaned for disposal as solid waste. Liners materials will be cleaned without soils or contaminated material for disposal as

solid waste. Fiberglass tanks and liner materials will meet the conditions of paragraph 1 subsection D of 19.15.9.712 NMAC. Disposal will be at a licensed disposal facility, presently San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

- 7. Any equipment associated with the BGT that is no longer required for some other purpose, following the closure will be removed from the location.
- 8. Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and tested per 19.15.17.13(E)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is wet, discolored or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Form C-141.

Table 1: Closure Criteria for BGTs

Components	Testing Methods :	ে (Closure:Limits (mg/kg) 🔆
Benzene	EPA SW-846 Method 8021B or 8260B	- 0.2
BTEX	EPA SW-846 Method 8021B or 8260B	50
TPH	EPA SW-846 Method 418.1(1)	100
Chlorides	EPA SW-846 Method 300.1(1)	250(2)

⁽¹⁾ Method modified for solid waste.

- 9. If the Division and/or WPX determine there is a release, WPX will comply with 19.15.3.116 NMAC and 19.15.1.19 NMAC.
- 10. Upon completion of the tank removal, the excavation will be backfilled with non-waste earthen material compacted and covered with a minimum of one foot of top soil or background thickness whichever is greater and to existing grade. The surface will be recontoured to match the native grade and prevent ponding.
- 11. For those portions of the former pit area no longer required for production activities, WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: If a surface owner agreement requires reseeding or other surface restoration that do not meet the revegetation requirements of 19.15.17.13.1 NMAC then WPX will submit the proposed alternative with written documentation that the surface owner agrees to the alternative, for Division approval.
- 12. For those portions of the former pit area required for production activities, reseeding will be done at well abandonment, and following the procedure noted above.

Closure Report:

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the BGT closure on a Closure Report using Division Form C-144. The Report will include the following:

- Proof of Closure Notice (surface owner & NMOCD)
- Backfilling & Cover Installation
- Site Diagram with coordinates
- Available Inspection reports

- Confirmation Sampling Analytical Results
- Disposal Facility Name(s) and Permit Number(s)
- Application Rate & Seeding techniques
- Photo Documentation of Reclamation

⁽²⁾ If background concentration of Chlorides greater than 250 mg/Kg, then higher concentration will be used for closure.

Production Pit: Fiberalass Below-Grade Tank

Although these tanks have performed well to protect the public health, welfare and environment, in accordance with Rule 19.15.17.13.A (4) NMAC, Williams will removed all BGTs constructed of fiberglass by June 16, 2013. These tanks do not meet the construction/design standards specified in 19.15.17.11 (1-4). The following plans describes the general design and construction (D&C) and Operations and Maintenance (O&M)of these production pits used on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico.

Design and Construction Plan

The pit is located as close as possible to the well and associated production/process equipment to minimize surface disturbance. The excavation bottom and sidewalls were compacted prior to installation of the pit. The BGT consisted of single-wall fiberglass tank following appropriate API and industry codes, placed in a 20-mil High-Strength Polyethylene resin (Permeability Rating – 0.041 USPerms), and the liner banded to the tanks. A 2" Sch-40 PVC riser was placed between the tank and liner as a leak-detection inspection port. See the attached Schematic and liner spec sheet. The pit is protected from runon by the construction of a compacted earthen berm. Fencing is constructed to protect livestock/wildlife as specified by the federal Surface Management Agency or, if not federal land/minerals requirements. WPX posts a well sign in accordance with the federal Surface Management Agency and rule 19.15.3.103.

Operations and Maintenance Plan

- 1. WPX only allows produced liquids meeting the RCRA exemption for O&G wastes to be stored in the SGT. WPX will not discharge or store any hazardous waste as defined under RCRA 40CFR 261 and 19.15.1.7.W(3) NMAC in any temporary pit. Produced water is disposed by evaporation or transport any of the following NMOCD approved facilities depending on the well location: Basin Disposal, Inc in Bloomfield, New Mexico (Permit # NM-01-005), Williams Rosa SWD#1 (Permit # SWD-916), Williams Rosa #94 (Permit # SWD-758), Burlington Resources Jillson SWD#1 (Permit #R10168A), or other NMOCD approved water disposal facilities. WPX maintains sufficient freeboard for to prevent overtopping. Discharges to the pit will be shutoff if the liquid level does not provided sufficient free-board and liquid removal can not be scheduled in a timely manner. Any oil or hydrocarbon collecting on the pit is removed. Saleable condensate is returned to the sales tank. Slop oil from compression is recycled with Safety Kleen, Farmington, NM or Hydropure, Aztec, NM (No Permit Required).
- 2. If the tank integrity is compromised:
 - a. All discharges will be shut off to the pit.
 - b. All liquids will be removed as soon as possible but no more that within 24 hours of discovery
 - c. WPX will notify and report to NMOCD as follows:
 - i. If the release is less than 25 bbls, the Aztec District Office by phone or email within 48-hours of discovery and repair.
 - ii. If the release is suspected to be greater than 25 bbls, the Aztec District Office and the Environmental Bureau Chief by phone for immediate verbal notification pursuant to 19.15.3.116.B (1)(d).
 - d. Written Spill/Release reports will be submitted on Form C-141 per 19.15.3.116.C NMAC within 15 days to the Aztec District Office.
- 3. Berms around the perimeter of the pit, shall be maintained as protection from run-on.
- 4. WPX will inspect the BGT pit monthly. Electronic copies of the inspections will be kept at the WPX San Juan Basin office for a minimum of five years following completion. Copies of the inspections will be available to NMOCD upon request.

Production Pit: Below-Grade Tank Closure Plan

In accordance with Rule 19.15.17.13 NMAC, the following plan describes the general closure requirements of below-grade tanks (BGT) on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard procedure for all out-of-service BGTs used to store produced liquids during production operations at gas wells operated by WPX.

For those closures which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized. All closure activities will include proper documentation and will be submitted to OCD within 60 days of the pit closure on a Closure Report using Division Form C-144. The Report will include the following:

- Plot Plan (Pit Diagram)
- Available Inspection reports

- Sampling Results
- Waste disposal documentation

ļ

General Plan Requirements:

- 1. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank ...). The well will be temporarily shut in until the rerouting is completed.
- 2. All produced water will be removed from the BGT following discharge-pipe rerouting. Produced water will be disposed of by injection at one of the Williams Production Rosa Unit Salt Water Disposal wells: Rosa SWD #1 (API: 30-039-27055) I-23-31N-06W Permit SWD-916 or Rosa Unit #94 (API: 30-039-23035) K-16-31N-05W, Permit SWD-758.
- 3. Notice of Closure will be given to the landowner or SMA, and the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)
- 4. The BGT and all associated materials will be removed, and recycled, reused, or disposed. of in a Division-approved facility. All materials that can not be recycled or reused will be treated a solid waste and will be disposed of at a licensed disposal facility (probably San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426).
- 5. Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and tested per 19.15.17.13(B)(1)(b) NMAC. In the event that the criteria are not met (See Table 1), a release will be reported following Rule 116 and impacted soils will be excavated and hauled to Envirotech Landfarm near Bloomfield, NM (NMOCD Permit NM-01-0011). Approval to haul will be requested of the Aztec District office prior to initiation.

Table 1: Closure Criteria for BGTs

Components:	Testing Methods	Closure Limits (mg/kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2
BTEX	EPA SW-846 Method 8021B or 8260B	50
TPH	EPA SW-846 Method 8015 M(Full Range)*	100
	or Method 418.1	
Chlorides	EPA SW-846 Method 300.1	250

^{*} Preferred method

- 6. Upon completion of the tank removal and any necessary soil remediation, the excavation will be backfilled with non-waste earthen material compacted to native and covered with a minimum of one foot of top soil. The surface will be re-contoured to match the native grade.
- 7. For those portions of the former pit area no longer required for production activities, WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) or Land owner as part of a surface use agreement or APD are Division-appröved methods unless notified by the Division of their unacceptability.
- 8. For those portions of the former pit area required for production activities, re-seeding will be done at well abandonment, and following the procedure noted above.

Production Pit: Fiberglass Below-Grade Tank

Although these tanks have performed well to protect the public health, welfare and environment, in accordance with Rule 19.15.17.13.A (4) NMAC, Williams will removed all BGTs constructed of fiberglass by June 16, 2013. These tanks do not meet the construction/design standards specified in 19.15.17.11 (1-4). The following plans describes the general design and construction (D&C) and Operations and Maintenance (O&M)of these production pits used on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico.

Design and Construction Plan

The pit is located as close as possible to the well and associated production/process equipment to minimize surface disturbance. The excavation bottom and sidewalls were compacted prior to installation of the pit. The BGT consisted of single-wall fiberglass tank following appropriate API and industry codes, placed in a 20-mil High-Strength Polyethylene resin (Permeability Rating – 0.041 USPerms), and the liner banded to the tanks. A 2" Sch-40 PVC riser was placed between the tank and liner as a leak-detection inspection port. See the attached Schematic and liner spec sheet. The pit is protected from runon by the construction of a compacted earthen berm. Fencing is constructed to protect livestock/wildlife as specified by the federal Surface Management Agency or, if not federal land/minerals requirements. WPX posts a well sign in accordance with the federal Surface Management Agency and rule 19.15.3.103.

Operations and Maintenance Plan

- 1. WPX only allows produced liquids meeting the RCRA exemption for O&G wastes to be stored in the SGT. WPX will not discharge or store any hazardous waste as defined under RCRA 40CFR 261 and 19.15.1.7.W(3) NMAC in any temporary pit. Produced water is disposed by evaporation or transport any of the following NMOCD approved facilities depending on the well location: Basin Disposal, Inc in Bloomfield, New Mexico (Permit # NM-01-005), Williams Rosa SWD#1 (Permit # SWD-916), Williams Rosa #94 (Permit # SWD-758), Burlington Resources Jillson SWD#1 (Permit #R10168A), or other NMOCD approved water disposal facilities. WPX maintains sufficient freeboard for to prevent overtopping. Discharges to the pit will be shutoff if the liquid level does not provided sufficient free-board and liquid removal can not be scheduled in a timely manner. Any oil or hydrocarbon collecting on the pit is removed. Saleable condensate is returned to the sales tank. Slop oil from compression is recycled with Safety Kleen, Farmington, NM or Hydropure, Aztec, NM (No Permit Required).
- 2. If the tank integrity is compromised:
 - a. All discharges will be shut off to the pit.
 - b. All liquids will be removed as soon as possible but no more that within 24 hours of discovery
 - c. WPX will notify and report to NMOCD as follows:
 - i. If the release is less than 25 bbls, the Aztec District Office by phone or email within 48-hours of discovery and repair.
 - ii. If the release is suspected to be greater than 25 bbls, the Aztec District Office and the Environmental Bureau Chief by phone for immediate verbal notification pursuant to 19.15.3.116.B (1)(d).
 - d. Written Spill/Release reports will be submitted on Form C-141 per 19.15.3.116.C NMAC within 15 days to the Aztec District Office.
- 3. Berms around the perimeter of the pit, shall be maintained as protection from run-on.
- 4. WPX will inspect the BGT pit monthly. Electronic copies of the inspections will be kept at the WPX San Juan Basin office for a minimum of five years following completion. Copies of the inspections will be available to NMOCD upon request.

Production Pit: Below-Grade Tank Closure Plan

In accordance with Rule 19.15.17.13 NMAC, the following plan describes the general closure requirements of below-grade tanks (BGT) on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard procedure for all out-of-service BGTs used to store produced liquids during production operations at gas wells operated by WPX.

For those closures which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized. All closure activities will include proper documentation and will be submitted to OCD within 60 days of the pit closure on a Closure Report using Division Form C-144. The Report will include the following:

- Plot Plan (Pit Diagram)
- Available Inspection reports

- Sampling Results
- Waste disposal documentation

General Plan Requirements:

- 1. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank ...). The well will be temporarily shut in until the rerouting is completed.
- 2. All produced water will be removed from the BGT following discharge-pipe rerouting. Produced water will be disposed of by injection at one of the Williams Production Rosa Unit Salt Water Disposal wells: Rosa SWD #1 (API: 30-039-27055) I-23-31N-06W Permit SWD-916 or Rosa Unit #94 (API: 30-039-23035) K-16-31N-05W, Permit SWD-758.
- 3. Notice of Closure will be given to the landowner or SMA, and the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)
- 4. The BGT and all associated materials will be removed, and recycled, reused, or disposed, of in a Division-approved facility. All materials that can not be recycled or reused will be treated a solid waste and will be disposed of at a licensed disposal facility (probably San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426).
- 5. Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and tested per 19.15.17.13(B)(1)(b) NMAC. In the event that the criteria are not met (See Table 1), a release will be reported following Rule 116 and impacted soils will be excavated and hauled to Envirotech Landfarm near Bloomfield, NM (NMOCD Permit NM-01-0011). Approval to haul will be requested of the Aztec District office prior to initiation.


Table 1: Closure Criteria for BGTs


Components:	.Testing/Methods	Glosvie dimils (mg/kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2
BTEX	EPA SW-846 Method 8021B or 8260B	50
TPH	EPA SW-846 Method 8015 M(Full Range)*	100
	or Method 418.1	
Chlorides	EPA SW-846 Method 300.1	250

^{*} Preferred method

- 6. Upon completion of the tank removal and any necessary soil remediation, the excavation will be backfilled with non-waste earthen material compacted to native and covered with a minimum of one foot of top soil. The surface will be re-contoured to match the native grade.
- 7. For those portions of the former pit area no longer required for production activities, WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) or Land owner as part of a surface use agreement or APD are Division-approved methods unless notified by the Division of their unacceptability.
- For those portions of the former pit area required for production activities, re-seeding will be done at well abandonment, and following the procedure noted above.

Cox Can on #1








Cox Canyon #1B





separator





EPA METHOD 8015 Modified Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

Client:	WPX	Project #	04108-0137
Sample ID:	BGT Removal	Date Reported:	07-21-10
Laboratory Number:	55200	Date Sampled:	07-16-10
Chain of Custody No:	9986	Date Received:	07-19-10
Sample Matrix:	Soil	Date Extracted:	07-20-10
Preservative:		Date Analyzed:	07-20-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

ND - Parameter not detected at the stated detection limit

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, References:

SW-846, USEPA, December 1996.

Comments: Cox Cyn #1B

5796 US Highway 64 Farmington NM 87401 | Ph (505)632-0615 Fr (800)362-1879 Fy (505) 632-1865 | Jah@appyrotech.inc.com | appyrotech.inc.com



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client: Sample ID: Laboratory Number: Sample Matrix: Preservative: Condition:	QA/QC 07-20-10 QA/0 55198 Methylene Chlor N/A N/A	•	Project # Date Reported: Date Sampled: Date Received: Date Analyzed: Analysis Reque		N/A 07-21-10 N/A N/A 07-20-10 TPH
Gasoline Range C5 - C10 Diesel Range C10 - C28	i-Cal Date 05-07-07 05-07-07	I-Cal RF: 9.9960E+002 9.9960E+002	C-Cal RF: 1.0000E+003 1.0000E+003	% Difference 0.04% 0.04%	Accept. Range 0 - 15% 0 - 15%
Blank Conc. (mg/L - mg/Kg) Gasoline Range C5 - C10 Diesel Range C10 - C28 Total Petroleum Hydrocarbons		Concentration ND ND ND		Detection Limit 0.2 0.1 0.2	
Duplicate Conc. (mg/Kg) Gasoline Range C5 - C10 Diesel Range C10 - C28	Sample ND ND	Duplicate ND ND	% Difference 0.0% 0.0%	Accept. Range 0 - 30% 0 - 30%	,
Spike Conc. (mg/Kg) Gasoline Range C5 - C10 Diesel Range C10 - C28	Sample ND ND	Spike Added 250 250	Spike Result 251 252	% Recovery 100% 101%	Accept. Range 75 - 125% 75 - 125%

ND - Parameter not detected at the stated detection limit.

References¹

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996

Comments:

QA/QC for Samples 55198-55200; 55211-55213



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	WPX	Project #·	04108-0137
Sample ID:	BGT Removal	Date Reported:	07-21-10
Laboratory Number:	55200	Date Sampled ⁻	07-16-10
Chain of Custody:	9986	Date Received:	07-19-10
Sample Matrix:	Soil	Date Analyzed:	07-20-10
Preservative:		Date Extracted:	07-20-10
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	ND	0.9
Toluene	ND	1.0
Ethylbenzene	ND	1.0
p,m-Xylene	ND	1.2
o-Xylene	1.1	0.9
Total BTEX	1.1	

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
_	Fluorobenzene	100 %
	1,4-difluorobenzene	100 %
	Bromochlorobenzene	100 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments: Cox Cyn #1B

Analyst



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client: Sample ID: Laboratory Number Sample Matrix	N/A 0720BBLK QA/QC 55198 Soil		Project # Date Reported Date Sampled Date Received		N/A 07-21-10 N/A N/A
Preservative ⁻	N/A		Date Analyzed		07-20-10
Condition ⁻	N/A		Analysis		BTEX
Calibration and	I-Cal RF:	C-Cal RF:	%Diff.	Blank	Detect.
Detection Limits (ug/L)		Accept. Ran	ge 0 - 15%	Conc	Limit
Benzene	7 8940E+006	7 9099E+006	0.2%	ND	0.1
Toluene	6 1562E+006	6 1685E+006	0.2%	ND	0.1
Ethylbenzene	4 4104E+006	4 4192E+006	0.2%	ND	0.1
p,m-Xylene	1 0619E+007	1 0640E+007	0.2%	ND	0.1
o-Xylene	3 7124E+006	3 7198E+006	0.2%	ND	0.1
Duplicate Conc. (ug/Kg)	Sample	Duplicate	%Diff.	Accept Range	Detect. Limit
Benzene	ND	ND	0.0%	0 - 30%	0.9
Toluene	ND	ND	0.0%	0 - 30%	1.0
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0
p,m-Xylene	ND	ND	0.0%	0 - 30%	1.2
o-Xylene	ND	ND	0.0%	0 - 30%	0.9
Spike Conc. (ug/Kg)	Sample	Amount Spiked	Spiked Sample	% Recovery	Accept Range
Benzene	ND	50.0	50.0	100%	39 - 150
Toluene	ND	50.0	51.2	102%	46 - 148
Ethylbenzene	ND	50.0	49.5	99.1%	32 - 160
p,m-Xylene	ND	100	101	101%	46 - 148
o-Xylene	ND.	50.0	50.0	100%	46 - 148
o zgrene	110	50.0	30.0	.0070	70-170

ND - Parameter not detected at the stated detection limit

References Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste SW-846, USEPA,

December 1996

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using

Photoionization and/or Electrolytic Conductivity Detectors SW-846, USEPA December 1996

QA/QC for Samples 55198-55200; 55211-55214 Comments:

Analyst



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client [.]	WPX	Project #:	04108-0137
Sample ID:	BGT Removal	Date Reported:	07-21-10
Laboratory Number:	55200	Date Sampled:	07-16-10
Chain of Custody No:	9986	Date Received:	07-19-10
Sample Matrix:	Soil	Date Extracted:	07-20-10
Preservative:		Date Analyzed:	07-20-10
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons 66.5 5.0

ND = Parameter not detected at the stated detection limit.

References: Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Cox Cyn #1B Comments:



EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT

Client:	QA/QC	Project #:	N/A
Sample ID:	QA/QC	Date Reported:	07-20-10
Laboratory Number:	07-20-TPH.QA/QC 55199	Date Sampled:	N/A
Sample Matrix:	Freon-113	Date Analyzed:	07-20-10
Preservative:	N/A	Date Extracted:	07-20-10
Condition:	N/A	Analysis Needed ⁻	TPH

Calibration	I-Cal Date	C-Cal Date	I-Cal RF:	C-Cal RF:	% Difference	Accept. Range
	07-15-10	07-20-10	1,846	1,770	4.1%	+/- 10%

Blank Conc. (mg/Kg) TPH		Concentration ND		Detection Limit 5.0			
Duplicate Conc. (mg/Kg) TPH		Sample 36.9	Duplicate 39.9	% Difference 8.1%	Accept. Range		
Spike Conc. (mg/Kg) TPH	Sample 36.9	Spike Added 2,000	Spike Result 1,770	% Recovery 86.9%	Accept Range 80 - 120%		

ND = Parameter not detected at the stated detection limit.

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water References:

and Waste, USEPA Storet No 4551, 1978

Comments: QA/QC for Samples 55199-55200; 55172-55173



Chloride

Client: WPX Project # 04108-0137 **BGT Removal** Sample ID: Date Reported: 07-21-10 Lab ID# 55200 Date Sampled: 07-16-10 Sample Matrix: Soil Date Received 07-19-10 Preservative: Date Analyzed 07-20-10 Condition: intact Chain of Custody 9986

Parameter

Concentration (mg/Kg)

Total Chloride 5

Reference: U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments: Cox Cyn #1B

Analyst

CHAIN OF CUSTODY RECORD

09986

Client:		1	Project Name / L						ANALYSIS / PARAMETERS													
WITX			Cax Cyr		B				L.	1			1			ı	K —	~	 F		—-т	
Client Address:			Sampler Name:	_					<u>(3</u>)	BTEX (Method 8021)	8											
			WACT SHYDER				8	80	182	ड्ड	_		<u>o</u> .									
Client Phone No.:		(Client No.:						<u> </u>	etpc	thoc	Met	nio		Ţ		3.1	Щ			joo	ntac
\.			04108-			,			TPH (Method 8015)	Š	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion		TCLP with H/P		TPH (418.1)	CHLORIDE			Sample Cool	Sample Intact
Sample No./	Sample	Sample	Lab No.	i .	ample	No./Volume of			표	鱼	8	S.	atio	RC E	CLP	PAH	표	님			amb	amb
Identification	Date	Time			Matrix	Containers	HgCl	HUI	F	'n	>	Œ	Ö	Œ.	F	9	E	0	 		ŝ	S
BGT REMOURE	7/16	1050	55200	Solid	Sludge Aqueous	(-	1	<u>۔۔</u>							س	سسنا			17	4
				Soil Solid	Sludge Aqueous																	1
				Soil Solid	Sludge Aqueous																	
				Soil Solid	Sludge Aqueous																	
				Soli Solid	Sludge Aqueous																	
				Soil	Sludge																	
				Solid Soil	Aqueous Sludge		H	-	-													
				Solid Soil	Aqueous Sludge			-														
				Solid	Aqueous			_	_													
				Soil Solid	Sludge Aqueous																	
			_	Soil Solid	Sludge Aqueous	ı																
Relinquished by: (Signa	ture)	7			Date	Time	B	ceive	ed by:	(Sign	ature)		,					·	 _ D	ate,	Tir	ne
		//	20_		7/19/10	1245	1		$A \cap k$	1/6	٠ ـ	St	<u>'</u>	21 E	2- [1	>		1/10	ate 7/10	10%	45
Relinquished by: (Signa	ture)				1,4,10	1-2-2		eceive	ed by:	(Signa	ature)			74								
Relinquished by: (Signa	ture)						Re	eceive	ed by:	(Signa	ature)	· · · · · · · · · · · · · · · · · · ·										
																		······································	 <u> </u>	 		
				1		env	/ Î	rc	a fr	a (- -	A										
						An	aly	ı 📞 tica	l La	boro	⇒ ¤ itory	# /										
			5796 US	Highway	64 • Farmin	aton. NM 874	101 •	505-6	32-061	5 • lab	o@env	rotec	h-inc.c	om								

							Liner Leak detection			
Date	WellName	Run	Formation	Construction	SGT. BGT, Above	Plastic liner, Double Wall Steel, Bottom Plastic Liner	Y/N	level	level	Comments / Repairs needed
	cox									
Aug-08	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT			2	14	
Sep-08	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT		Yes	2	37	PVC cap on leak detection tube is
· · · · · · · · · · · · · · · · · · ·	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES	2	54	detection tabe is
Nov-08	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES	2	54	
12/31/2008	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		24	
1/28/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		57"	
3/31/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		17"	
4/27/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		5"	
5/27/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		34"	
6/29/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES	1"	15"	
7/31/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		3"	

04-42

			****			Liner	Leak detection		Pit	
Date	WellName	Run	Formation	Construction	SGT. BGT, Above	Plastic liner, Double Wall Steel, Bottom Plastic Liner	Y/N	level	level	Comments / Repairs needed
8/31/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		53"	
	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		36"	
10/30/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		36"	
11/30/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		53"	
12/31/2009	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		38"	
1/1/2010	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES			
2/2/2010	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		29"	
3/31/2010	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		44"	
4/2/2010	CANYON UNIT #001B	04-42	Mesa Verde	FIBERGLASS	BGT	NO	YES		44	

Below-Grade Tank Removal Closure Report

Well:

(Cox Canyon_#001B)

API No:

30-04530791

Location: L-S16-T32N-R11W, NMPM



In accordance with Rule 19.15.17.13 NMAC, the following report describes the general closure of the referenced below-grade tanks (BGT) on Williams Production Co, LLC (WPX) location in the San Juan Basin of New Mexico. The closure follows this WPX's standard closure procedure for all BGTs regulated under Rule 19.15.17 NMAC and operated by WPX. For those closures which do not conform to the standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

Pursuant to 19.15.17.13 (A) NMAC, WPX will initiate closure of any BGT should any one of these conditions occur:

- The Division requires closure because of imminent danger to fresh water, public health or the environment.
- The integrity of the BGT fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19.15.17.12 (A) (5) NMAC.
- WPX chooses to take the BGT out-of-service due to operational needs. Closure under these conditions will be initiated within 60 days of cessation of the BGT's operation.
- BGTs installed prior to June 16, 2008 that do not meet the requirements under 19.15.17.11.1(6) NMAC and WPX chooses not to retrofit or upgrade. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

1. Prior to initiating any BGT Closure except in the case of an emergency, WPX will review County Tax Records for the current landowner of record. The landowner of record will be notified of the intent to closure the BGT by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the landowner of record will be notified as soon as practical.

Williams notified the SMA of its intent to clean close the BGT via Certified Mail on March 10, 2009 see attached. No return receipt required per BLM:FFO/NMOCD MOU dated 5/4/09.

- 2. Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)

Aztec District office was notified of Williams E&P intent to close on (05/26/2010). Email attached.

3. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank, ...). The well will be temporarily shut-in until the rerouting is completed.

Williams closed the BGT used by the Cox Canyon #001B separator and piped all liquids to the Produced Water Storage Tank.

4. All produced water will be removed from the BGT following discharge-pipe rerouting. Produced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BGT site: Rosa Unit SWD #1 (Order: SWD-916, API: 30-039-27055), Rosa Unit #94 (Order: SWD-3RP-1003-0, API: 30-039-23035), Jillson Fed. SWD #001 (Order: R10168/R10168A, API: 30-039-25465), Middle Mesa SWD #001 (Order: SWD-350-0, API: 30-045-27004) and/or Basin Disposal (Permit: NM-01-0005).

<u>Produced water in the BGT prior to closures was removed by vacuum truck and hauled to the Rosa Unit disposal wells listed.</u>

5. Solids and sludges will be shoveled and /or vacuumed out for disposal at Envirotech (Permit Number NM-01-0011).

No solids or sludge required removal prior to excavation and removal of the tank.

6. Williams will obtain prior approval from NMOCD to dispose, recycle, reuse, or reclaim the BGT and provide documentation of the disposition of the BGT in the closure report. Steel materials will be recycled or reused as approved by the Division. Fiberglass tanks will be empty, cut up or shredded, and EPA cleaned for disposal as solid waste. Liners materials will be cleaned without soils or contaminated material for disposal as solid waste. Fiberglass tanks and liner materials will meet the conditions of paragraph 1 subsection D or 19.15.9.712 NMAC. Disposal will be at a licensed disposal facility, presently San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

The fiberglass tank and plastic liner was disposed of at the San Juan Regional Landfill.

- 7. Any equipment associated with the BGT that is no longer required for some other purpose, following the closure will be removed from the location.

 The fiberglass tank and plastic liner were removed offsite. All other piping and equipment remains in use. See attached photo.
- 8. Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and tested per 19.15.17.13(E)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is wet, discolored or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Form C-141.

Table 1. Closore emena for Bots			
Components	Testing Methods	Closure Limits (mg/Kg)	Sample Results (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2	ND
BTEX	EPA SW-846 Method 8021B or 8260B	50	ND
TPH	EPA SW-846 Method 418.1(1)	100	33.2
Chlorides	EPA SW-846 Method 300.1(1)	250(2)	5

Table 1: Closure Criteria for BGTs

- (1) Method modified for solid waste
- $^{(2)}$ If background concentration of Chlorides greater than 250 mg/Kg, then higher concentration will be used for closure
- 9. If the Division and/or Williams determine there is a release, Williams will comply with 19.15.3.116 NMAC and 19.15.1.19 NMAC.

No release detected.

10. Upon completion of the tank removal, and any necessary soil remediation, the excavation will be backfilled with non-waste earthen material compacted to native and covered with a minimum of one foot of top soil or background thickness. The surface will be recontoured to match the native grade.

<u>Pit area backfilled with clean earthen material following sample results. No contaminated soil taken off site.</u> Backfill compacted to avoid settling and pit area remains in use for production operations.

11. For those portions of the former pit area no longer required for production activities, WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) APD are Division-approved methods unless notified by the Division of their unacceptability. If a landowner agreement requires reseeding or other surface restoration that does not meet the revegetation requirements of 19.15.17.13., I then WPX will submit the proposed alternative with written documentation that the landowner agrees to the alternative, for Division approval.

Pit area along with unused portions of well pad interim reclaimed and following P&A entire location to be reclaimed and recontoured in accordance with Surface Management Agency requirements in APD-COAs and per BLM:FFO/NMOCD MOU dated 5/4/09.

12. For those portions of the former pit area required for production activities, reseeding will be done at well abandonment, and following the procedure noted above.
See above notes.

Closure Report:

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the BGT closure on a Closure Report using Division Form C-144. The Report will include the following:

- Proof of Closure Notice (surface owner & NMOCD)
- Backfilling & Cover Installation
- Site Diagram with coordinates
- Available Inspection reports

- Confirmation Sampling Analytical Results
- Disposal Facility Name(s) and Permit Number(s)
- Re-vegetation Application Rate & Seeding techniques
- Photo Documentation of Reclamation