



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-15-11 Operator Burlington Resources API #30-0 39-01198
Property Name San Juan Well No. 30644 Location: Unit 11 Section 24 Township 30 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 134 Intermediate 60 Casing 135 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	63	134	0	134
10 min				0	134
15 min				0	134
20 min				0	134
25 min				0	135
30 min				0	135

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		/
Surges		
Down to Nothing		
Nothing	/	
Gas		/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 3

REMARKS:

This well had 164 lbs in June. Shut in since
Thursday and built to 60 lbs & climbing
BH doing nothing when opened - 2 int. Had blow to 2 min Med flow

By [Signature]

Witness Monica Kuehling

(Position)

at 2.5 soft blow by 4 min at 5-10-
15-20-25-30

E-mail address _____

