



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-15-11 Operator Burlington Res. API #30-0 B-39-26120

Property Name San Juan 30-6 lot Well No. 71E Location: Unit Section 13 Township 38 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 105 Intermediate 1.4 Casing 585 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	1.4	604	0	610
10 min			604	0	614
15 min				0	618
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		/ vapors
Surges		
Down to Nothing		
Nothing	/	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Int. Soft blow to vapors at 5 min. - 10 - 15
BH nothing when opened.

By [Signature]
(Position)

Witness [Signature]

E-mail address

