NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-9-11 Operator Burlington Res. API #30-0 45 07690

Property Name Hartman Well No. 1 Location: Unit ___ Section 31 Township 29 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 82 Intermediate N/A Casing 83 Bradenhead 68

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Int	Csg	INTERM Int	Csg
TIME 5 min	0		92.2		
10 min	0		94.3		
15 min	0		95.0		
20 min	0		95.8		
25 min	0		96.4		
30 min	0		97.0		

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

RECEIVED AUG 2011 OIL CONS. DIV. DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 5 INTERMEDIATE N/A

REMARKS: 16.5" in pit before puff for 2 seconds - 88.7 - clean at 10-15-20-25-30

By Che Tolbe Witness Monica Kuehling

MSO COPC
(Position)

E-mail address ___