



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-16-11 Operator Burlington Resources API # 30-045 07842

Property Name Mangum SRC Well No. 1 Location: Unit 29 Section 29 Township 29 Range 11

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing N/A Intermediate 0 Casing 7 Bradenhead 44

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	7	0	11.5
10 min	0	0	7		
15 min	0	0	7		
20 min	0	0	7		
25 min	0	0	7		
30 min	0	0	10		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		✓
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

No tubing - this well is producing out of casing
pipe that looks like casing is cut. Compressor down last
Vapors at 5-10-15. dead at 20 min. 3 men.

By Cher Zhe

Witness Monica Kahlberg

M90 CORC
(Position)

E-mail address

