



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-27-11 Operator Burlington API #30-0 45-07937
Property Name Dallabetta Well No. 1 Location: Unit Section 20 Township 29 Range 11
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 10 Intermediate N/A Casing 11 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>11</u>		
10 min	<u>0</u>		<u>12</u>		
15 min	<u>0</u>		<u>12</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>RCVD JUL 27 '11</u>
Gas & Water	<u>OIL CONS. DIV.</u>
Water	<u>DIST. 3</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Paft when opened.

By Philp Lingo

Witness Monica Luedtke

(Position)

E-mail address