



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emprd.state.nm.us/ocd/District III/3district.htm](http://emprd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-25-11 Operator Burlington API #30-0 45-08969
Property Name Sanchez Well No. 3 Location: Unit 34 Township 30 Range 10
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 102 Intermediate N/A Casing 109 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	/
Gas	
Gas & Water	
Water	

RCVD JUL 25 '11

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing when opened

OIL CONS. DIV.

By Geoff Davis
Geoff Davis MSO COP
(Position)

Witness Monica Kuchling
DIST. 3

E-mail address _____