



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-5-11 Operator Burlington Res. API #30-0 45-09510

Property Name Howell Well No. 4 Location: Unit 17 Section 30 Township 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 56 Intermediate 137 Casing 68 Bradenhead 14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	14	137	69	0	69
10 min	0	134	69	0	69
15 min	2	128	68	0	69
20 min	4	122	69		
25 min	1	113	69		
30 min	2	78	69		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	/	/
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		/ pucky to smaller
Water	/	

If bradenhead flowed water, check all of the descriptions that apply below:

3# CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____
Milky/clear Int. Milky-mixed w/gas

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 25 INTERMEDIATE 10

REMARKS: BH flowed clear/milky water - clear steady flow at 10-15
20-25-30 3 3/4 barrels Int flowing pucky finger at 5-10-15-20-25-30
BHE Int piped together 1/4" in sm - 15 bands

By Donny Trujillo

Witness Monica Kuehling

(Position)

E-mail address _____

Requested
Schematic - Int.

