



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-16-11 Operator Buckley/Takes API #30-0 45-23366


Property Name Calloway Well No. 2 Location: Unit Section 22 Township 31 Range 11

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 185 Intermediate N/A Casing 191 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		192		
10 min	0		192		
15 min	0		192		
20 min	0		192		
25 min	0		192		
30 min	0		192		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>/</u>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 5

INTERMEDIATE N/A

REMARKS:

11.5 inches in tank at start - at 2 minutes started flowing to tank not even bucket size - Flowed clear water for whole 30 minutes - 4 1/2 buckets to tank

By P. J. Hudson

Witness Mona Kuchling 2/3 barrel

Specialist Area 2
(Position)

E-mail address