



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-10-11 Operator Burlington Res. API #30-0 45-34901
Property Name Randkernon Well No. 1C Location: Unit M Section 23 Township 31 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 115 Intermediate 506 Casing 243 Bradenhead 5.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0	505	243	166	243
10 min	0	505	243	62	243
15 min	0	505	243	18	243
20 min				2.2	243
25 min				0	243
30 min				0	243

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing	✓	
Nothing		
Gas		✓
Gas & Water		
Water		

DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

OIL CONS. DIV.

REMARKS:

BH closed at 5 seconds
Int. - screaming hard blow - less at 7 min. - closed at 10 min.
Surge at 12.45 min. - stopped at 25 min. Steadily light blow at 25.
started building light blow last 5 min.

By [Signature]
Area 2 MGR
(Position)

Witness _____

E-mail address _____

Please Submit a schematic
with all formation tops

Re-test in one month