



AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-19-04 Operator CDX Rio, LLC API # 300390604

Property Name Jicarella Cont 148 #13 Location: Unit C Section 15 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 70* Intermediate _____ Casing 70* Bradenhead 0*

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH- Blowdown	Casing- Monitor	Intermediate- Monitor	Intermediate- Blowdown	Casing- Monitor
5 minutes	<u>0*</u>				
10 minutes					
15 minutes					
20 minutes					
25 minutes					
30 minutes					
5 minute St					


	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow <u>-X</u>		
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0* Intermediate _____

REMARKS:



Harry Whitson
Tech T.P.S
(Position)

Witness

Danell Spear T.P.S

NMOCD Test Area: