



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-21-04 Operator CDX Rio, LLC API # 3003905975

Property Name Jicarilla Cont 148-16 Location: Unit N Section 14 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 215 Intermediate _____ Casing 145 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes					
10 minutes					
15 minutes					
20 minutes					
25 minutes					
30 minutes					
5 minute St					


	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	X	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:



Witness _____

James Simpson
TPS Tech

(Position)

NMOCD Test Area: