



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-23-04 Operator CDX Rio, LLC API # 3003922086

Property Name Jicarilla Cont. 147-3E Location: Unit P Section 6 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 165 Intermediate Casing 180 Bradenhead 55

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH- Blowdown	Casing- Monitor	Intermediate- Monitor	Intermediate- Blowdown	Casing- Monitor		
5 minutes	<u>0</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute St						Water	

90 Sec
X

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black


5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

James Simpson
TPS Tech

(Position)

Witness



NMOCD Test Area: