



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-21-04 Operator CDX RIO LLC API # 3003923786

Property Name Jicarilla Cont. 148-37 Location: Unit C Section 13 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 1250 Intermediate Casing 950 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Flow
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	
5 minutes						Steady Flow
10 minutes						Surges
15 minutes						Down to Nothing
20 minutes						No Flow
25 minutes						Gas
30 minutes						Gas and Water
5 minute St						Water

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:



1 James Angerson Witness _____
TPS Tech
(Position)

NMOCD Test Area: