



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 12/27/04 Operator ELMER DGE RES. API #30-0 39-24373

Property Name MISSY Well No. 3 Location: Unit A Section 35 Township 25N Range 3W

Well Status (Shut-In or Producing) Tubing 11 Intermediate N/A Casing 78 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes				Steady Flow	
10 minutes				Surges	
15 minutes				Down to Nothing	
20 minutes				Nothing <input checked="" type="checkbox"/>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

By David Chapman

Witness \_\_\_\_\_

Pump Operator  
(Position)

E-mail address \_\_\_\_\_

