



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-21-04 Operator CDX RIO, LLC API # 3003960035

Property Name JICARILLA CONT. 148-6 Location: Unit F Section 15 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow	
25 minutes						Gas <u>X</u>	
30 minutes						Gas and Water	
5 minute St						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear 0 Fresh 0 Salty 0 Sulfur 0 Black 0

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS:



Witness _____

James Simpson
TPS. Tech

(Position)

NMOCD Test Area: