## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## RECEIVED

JUL 18 2011

1. Type of Well GAS  1. Type of Well GAS  1. Type of Well GAS  1. Type of Operator  BURLINGTON  RESQUENCES OIL & GAS COMPANY LP  2. Name of Operator  BURLINGTON  Address & Phone No. of Operator  PO Box 4289, Fatmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM  BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Check APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  Type of Action  Now Construction  Now Co		Sundry Notices and Reports on Wells	Far	rmington Field Office au of Land Managemen.
1. Type of Well GAS  2. Name of Operator BURLINGTON RESQUENCES OIL & GAS COMPANY LP  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Subuission Type of Action Now Construction Now Construction Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Subuission Type of Action Now Construction				Lease Number
2. Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY LP  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK 11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Notice of Intent Abandonment Non-Routine Fracturing Casing Repair Non-Routine Fracturing No	1	Type of Well	6	
3. Address & Phone No. of Operator  PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission  Type of Submission  Abandonment  Abandonment  Casing Repair  Casing Repair  Water Shut off Casing Repair  Final Abandonment  Altering Casing  Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.	1.	GAS GAS	0.	•
3. Address & Phone No. of Operator  PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Submission Notice of Intent Abandonment Casing Repair Casing Repair Casing Repair Final Abandonment Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.		A BEOT		111001(81110
3. Address & Phone No. of Operator  PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Submission Notice of Intent Abandonment Casing Repair Casing Repair Casing Repair Final Abandonment Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.	_	OF THE EVED 3	7.	
3. Address & Phone No. of Operator  PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission  Type of Submission  Abandonment  Abandonment  Casing Repair  Casing Repair  Water Shut off Casing Repair  Final Abandonment  Altering Casing  Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.	2.	Name of Operator		San Juan 30-6 Unit
Address & Phone No. of Operator  PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission  Type of Action  Abandonment  Abandonment  Casing Repair  Casing Repair  Water Shut off Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.		DURLING LON CAS COMPANY IN TO CONS. DIV. DIST. S. CO.	,	
3. Address & Phone No. of Operator  PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Submission Notice of Intent Abandonment Casing Repair Casing Repair Casing Repair Final Abandonment Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.		HESOURGES OIL & GAS COMPANY LP	8.	Well Name & Number
PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM  BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  Type of Action  Recompletion  Notice of Intent  Abandonment  Recompletion  New Construction  New Construct	3.	Address & Phone No. of Operator	٠.	San Juan 30-6 Unit 97M
4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM  BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission  Type of Action  Notice of Intent  Abandonment  Recompletion  New Construction  New Construction  New Construction  New Construction  New Tonstruction  Non-Routine Fracturing  Water Shut off  Casing Repair  Altering Casing  Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.			_	
4. Location of Well, Footage, Sec., T, R, M  Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM  BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  10. Field and Pool Blanco MV/Basin DK  BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  Type of Action  Abandonment  Recompletion  Non-Routine Fracturing  Water Shut off  Casing Repair  Altering Casing  Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.		PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	
Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM  BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  Type of Action  Notice of Intent  Recompletion  Recompletion  Plugging  Non-Koutine Fracturing  Casing Repair  Water Shut off  Final Abandonment  Altering Casing  Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.	4.	Location of Well, Footage, Sec., T, R, M		30-039-30944
BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM  11. County and State Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  Type of Action  Notice of Intent  Abandonment  Recompletion  New Construction  Non-Routine Fracturing  Water Shut off  Casing Repair  Casing Repair  Altering Casing  Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.			10.	
Rio Arriba, NM  12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  Type of Action  Notice of Intent  Recompletion  Recompletion  New Construction  Non-Routine Fracturing  Casing Repair  Altering Casing  Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has me the BLM requirements on this reclamation work.		Surface: Unit J (NWSE), 1491' FSL & 1559' FEL, Section 27, T30N, R7W, NMPM		Blanco MV/Basin DK
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  Type of Action  Abandonment Abandonment Abecompletion Non-Routine Fracturing Casing Repair Final Abandonment Altering Casing Conversion to Injection  13. Describe Proposed or Completed Operations  The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.		BH: Unit H (SENE), 2192' FNL & 752' FEL, Section 27, T30N, R7W, NMPM	11.	
Type of Submission Notice of Intent Abandonment Notice of Intent Recompletion New Construction Non-Routine Fracturing Vater Shut off Final Abandonment Altering Casing The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has me the BLM requirements on this reclamation work.				Rio Arriba, NM
The subject well was drilled and completed in (2011) and (Burlington Resources) has recently completed the interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.  14. I hereby certify that the foregoing is true and correct.		Recompletion New Construction  X Subsequent Report Plugging Non-Routine Fracturing  Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	<u>X</u>	Other – <u>Interim Reclamation</u>
interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.  14. I hereby certify that the foregoing is true and correct.	13.	Describe Proposed or Completed Operations		•
interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.  14. I hereby certify that the foregoing is true and correct.				
interim reclamation of the location. Please schedule a field inspection to verify (Burlington Resources) has m the BLM requirements on this reclamation work.  14. I hereby certify that the foregoing is true and correct.				
the BLM requirements on this reclamation work.  14. I hereby certify that the foregoing is true and correct.				
14. I hereby certify that the foregoing is true and correct.		- · · · · · · · · · · · · · · · · · · ·	Burli	ngton Resources) has me
	the	e BLM requirements on this reclamation work.		
	1.4	The makes and Smith at the Control of the Control o		
Signed ANIAA MILAALI Danies Isyamay Titles Regulatory Technician Data 7/1/11	14.	I neverly certify that the foregoing is true and correct.		
Signed 1 Define Journey Title. Regulatory Technician Date //1/11	Sig	ned Denise Journey Title: Regulatory	Гесhni	<u>cian</u> Date <u>7/1/11</u>
CALVIDOMAGAITAL		CALUDOMACAITAL		
(This space for Federal 1984 the Office use)		ais space for Federal #18th to Office use)		
APPROVED BY APPROVED BY COMPLIANCE TEAM LEAD Date 9-22-11	AF	PROVED BY TOLK TO COMPLIANCE TEAM LEAD		Date 9-22-//
CONDITION OF APPROVAL, if any: Title 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of				