



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX. (505) 334-6170
<http://emnrd.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 9/21/2011 Operator Chaparral Energy API #30-0 4529518
Property Name Hut Well No. 1 Location: Unit E Section 8 Township 29N Range 11W
Well Status (Shut-In or Producing) Initial PSI: Tubing 4 Intermediate N/A Casing 33 Bradenhead 23

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>2</u>		<u>33</u>		
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 2 INTERMEDIATE _____

REMARKS: down to nothing in less than 2 seconds through 1" valve

By Tim Merilatt
Contract Pumper
(Position)

Witness _____

E-mail address tmerilatt@hotmail.com