UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



BUREAU OF LAND MANAGEMENT	RECEIVED
Sundry Notices and Reports on Wells	SEP 13 2011
1. Type of Well GAS 2. Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator	5. Lease Number Fastilo 78439 ield Office 6 Bure it midian, Alignagemen. Tribe Name
2. Name of Operator BURLINGTON BURLINGTON BURLINGTON BURLINGTON BURLINGTON	7. Unit Agreement Name
RESCURCES OIL & GAS COMPANY LP 3. Address & Phone No. of Operator	8. Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	Johnston Federal 9F 9. API Well No.
	30-045-35152
4. Location of Well, Footage, Sec., T, R, M Surface: Unit B (NWNE), 749' FNL & 1453' FEL, Section 35, T31N, R9W, N	10. Field and Pool
BH: Unit G (SWNE), 2100' FNL & 1930' FEL, Section 35, T31N, R9W, NMPM	11. County and State San Juan, NM
Casing Repair Water Shut off Conversion to land International Casing Repair Altering Casing Water Shut off Conversion to land International Conversion Land International Conversion to land International Conversion to land International Conversion Land	8/29/11. TIH w/ 104 jts., 7", 23#, J-55 csg, set @ x (57cf-10bbls=3.02 yld), Premium Lite w/ 0.3% 145 sx (309cf-55bbls=2.13 yld) Premium Lite w/ 1 w/ 103 sx (142cf-25bbls=1.38 yld) Type III cmt., ump plug & open stage tool @ 2,759'. Plug down @
05:55 hrs on 8/30/11, circ 30 bbls cmt to surface. WOC. 2 nd Stage: Pre-flush w/ 10 bbls FW, 10 (57cf-10bbls=3.02 yld) Premium Lite w/ 0.3% CACL2, .25 pps cello-flake, 0.4% FL-52, 5 pps I (703cf-125bbls=2.13 yld) Premium Lite w/ 0.3% CACL2, .25 pps cello-flake, 0.4% FL-52, 5 pp and displaced w/ 109 bbls FW. Bump plug & close stage tool. Circ. 30 bbls cmt to surface. Plu TIH w/ 6 ¼" bit, tag cmt @ 2,757". DO cmt & stage tool @ 2,759". PT 7" csg to 1500#/30 min 8/31/11 TIH w/ 6 ¼" bit and drilled ahead to 7,760" (TD) – TD reached 9/4/11. Circ. hole. 9/2/11 Note: NOI dated 9/2/11 for permission to deeped TD to 7,804", but didn't deepen af 9/9/11 TIH w/ 182 jts., 4 ½" 11.6#, L-80 csg., (31 jts BT&C & 151 jts LT&C) set @ 7,752". RUPumped scavenger 9 sx(27cf-5bbls=3.02 yld) Premium Lite w/ 6.25 pps LCM-1, 0.3% CD-32, 10 (455cf-81bbls=1.98 yld) Premium Lite w/ 6.25 pps LCM-1, 0.3% CD-32, 10 (455cf-81bbls=1.98 yld) Premium Lite w/ 6.25 pps LCM-1, 0.3% CD-32, 10 FL-52, & .25 pps FW. Bump plug. Plug down @ 9:35 hrs on 9/9/11. WOC. RD cmt. ND BOPE. NU WH. RU	10 bbls GW, & 10 bbls FW. Pumped scavenger 19 st. CM-1, 8% bentonite, & 0.4% SMS. Lead w/ 330 st. CM-1, 8% bentonite, & 0.4% SMS. Drop plug ag down @ 11:35 hrs on 8/30/11. RD cmt. WOC. @ 23:00 hrs on 8/30/11. Test – OK. ter all. J to cmt. Pre-flush w/ 10 bbls CW & 2 bbls FW. 1% FL-52, & .25 pps cello-flake. Tail w/ 230 sx cello-flake. Drop plug and displaced w/ 120 bbls
PT will be conducted by Completion Rig. Results & TOC will appear on next report.	. • v
14. I hereby certify that the foregoing is true and correct. Signed Denise Journey Title: Regulatory T	Cechniciam Cozate FED FOR RECORD
(This space for Federal or State Office use)	SEP 1 4 2011
APPROVED BYTitle CONDITION OF APPROVAL, if any:	Date FARMINGTONE DETICE

NMOCD R

Q