NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-20-11 Operator Devon Energy API #30-0 45-28553

Property Name Nazu Middle Mesa Well No. 2 Location: Unit M Section 11 Township 31 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 761 Intermediate N/A Casing 14 Bradenhead 45.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	3		12		
10 min	0		12		
15 min	0		12		
20 min	0		12		
25 min	0		13		
30 min	0		13		

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

DIST. 3
OIL CONS. DIV.
RCVD OCT 20 '11

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Hard blow to whistle in 3 minutes - Med blow at 7½ minutes - ~~clear~~ clear at 7 min. 45 seconds - 10 - Vapors at 15-20-25-30 ~~vapors~~

By [signature]
Lease Operator Tech
(Position)

Witness Monica Kuehling

E-mail address _____

request schematic
Re-test bradenhead in 6 months