District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources** Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

## Part of Devon Clean-up Program

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Proposed Alternative Method Permit or Closure Plan Applica	ution
Type of action:  Permit of a pit, closed-loop system, below-grade tank, or proposed Closure of a pit, closed-loop system, below-grade tank, or propose Modification to an existing permit Closure plan only submitted for an existing permitted or non-permit below-grade tank, or proposed alternative method	d alternative method
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade	e tank or alternative request
Please be advised that approval of this request does not relieve the operator of <u>liability</u> should operations result in pollution of the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental operators.	
operator. DEVON ENERGY PRODUCTION COMPANY, L.P. OGRID #: 6137	
Address: c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401	
Facility or well name: NEBU #258H	
API Number: 30-039-30531 OCD Permit Number:	
U/L or Qtr/Qtr K Section 2 Township 30-N Range 07-W County:	
Center of Proposed Design: Latitude 36.84133 Longitude -107.54133	NAD: □1927 ⊠ 1983
Surface Owner:  Federal State Private Tribal Trust or Indian Allotment	
Pit: Subsection F or G of 19 15.17 11 NMAC	RCVD JUL 24'09
Temporary: Drilling Workover	OIL CONS. DIV.
Permanent Emergency Cavitation P&A	and the second second
☐ Lined ☐ Unlined Liner type: Thickness 12 mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other	DIST. 3
String-Reinforced	
Liner Seams Welded Factory Other Volume: 12,857 bbl Dimension	s: L_120' x W_75' x D_10'
3	
Closed-loop System: Subsection H of 19 15.17.11 NMAC	
Type of Operation.  P&A Drilling a new well Workover or Drilling (Applies to activities which require printent)	prior approval of a permit or notice of
☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other	
☐ Lined ☐ Unlined Liner type: Thicknessmil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other	
Liner Seams.  Welded Factory Other	
The land of the state of the st	
Below-grade tank: Subsection I of 19.15.17.11 NMAC  Volume:bbl Type of fluid:	
Tank Construction material:	
Secondary containment with leak detection  Visible sidewalls, liner, 6-inch lift and automatic overflow shut	-off
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other	1
Liner type: Thickness mil	
5.	
Alternative Method:	
Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau	office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)								
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school institution or church)	, hospital,							
Four foot height, four strands of barbed wire evenly spaced between one and four feet								
Alternate. Please specify								
7 N. 44' C. L								
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)  Screen Netting Other								
Monthly inspections (If netting or screening is not physically feasible)								
8.								
Signs: Subsection C of 19.15.17.11 NMAC								
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers								
Signed in compliance with 19.15.3.103 NMAC								
9. Administrative Approvals and Exceptions:								
Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.								
Please check a box if one or more of the following is requested, if not leave blank:  Administrative approval(s). Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau	office for							
consideration of approval.								
Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.								
Siting Criteria (regarding permitting): 19.15.17.10 NMAC								
Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acc material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appr								
office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of	approval.							
Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dry above-grade tanks associated with a closed-loop system.	ing pags or							
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No							
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).	Yes No							
- Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  (Applies to temporary, emergency, or cavitation pits and below-grade tanks)  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	NA NA							
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits)	☐ Yes ☐ No ☐ NA							
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image								
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.  - NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site	Yes No							
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.	☐ Yes ☐ No							
- Written confirmation or verification from the municipality; Written approval obtained from the municipality								
Within 500 feet of a wetland.  - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Within the area overlying a subsurface mine.  - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No							
Within an unstable area.  - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No							
Within a 100-year floodplain - FEMA map	☐ Yes ☐ No							

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC  Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC  Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC  Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17 9 NMAC  Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.  Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9  Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17 10 NMAC  Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC  Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC  Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design)  API Number:
Previously Approved Operating and Maintenance Plan API Number: (Applies only to closed-loop system that use above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC   Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.   Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC   Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC   Climatological Factors Assessment   Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC   Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC   Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC   Liner Specifications and Compatibility Assurance Construction and Installation Plan   Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC   Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC   Nuisance or Hazardous Odors, including H <sub>2</sub> S, Prevention Plan   Emergency Response Plan   Oil Field Waste Stream Characterization   Monitoring and Inspection Plan   Erosion Control Plan   Erosion Control Plan   Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.  Type. Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative  Proposed Closure Method Waste Excavation and Removal Waste Removal (Closed-loop systems only)
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached.  Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC  Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)  Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC  Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC  Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15 17.13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Instructions: Please indentify the facility or facilities for the disposal of liquids, drilli facilities are required.								
Disposal Facility Name Disposal Facility Permit Number:								
Disposal Facility Name: Dis	Disposal Facility Permit Number:							
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and operations?  Yes (If yes, please provide the information below) No								
Required for impacted areas which will not be used for future service and operations  Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection I of  Site Reclamation Plan - based upon the appropriate requirements of Subsection Countries.	19.15.17.13 NMAC	С						
17. Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the clos provided below. Requests regarding changes to certain siting criteria may require ad considered an exception which must be submitted to the Santa Fe Environmental Bu demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for g	ministrative approval from the appropriate disc reau office for consideration of approval. Just	trict office or may be						
Ground water is less than 50 feet below the bottom of the buried waste.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obt	ained from nearby wells	☐ Yes ☐ No ☐ NA						
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obt	ained from nearby wells	☐ Yes ☐ No ☐ NA						
Ground water is more than 100 feet below the bottom of the buried waste.  - NM Office of the State Engineer - iWATERS database search; USGS; Data obt	ained from nearby wells	☐ Yes ☐ No ☐ NA						
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).  - Topographic map; Visual inspection (certification) of the proposed site								
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.  - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image								
Within 500 horizontal feet of a private, domestic fresh water well or spring that less that watering purposes, or within 1000 horizontal feet of any other fresh water well or spring  NM Office of the State Engineer - IWATERS database; Visual inspection (certification)	g, in existence at the time of initial application.	Yes No						
Within incorporated municipal boundaries or within a defined municipal fresh water we adopted pursuant to NMSA 1978, Section 3-27-3, as amended.  - Written confirmation or verification from the municipality; Written approval ob		☐ Yes ☐ No						
Within 500 feet of a wetland.  - US Fish and Wildlife Wetland Identification map, Topographic map; Visual inst	spection (certification) of the proposed site	☐ Yes ☐ No						
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and	Mineral Division	☐ Yes ☐ No						
Within an unstable area.  - Engineering measures incorporated into the design; NM Bureau of Geology & Society; Topographic map	Mineral Resources; USGS; NM Geological	☐ Yes ☐ No						
Within a 100-year floodplain - FEMA map		☐ Yes ☐ No						
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the followy a check mark in the box, that the documents are attached.  Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of Sub Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - Protocols and Procedures - based upon the appropriate requirements of 19.15.17.  Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subs Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill of Re-vegetation Plan - based upon the appropriate requirements of Subsection I of	nents of 19.15 17.10 NMAC section F of 19.15 17.13 NMAC oriate requirements of 19.15.17.11 NMAC based upon the appropriate requirements of 19. 13 NMAC ments of Subsection F of 19.15 17.13 NMAC section F of 19.15.17.13 NMAC outtings or in case on-site closure standards cann 19.15.17.13 NMAC 19.15.17.13 NMAC	15.17.11 NMAC						
☐ Site Reclamation Plan - based upon the appropriate requirements of Subsection C	i of 19.15.17.13 NMAC							

19. Operator Application Certification:									
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.									
Name (Print): Title:									
Signature: Date:									
e-mail address Telephone:									
20.  OCD Approval: Permit Application (including closure plan)  Closure Plan (only)  OCD Conditions (see attachment)									
OCD Representative Signature: Approval Date:									
OCD Representative Signature:									
Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.									
Closure Completion Date: 2/2/09									
Closure Method:  Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only)  If different from approved plan, please explain.									
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized.									
Disposal Facility Name: Disposal Facility Permit Number:									
Disposal Facility Name: Disposal Facility Permit Number:									
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations?  Yes (If yes, please demonstrate compliance to the items below) No									
Required for impacted areas which will not be used for future service and operations.  Site Reclamation (Photo Documentation)  Soil Backfilling and Cover Installation  Re-vegetation Application Rates and Seeding Technique									
Closure Report Attachment Checklist: _Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached.  Proof of Closure Notice (surface owner and division)  Proof of Deed Notice (required for on-site closure)  Plot Plan (for on-site closures and temporary pits)  Confirmation Sampling Analytical Results (if applicable)  Waste Material Sampling Analytical Results (required for on-site closure)  Disposal Facility Name and Permit Number  Soil Backfilling and Cover Installation  Re-vegetation Application Rates and Seeding Technique  Site Reclamation (Photo Documentation)  On-site Closure Location: Latitude									
Operator Cleaning Cartification									
Operator Closure Certification:  I hereby certify that the information and attachments submitted with this closure report is true, accurate and complete to the best of my knowledge and belief I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.									
Name (Print): Mike Pippin Title. Petroleum Engineer									
Signature: Date: June 25, 2009									
e-mail address: mike@pippinllc.com Telephone: 505-327-4573									

# DEVON ENERGY PIT CLOSURE NEBU #258H

## Block #24, Box #4

The attached analytical data was taken by Blagg Engineering & analyzed by Envirotech Laboratories and passed all the State criteria.

## Block #24, Box #6

All liquids were hauled to one of the following company disposal wells:

Middle Mesa SWD #2 SWD-441
Middle Mesa SWD #1 SWD-365
Simms Mesa SWD #1 SWD-339
Pump Mesa SWD #1 SWD-366

## Block #24, Box #7

The liner was removed above "mud level" after stabilization. Pit contents were mixed with clean soil. After solidification and testing, the pit was backfilled with compacted, non-waste containing, soil. The pit was filled with clean excavated dirt and covered with 1 foot of top soil.

## Block #24, Box #8

The area where the temporary drilling pit has been buried in place was seeded on 6/4/09 with 40 lbs of BLM seed mix for precipitation less than 10". Seed was no till drill over a total acreage of 3.0 acres. The seed rate was 20 lbs PLS/acre for mechanical and 35 lbs PLS/acre for hand/broadcast and Harrow

Submit To Appropr Two Copies	riate District Off	State of New Mexico							Form C-105									
District I 1625 N French Dr	. Hobbs, NM 88	8240	Ene	Energy, Minerals and Natural Resources					July 17, 2008  1. WELL API NO.									
District II 1301 W Grand Av				Oil Conservation Division						30-039-30531								
District III 1000 Rio Brazos R				1220 South St. Francis Dr.						2 Type of Lease								
District IV							STATE FEE FED/INDIAN  3 State Oil & Gas Lease No E-289-23											
WELL COMPLETION OR RECOMPLETION REPORT AND LOG							,	State Office das Lease No. 12 207-23										
4 Reason for fil		TION	IN INLOO	IVII L	LIONIC	21(1/414	D LOG		5 Lease Name or Unit Agreement Name									
□ COMPLET	ION DEPOR	T (Fill in b	oves #1 throug	oh #31	for State and Fee w	elle only)			Northeast Blanco Unit 6 Well Number: 258H									
_		•	•	-		•			6 Well Num	ber: 2	258H							
					rough #9, #15 Date Fordance with 19 15			id/or										
7 Type of Com	pletion							VOI	ОТИГР			****						
8 Name of Oper					□PLUGBACK □ ndany, L.P.	] DIFFERI	INI KESEK	VOIF	9 OGRID (	06137								
10 Address of O	perator								11 Pool nam	e or W	'ildcat							
12.Location	Unit Ltr	Section	Townsh	пр	Range Lo	ot	Feet from	the	N/S Line	Fee	t from the	E/W	Line	County				
											······							
		<u> </u>								<u></u>				<u> </u>				
13 Date Spudde	d 14 Date	TD Reache	ed   15 D   10/30		Illing Rig Released	] 1	6. Date Com	plete	d (Ready to Pro	duce		7 Eleva RT, GR,		F and RKB,				
18 Total Measur	red Depth of V	Well			ck Measured Depth	2	) Was Dire	ction	al Survey Made	;7			,	ther Logs Run				
22 5	. 1() 6:1								<sub></sub>		<u> </u>							
22 Producing In	terval(s), or th	us compieti	on - 10p, Bott	om, iva	ame				ļ									
23				CAS	ING RECO	RD (Re	ort all s	trin	gs set in w	rell)								
CASING SI	ZE	WEIGHT			DEPTH SET		OLE SIZE		CEMENTIN		CORD	A	MOUNT	PULLED				
						<del> </del>												
						ļ			Ţ									
24.				LIN	IER RECORD	ــــــــــــــــــــــــــــــــــــــ		25	J	TURI	NG REC	ORD	····					
SIZE	TOP		BOTTOM		SACKS CEMEN	Γ SCRE	N	SL			EPTH SE		PACK	ER SET				
26					<u> </u>		arroa		- COVER O	33 (13)	III. COL	DEGE	P.T.C.					
26							LID, SHOT LINTERVA		ACTURE, CI					· · · · · · · · · · · · · · · · · · ·				
						-			ļ									
					DD	ODUC	TION											
Date First Produc	ction	Pro	duction Meth	od (Fle	owing, gas lift, pum			np)	Well Statu	s (Pro	d. or Shu	t-ın)						
		ĺ																
Date of Test	Hours Te	sted	Choke Size		Prod'n For	Oıl - B	bl	Ga	s - MCF	. W	ater - Bb		Gas - 0	Oil Ratio				
						1												
Flow Tubing	Casing Pr	essure	Calculated 2	4-	Oīl - Bbl	Ga	s - MCF		Water - Bbi		Oil Gr	avity - A	PI - (Cor	r)				
Press			Hour Rate															
29 Disposition o	,	ised for fuel	, vented, etc)							30.	Test Witn	essed By	у					
31 List Attachm	ents													· · · · · · · · · · · · · · · · · · ·				
32 If a temporar	y pit was used	at the well,	attach a plat	with th	e location of the ten	porary pit					•							
33 If an on-site l	burial was use	d at the wel	l, report the ex	cact loc	cation of the on-site	burial								<u> </u>				
I hereby corti	fu that the	nformati.	on shown a	n hotl	Latitude h sides of this for	36 84133	and com	nlete	Longitude		107 54133		NAD 19					
	y mai ine i		a a	]	Printed		-					Ü		/				
Signature	Mak	so oyo	yem		Name Mike P	ippin	Title:	Peti	oleum Engi	neer	Dat	e: 6/2	5/09					
E-mail Addre	ss: mike@r	oippinllc.	com															

## Castro, Melisa

From:

Castro, Melisa

Sent:

Thursday, September 18, 2008 1:26 PM

To:

**SLO Contact** 

Subject:

NEBU 258H Temporary Pit Closure Notification

Attachments: Pit Closure Plan.doc

Devon Energy Corporation 20 North Broadway Oklahoma City, OK 73102-8260 405 552 7917 Phone www.devonenergy.com

July 23, 2008

IN RE: NEBU 258H
API # 30-039-30531
NE SW 2,685' FNL & 2,415' FWL
Sec. 2, T30N, R7W
Rio Arriba County, New Mexico

VIA EMAIL:

Dear Mr. Martinez,


This submittal is pursuant to Rule 19.15.17.13 requiring operators to notify the surface owners of an onsite burial of a temporary pit. Devon Energy Production Company, L.P. is herby providing written documentation of our intention to close the temporary pit associated with the aforementioned location by means of in place on-site burial.

Please feel free to contact me with any questions or require further information. My contact information is listed below.

Respectfully,

Melisa S. Castro
Devon Energy Production Company, L.P.
Senior Staff Operations Technician
405-323-3184 - Cell.
405-323-1357 - Fax
Melisa.Castro@dvn.com

9/18/2008



District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

AS DRILLED

Form C-102

Revised October 12, 2005

Submit to Appropriate District Office

State Lease - 4 Copies

Fee Lease - 3 Copies

ROUD NOV 21 '08 AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT DIL CONS. DIV.

API Numbe	er	<sup>2</sup> Pool Code	<sup>3</sup> Pool Name	DIST. 3				
30-039-305	31	80690	So. Los Pinos Frt/Sand Pictured Cliffs					
<sup>4</sup> Property Code		<sup>5</sup> Pr	<sup>6</sup> Well Number					
19641		Northea	258 <i>H</i>					
OGRID No.		8 OI	perator Name	, Elevation				
06137		Devon Energy Pro	oduction Company, L.P.	6322' GL				

<sup>10</sup> Surface Location

UL or let no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
K	2	30-N	7-W		2685'	NORTH	2415'	WEST	Rio Arriba
<u> </u>			11						

Bottom Hole Location If Different From Surface


UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
D	24	30-N	7-W		695'	NORTH	678'	WEST	Rio Arriba
12 Dedicated Acres	Joint or	r Infili	onsolidation	Code 15 Or	der No.				
NW/4-158.62	2			- 1					


No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the

division.	5280'®	recen consolidated or a non-standard unit has been approved by the
678' BOTTO	м ноге 2685°	17 OPERATOR CERTIFICATION  I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased numeral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a interest or working interest, or to a voluntary pooling agreement or a compulsory pooling order hereinfore entered by the diffusion.
1718'	7" SHOE	Signature Date  Mike Pippin Pruted Name
2415'	SURFACE	18 SURVEYOR CERTIFICATION  I hereby certify that the well location shown on this  plat was plotted from field notes of actual surveys  made by me or under my supervision, and that the  same is true and correct to the best of my belief.  4/1/08
		Date of Survey Signature and Seal of Professional Surveyor  Gary D Mann  7016  Certificate Number

## PAD LAYOUT PLAN & PROFILE DEVON ENERGY PRODUCTION COMPANY, L.P.

5053260050





08/14/2008 12:13PM (GMT-05:00)

# **CHAIN OF CUSTODY RECORD**

Client:		1	Project Name / L		· · · · · · · · · · · · · · · · · · ·	1			ANALYSIS / PARAMETERS														
BLAGG DE	EWN		RESERVE	: Pi	- Pr	UJECT	-																
Client Address:		• ;	Sampler Name:				5)	)21)	) (0)														
								96 0	826	<u>s</u>	ے		ட								4		
Client Phone No.:		} (	Client No :		. ~				pod	atho		Meta	į		Ţ		3.1)	ㅂ				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	ntac
	· · · · · · · · · · · · · · · · · · ·		9403						Met	Š	(Me	181	n/A		wit		(418	뚪			-	e l	ole l
Sample No./ Identification	Sample	Sample	Lab No.		ample	No./Volume of			TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion	S	TCLP with H/P	PAH	TPH (418.1)	CHLORIDE	ľ			Sample	Sample Intact
	Date	Time		Soil	latrix Sludge	Of Containers	nguş	HU	<u> </u>	m m	>	<u> </u>	0	<u>ac</u>	<u> </u>	α.			$\rightarrow$	_		,	, 0)
5-Pt Coup.	14/03	1300	48458 (	Solid	Aqueous	1-402			×	×							×	×				4	
				Soil Solid	Sludge Aqueous																		
NEBU 485A 5-Pt comp	น	140	48459(	Soil Solid	Sludge Aqueous	11			×	×							~	2			L		1
				Soil Solid	Sludge Aqueous																		,
NEBU 258H 5-PE COLP	11	150	48460	Soil Solid	Sludge Aqueous	K			×	×							×	بذ			l		
				Sold	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous										]								-
				Soil Solid	Sludge Aqueous	-																	
				Soll Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous																		,
Relinquished by: (Signa	iture)				Date	Time			ed by									·		Da	te	Tir	me
11/1/	79.49		•		12/10/03	1235	1	hi	ved by	1		V)	1.	ce.	te					12/2	108	12	35
Relinguished by: (Signa	ature)				, ,		(F	Receiv	ed by	(Sign	ature	)								<i>1</i> 9,			
Relinquished by: (Signa	ature)			· ·	<u> </u>		F	Receiv	ed by	(Sign	ature	<u> </u>											
, samiquiona by, (Olgine		, -	•		,			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	. Ju Dy	, (~;a,		,		- •								1 £	
	*		,							io		,						*		L		<u> </u>	` ,
	1		,			RO	27 27 13	الله الله الله الله الله الله الله الله		1) e	<u>ن.</u>	-					•	•					

5796 U.S. Highway 64 • Farmington, NM 87401 • Tel 505-632-0615



# **EPA METHOD 8015 Modified** Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

Client	Blagg/Devon	Project #	94034-0010
Sample ID	NEBU 258H 5-pt Comp	Date Reported	12-16-08
Laboratory Number	48460	Date Sampled	12-04-08
Chain of Custody No	5904	Date Received	12-10-08
Sample Matrix	Soil	Date Extracted	12-12-08
Preservative	Cool	Date Analyzed	12-15-08
Condition	Intact	Analysis Requested	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	111	0.1
Total Petroleum Hydrocarbons	111	0.2

ND - Parameter not detected at the stated detection limit

References Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996

Comments. **Reserve Pit Project** 

Analyst

5796 US Highway 64, Farmington, NM 87401 Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com



# EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client	Blagg/Devon	Project #	94034-0010
Sample ID	NEBU 258H 5-pt Comp	Date Reported	12-16-08
Laboratory Number	48460	Date Sampled	12-04-08
Chain of Custody	5904	Date Received	12-10-08
Sample Matrix	Soil	Date Analyzed	12-15-08
Preservative	Cool	Date Extracted	12-12-08
Condition	Intact	Analysis Requested	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	ND	0.9	
Toluene	27.1	1.0	
Ethylbenzene	9.6	1.0	
p,m-Xylene	74.6	1.2	
o-Xylene	34.2	0.9	
Total BTEX	145		

ND - Parameter not detected at the stated detection limit

Surrogate Recoveries	Parameter	Percent Recovery
	Fluorobenzene	98.0 %
	1,4-difluorobenzene	98.0 %
	Bromochlorobenzene	98.0 %

References

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996

Comments:

**Reserve Pit Project** 

Analyst

Review

## **EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS**

Client:	Blagg/Devon	Project #:	94034-0010
Sample ID.	NEBU 258H 5-pt Comp	Date Reported:	12-16-08
Laboratory Number:	48460	Date Sampled:	12-04-08
Chain of Custody No:	5904	Date Received:	12-10-08
Sample Matrix:	Soil	Date Extracted:	12-12-08
Preservative·	Cool	Date Analyzed:	12-12-08
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

**Total Petroleum Hydrocarbons** 

445

5.0

ND = Parameter not detected at the stated detection limit

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Reserve Pit Project.

Mustly m Welters
Review



#### Chloride

Blagg/Devon Project #: 94034-0010 Client. NEBU 258H 5-pt Comp Date Reported: 12-16-08 Sample ID: Lab ID# 48460 Date Sampled: 12-04-08 Date Received: 12-10-08 Sample Matrix: Soil Preservative: Cool Date Analyzed: 12-12-08 Chain of Custody: 5904 Condition. Intact

Parameter Concentration (mg/Kg)

Total Chloride 140

Reference: U.S.E.P.A, 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments: Reserve Pit Project.

Vinto Bang Mustum Weeters
Review



# EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client	N/A	Project #.	N/A
Sample ID	12-15-BT QA/QC	Date Reported	12-16-08
Laboratory Number	48437	Date Sampled	N/A
Sample Matrix	Soil	Date Received	N/A
Preservative	N/A	Date Analyzed	12-15-08
Condition	N/A	Analysis	BTEX

Calibration and Detection Limits (ug/L)	J-Cal'RP2	C-Cal RF Accept. Rank		Blank Gonc	Defect. Limit
Benzene	1 4544E+006	1 4573E+006	0.2%	ND	0.1
Toluene	1 4038E+006	1 4066E+006	0.2%	ND	0.1
Ethylbenzene	1 2883E+006	1 2909E+006	0.2%	ND	0.1
p,m-Xylene	3 1205E+006	3 1267E+006	0.2%	ND	0.1
o-Xylene	1 3258E+006	1 3284E+006	0.2%	ND	0.1

Duplicate Conc. (ug/Kg). Sample Duplicate %Diff Accept Range Defect Limit						
Benzene	ND	ND	0.0%	0 - 30%	0.9	
Toluene	20.0	20.3	1.5%	0 - 30%	1.0	
Ethylbenzene	28.0	27.4	2.2%	0 - 30%	1.0	
p,m-Xylene	562	556	1.1%	0 - 30%	1.2	
o-Xylene	195	201	3.4%	0 - 30%	0.9	

Spike Conc. (ug/Kg)	Sample Amo	um Spiked "Spil	ked Sample	% Recovery	Accept Range
Benzene	ND	50.0	48.0	96.0%	39 - 150
Toluene	20.0	50.0	68.7	98.1%	46 - 148
Ethylbenzene	28.0	50.0	75.9	97.3%	32 - 160
p,m-Xylene	562	100	656	99.1%	46 - 148
o-Xylene	195	50.0	247	101%	46 - 148

ND - Parameter not detected at the stated detection limit

References Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996

Comments:

QA/QC for Samples 48437 - 48441 and 48456 - 48460.

Analyst

Review



# **EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons**

# **Quality Assurance Report**

Client.	QA/QC	Project #:	N/A
Sample ID <sup>.</sup>	12-15-08 QA/QC	Date Reported:	12-16-08
Laboratory Number	48437	Date Sampled.	N/A
Sample Matrix.	Methylene Chloride	Date Received <sup>.</sup>	N/A
Preservative <sup>-</sup>	N/A	Date Analyzed	12-15-08
Condition	N/A	Analysis Requested	TPH

Diff.	I-Cal Date	LCel RF	*G-Cal RF	% Difference	Accept Range
Gasoline Range C5 - C10	05-07-07	9 9960E+002	1 0000E+003	0.04%	0 - 15%
Diesel Range C10 - C28	05-07-07	9 9960E+002	1 0000E+003	0.04%	0 - 15%

Blank Conc (mg/L - mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	ND	0.2
Diesel Range C10 - C28	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

Duplicate Conc. (mg/kg)	Sample	Duplicate	% Difference	Accept Range
Gasoline Range C5 - C10	80:1	76.6	4.4%	0 - 30%
Diesel Range C10 - C28	1,540	1,520	1.2%	0 - 30%

Spike Conc. (mg/Kg)	- Sample	* Spike Added	Spike Result	% Recovery	Accept Range
Gasoline Range C5 - C10	80.1	250	326	98.8%	75 - 125%
Diesel Range C10 - C28	1,540	250	1,780	99.4%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996

Comments:

QA/QC for Samples 48437 - 48441, 48458 - 48460, and 48487.



# **EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT**

Client: Sample ID: QA/QC QA/QC Project #:

N/A

Laboratory Number:

12-12-TPH.QA/QC -48458

Date Reported: Date Sampled:

12-16-08 N/A

Sample Matrix:

Freon-113

12-12-08

Date Analyzed:

12-12-08

TPH

Preservative:

N/A N/A

Date Extracted: Analysis Needed: 12-12-08

Condition:

Calibration I-Cal Date

C-Cal Date I-Cal RF C-Cal RF: % Difference Accept Range

12-03-08

1.590

1,500

5.7%

+/- 10%

Blank Conc. (mg/Kg)

Concentration

**TPH** 

ND

**Detection Limit** 17.8

Duplicate Conc. (mg/Kg)

Sample

Duplicate

% Difference Accept Range.

TPH

667

604

9.5%

+/- 30%

Spike Conc. (mg/Kg) Sample **TPH** 

667

Spike Added Spike Result % Recovery 2,000

2,540

95.2%

Accept Range 80 - 120%

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

QA/QC for Samples 48458 - 48461, 48463 - 48465 and 48467.

#### WELL SITE DOCUMENTATION

Company Name: DEVON ENERGY Well Name: NEBU 258H

Legal Description: Section 2 TWNSHP 30N Range 7W

County: Rio Arriba San Juan State: NM

Area Seeded: (See Attached Digital Photos) Dates of Seeding: 6-04-2009

Seed Mix: Southwest Colorado Seed Farmington Field Office Certified Mix NOTE: Application rate is based upon pure live seed (PLS). BLM certified seed is delivered from Dolores, Colorado in 20 lb. sacks. 100% PLS PER BAG. Included in the cost to customer per acre is \$6.40 per PLS pound. BLM recommended seeding rate for mechanical application is 13.25 LBS PLS per acre and 26.50 LBS per acre for broadcast application. \*Based upon BLM application rate chart dated May 5, 2006\*

Seed Rate: Mechanical:

20.00 lbs PLS/acre 30.00 lbs PLS/acre Hand/Broadcast and Harrow:

\*Based upon BLM application rate chart

Start: 1358.0 End: 1360.3 Mechanical Acreage: Acreage Meter

No-Till Drill Application Acreage:

Total: 2.5.

Note: An additional .50 acre charge for rocky topsoil conditions.

.5

Broadcast/Harrow Application Acreage:

Total: 3.0 Acres

**Total Acreage Seeded:** 

**No-Till Drill Application** 

TOTAL: 3.0 Acres 40 Lbs

Seeding Process: 2006 John Deere 5205 MFW 56 HP Tractor

2004 Great Plains No-Till Drill Model 605 NT

2006 Land Pride Broadcast

2006 8 ft. Harrow

Topography: Fairly clean site. Dry red clay/loam with some evidence of small to medium sized sandstone rock. Some tree debris throughout the site area. Moderate slope conditions on three sides of location. Some seeder slippage due to moderate slope conditions. Utilized no-till drill application and pre-harrowed site location. Comments: A separate invoice will be created for the following services rendered:

•	Operator Hourly Rate:	\$35.00 X 7.5 =	\$262.50
•	Tractor Hourly Rate:	\$75.00 X 3.5 =	\$262.50
•	Fuel/Milage Surcharge:	\$2.00 X 114 Miles =	\$228.00
•	Seeding Cost:	\$600.00 Per Acre X 3.5 acres =	\$1.800.00

NOTE: Cost includes the use of seeders and seed cost per acre.

**Total Invoice Cost:** \$2,853.00

NOTE: There is a minimum charge of \$600.00 per acre for each well site.

ST Seeding and Tractor P.O. Box 551 Bloomfield, NM 87413 Ph: 505.793.0364

#258# NEBU



