District I District 1 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr.

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD

1220 3 St. ITalicis DI, Sainta Fe, NW 67303	Santa Fe, NM 87505	District Office	ile (((() () () () () () () ()
73/7 Pit, Closed	d-Loop System, Below-Grad	e Tank, or	
Proposed Alternati	ve Method Permit or Closur		
☐ Closure of a☐ Modification	oit, closed-loop system, below-grade tan pit, closed-loop system, below-grade tan it to an existing permit only submitted for an existing permitted	nk, or proposed alternative metho	od
below-grade tank, or proposed alto			
Instructions: Please submit one application (F	Form C-144) per individual pit, closed-loop :	system, below-grade tank or alternat	tive request
Please be advised that approval of this request does not relievely invironment. Nor does approval relieve the operator of its re-			
Operator <u>Energen Resources</u>	OGRID	#162928	
Address 2010 Afton Place, Farmington, New Mexic	co 87401		
Facility or well name			•
API Number <u>3003921298</u>	OCD Permit Number.		
U/L or Qtr/Qtr <u>G</u> Section <u>7</u> Town	nship <u>25N</u> Range <u>04W</u> Co	unty <u>Rio Arriba</u>	
Center of Proposed Design Latitude 36 4168	Longitude <u>-107 28855</u>	NAD □1927 ⊠ 1983	
Surface Owner 🔲 Federal 🔲 State 🔲 Private 🖂 Trib			
Temporary			
3 ☐ Closed-loop System: Subsection H of 19 15 17 11 Type of Operation ☐ P&A ☐ Drilling a new well ☐ intent) ☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Ha	NMAC] Workover or Drilling (Applies to activities	s which require prior approval of a pe	ermit or notice of
☐ Lined ☐ Unlined Liner type Thickness Liner Seams ☐ Welded ☐ Factory ☐ Other	mil LLDPE HDPE PVC	A RECO	2324 ₂₅₂ 622 ENVED
** Below-grade tank: Subsection I of 19 15 17 11 NN	1AC		201n w
Volumebbl Type of fluid		OIL CONS. D	2010 33 N DET
Tank Construction material.		18	-0131.3
Secondary containment with leak detection Vis		ic overflow shut-off	, ag 7 6 U
☐ Visible sidewalls and liner ※ Visible sidewalls on	ly Dther	-08/	13-
Liner type Thicknessmil			
5			
Alternative Method:			
Submittal of an exception request is required Exception	ns must be submitted to the Santa Fe Enviro	nmental Bureau office for considerat	ion of approval

Fencing: Subsection D of 19 15 17 11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate Please specify	hospital,	
Netting: Subsection E of 19 15 17 11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)		
Signs: Subsection C of 19 15 17 11 NMAC 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers Signed in compliance with 19 15 3 103 NMAC		
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required Please refer to 19 15 17 NMAC for guidance Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s) Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval Exception(s) Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval	office for	
Siting Criteria (regarding permitting): 19 15 17 10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or above-grade tanks associated with a closed-loop system.		
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank - NM Office of the State Engineer - iWATERS database search, USGS, Data obtained from nearby wells	☐ Yes ☐ No	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) - Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	Yes No	
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to permanent pits) - Visual inspection (certification) of the proposed site. Aerial photo, Satellite image	Yes No	
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application - NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality, Written approval obtained from the municipality	☐ Yes ☐ No	
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map, Topographic map, Visual inspection (certification) of the proposed site	☐ Yes ☐ No	
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No	
 Within an unstable area Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources, USGS, NM Geological Society, Topographic map 	☐ Yes ☐ No	
Within a 100-year floodplain - FEMA map	☐ Yes ☐ No	

Form C-144 Oil Conservation Division Page 2 of 5

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19 15 17 9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15 17 9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC Design Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC				
Previously Approved Design (attach copy of design) API Number or Permit Number				
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19 15 17 10 NMAC Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15 17 9 NMAC and 19 15 17 13 NMAC				
Previously Approved Design (attach copy of design) API Number				
Previously Approved Operating and Maintenance Plan API Number (Applies only to closed-loop system that use				
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)				
Permanent Pits Permit Application Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19 15.17 9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19 15 17 11 NMAC Leak Detection Design - based upon the appropriate requirements of 19 15 17 11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19 15 17 11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19 15.17 9 NMAC and 19 15 17 13 NMAC				
Proposed Closure: 19 15 17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.				
Type Drilling Workover Emergency Cavitation P&A Permanent Pit X Below-grade Tank Closed-loop System Alternative Proposed Closure Method Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)				
Waste Excavation and Removal Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfüll and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC				

Oil Conservation Division

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Instructions: Please indentify the facility or facilities for the disposal of liquids, a facilities are required.				
•	Disposal Facility Permit Number			
	Disposal Facility Permit Number.			
Will any of the proposed closed-loop system operations and associated activities oc ☐ Yes (If yes, please provide the information below) ☐ No	cur on or in areas that will not be used for future serv	vice and operations?		
Required for impacted areas which will not be used for future service and operation Soil Backfill and Cover Design Specifications based upon the appropriate Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection	requirements of Subsection H of 19 15 17 13 NMAO I of 19.15 17 13 NMAC	С		
Siting Criteria (regarding on-site closure methods only): 19 15.17 10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.				
Ground water is less than 50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS, Data	a obtained from nearby wells	☐ Yes ☐ No ☐ NA		
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS, Data	obtained from nearby wells	☐ Yes ☐ No ☐ NA		
Ground water is more than 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search, USGS, Data	a obtained from nearby wells	Yes No		
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other sig lake (measured from the ordinary high-water mark) - Topographic map, Visual inspection (certification) of the proposed site	nificant watercourse or lakebed, sinkhole, or playa	☐ Yes ☐ No		
Within 300 feet from a permanent residence, school, hospital, institution, or church Visual inspection (certification) of the proposed site, Aerial photo, Satellite		☐ Yes ☐ No		
Within 500 horizontal feet of a private, domestic fresh water well or spring that less watering purposes, or within 1000 horizontal feet of any other fresh water well or s - NM Office of the State Engineer - iWATERS database, Visual inspection (pring, in existence at the time of initial application	☐ Yes ☐ No		
Within incorporated municipal boundaries or within a defined municipal fresh water adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality, Written approv	·	Yes No		
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map, Topographic map; Visua	ıl inspection (certification) of the proposed site	☐ Yes ☐ No		
Within the area overlying a subsurface mine - Written confirmation or verification or map from the NM EMNRD-Mining	and Mineral Division	☐ Yes ☐ No		
Within an unstable area - Engineering measures incorporated into the design, NM Bureau of Geology Society, Topographic map	& Mineral Resources, USGS, NM Geological	☐ Yes ☐ No		
Within a 100-year floodplain - FEMA map	· ·	☐ Yes ☐ No		
On-Site Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17 10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19 15.17 13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19 15 17 11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19 15 17 13 NMAC Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC Soil Cover Design - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC				

Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief
Name (Print) Title
Signature Date
e-mail address Telephone
OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment)
OCD Representative Signature: Approval Date: 10/04/2011
Title: OMPlance Office OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection K of 19 15 17 13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.
☐ Closure Completion Date: 9/30/10
Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain
23 Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only:
Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized.
Disposal Facility Name Disposal Facility Permit Number
Disposal Facility Name Disposal Facility Permit Number
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations? Yes (If yes, please demonstrate compliance to the items below) No
Required for impacted areas which will not be used for future service and operations Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique
24 Clause Day at Attachment Checklist. Justinisticus. Each of the following itsus must be attached to the classic many Plane in diagraphy a check
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location Latitude
25
Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure report is true, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.
Name (Print) Ed Hasely Title Sr Environmental Engineer
Signature Date Date
e-mail address — ed hasely@energen.com Telephone: (505) 324-4131

BELOW-GRADE TANK CLOSURE REPORT

ENERGEN RESOURCES Jicarilla 123C #124

CLOSURE STEPS: (Closure Report information is in **bold**)

- (1) Notify the surface owner by certified mail, return receipt requested, of the plans to close the below-grade tank. Attached
- (2) Notify the Aztec OCD office (Brandon Powell 334-6178, Ext 15) verbally or by other means at least 72 hours, but not more than one week, prior to the planned closure operation.

Attached

- (3) Remove liquids from the below-grade tank. Dispose of the liquids and sludge in a division-approved facility. No disposal of liquids was required.
- (4) Remove the below-grade tank for re-use in an above-ground setup or for disposal in a division-approved manner. Tank removed.
- (5) Unless the equipment is required for some other purpose, remove any on-site equipment associated with the belowgrade tank

All remaining equipment is required for operations.

- (6) Test the soils beneath the below-grade tank to determine whether a release has occurred
 - Collect, at a minimum, a five point, composite sample;
 - Collected composite sample.
 - Collect individual grab samples from any area that is wet, discolored or showing other evidence of a release;

No additional sampling was necessary.

Analyze for BTEX, TPH and chlorides to demonstrate:

- Benzene concentration does not exceed 0.2 mg/kg, as determined by EPA SW-846 methods 8021B or 8260B
- Total BTEX concentration does not exceed 50 mg/kg, as determined by EPA SW-846 methods 8021B or 8260B
- TPH concentration does not exceed 100 mg/kg, as determined by EPA method 418 1
- Chloride concentration does not exceed 250 mg/kg, as determined by EPA method 300.1 or the background concentration, whichever is greater

Constituent	Limit (mg/kg)	Actual Results (mg/kg)
Benzene	0.2	ND
Total BTEX	50.0	ND
TPH (418.1)	100	ND
Chlorides	250	35

(7) <u>IF the soil analyses show that the soils meet the concentrations specified in (6) above</u>, backfill the excavation with compacted, non-waste containing, earthen material in a manner that will prevent ponding or erosion. If the area will not be needed for operations, reclaim the area as described in the "RECLAMATION" section.

Excavation was backfilled w/ non-waste containing, earthen material in a manner that will prevent ponding and erosion, including one foot on top soil.

(8) <u>IF the soil analyses show that the soils exceed one or more of the concentrations specified in (6) above, notify the Aztec OCD office (Brandon Powell – 334-6178, Ext 15) and proceed per 19.15.3.116 NMAC Not applicable.</u>

NOTE. If groundwater is encountered at any time during the closure process, the OCD office will be notified and a specific closure plan will be submitted to the Aztec and Santa Fe OCD offices for approval.

Not applicable.

FINAL CLOSURE REPORT:

Within 60 days of closure completion, submit a closure report on form C-144, with necessary attachments to document all closure activities including sampling results.

This submittal is the closure report.

RECLAMATION:

If the area is not needed for operations, reclaim the area to a safe and stable condition that blends with the surrounding undisturbed area. Restore the impacted surface area to the condition that existed prior to oil and gas operations by placement of the soil cover, recontour the location and associated areas to a contour that approximates the original contour and blends with the surrounding topography and re-vegetate

- (A) Construct the soil cover to the site's existing grade and prevent ponding of water and erosion of the cover material. The soil cover shall consist of the background thickness of topsoil or one foot of suitable material to establish vegetation at the site, whichever is greater.
- (B) Seed or plant the disturbed areas the first growing season after closing the below-grade tank. Drill on the contour whenever practical or by other division-approved methods. The goal is to obtain vegetative cover that equals 70% of the native perennial vegetative cover (un-impacted by overgrazing, fire or other intrusion damaging to native vegetation) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. During the two successive growing seasons that prove viability, there shall be no artificial irrigation of the vegetation.
 - (C) Repeat seeding or planting until it successfully achieves the required vegetative cover
- (D) If conditions are not favorable for the establishment of vegetation, such as periods of drought, contact the Aztec OCD office to discuss possibly delaying seeding or planting until soil moisture conditions become favorable or using additional techniques such as mulching, fertilizing, irrigating, fencing or other practices
- (E) Notify the Aztec OCD office (Brandon Powell 334-6178, Ext 15) when the area has been seeded or planted and when it successfully achieves re-vegetation.

Area is needed for operations. Upon abandonment, seeding will be deferred to the BLM / Tribal requirements per the BLM / OCD MOU.



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

23.8

Client:	Energen Resources	Project #	03022-0168
Sample ID:	Jic 123C #24 Pile	Date Reported:	08-20-10
Laboratory Number:	55604	Date Sampled:	08-18-10
Chain of Custody No:	10214	Date Received:	08-18-10
Sample Matrix:	Soil	Date Extracted:	08-19-10
Preservative.	Cool	Date Analyzed.	08-19-10
Condition:	Intact	Analysis Needed:	TPH-418.1

	The standard design section is an experience of the section of the	Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons 29.8

ND = Parameter not detected at the stated detection limit.

References: Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments: Jicarilla BGTs

the state of the s



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Energen Resources	Project #:	03022-0168
Sample ID:	Jic 123C #24 Pıle	Date Reported:	08-20-10
Laboratory Number:	55604	Date Sampled:	08-18-10
Chain of Custody:	10214	Date Received:	08-18-10
Sample Matrix:	Soil	Date Analyzed:	08-19-10
Preservative:	Cool	Date Extracted:	08-19-10
Condition.	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	ND	0.9
Toluene	ND	1.0
Ethylbenzene	ND	1.0
p,m-Xylene	ND	1.2
o-Xylene	ND	0.9
Total BTEX	ND	

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery	
	Fluorobenzene	97.3 %	
	1,4-difluorobenzene	99.2 %	
	Bromochlorobenzene	e 102 %	

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Jicarilla BGTs

Analyst

Review



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client ⁻	Energen Resources	Project #:	03022-0168
Sample ID.	Jic 123C #24 Pile	Date Reported:	08-20-10
Laboratory Number:	55604	Date Sampled:	08-18-10
Chain of Custody No:	10214	Date Received:	08-18-10
Sample Matrix:	Soil	Date Extracted:	08-19-10
Preservative:	Cool	Date Analyzed [.]	08-19-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)	
Gasoline Range (C5 - C10)	ND	0.2	
Diesel Range (C10 - C28)	ND	0.1	
Total Petroleum Hydrocarbons	ND	0.2	

ND - Parameter not detected at the stated detection limit

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments: Jicarilla BGTs

Analyst

Review



Chloride

Client:	Energen Resources	Project #:	03022-0168
Sample ID ⁻	Jic 123C #24 Pile	Date Reported.	08-20-10
Lab ID#:	55604	Date Sampled:	08-18-10
Sample Matrix:	Soil	Date Received:	08-18-10
Preservative:	Cool	Date Analyzed ⁻	08-20-10
Condition:	Intact	Chain of Custody:	10214

Parameter		Concentration (mg/Kg)	

Total Chloride 30

Reference: U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments: Jicarilla BGTs

Analyst Hompson

Review

Ed Hasely

From:

Ed Hasely

Sent:

Monday, August 09, 2010 1 41 PM

To:

'Powell, Brandon, EMNRD'

Subject:

BGT Notification - 4 Jicarilla Wells

Brandon – this is to notify you that Energen plans to close the below grade tanks that are located on the following locations:

The contract of the contract o	~~ ž
Jicarilla 120C #13 - Unit Letter L, Section 30, Township 25N, Range 5W	
Jicarilla 123C #17 - Unit Letter E, Section 30, Township 25N, Range 5W	3
Jicarilla 123C #19 - Unit Letter D, Section 24, Township 26N, Range 3W	To see also
Jicarilla 123C #24 - Unit Letter O, Section 24, Township 26N, Range 3W	1

Let me know if you have any questions.

Ed Hasely

Energen Resources Corporation

Sr Environmental Engineer ed hasely@energen com
Office (505) 324-4131
Cell (505) 330-3584



August 9, 2010

Jicarilla Apache Nation
Environmental Protection Office
P.O. Box 507
Dulce, NM 87528

Attn: Mr. Dixon Sandoval, Environmental Specialist



Below Grade Tank Closures

Multiple Wells

Dear Sirs:

Energen Resources plans to close the below grade tanks located on the well locations listed below. You are on record as the surface owner where these wells are located. New Mexico Oil Conservation Division (NMOCD) rules require notification to the surface owner of our plans to close the below grade tanks. NMOCD rules and guidelines will be followed. The wells are all located in Rio Arriba County, New Mexico.

5397

Certified Fee

Return Receipt Fee (lorsement Required

Restricted Delivery Fee (Endorsement Required)

Total Postage & Fees

Street, Apt No or PO Box No.

City, State, ZIP+4

Postmark

Here

Jicarilla 120C #13 - Unit Letter L, Section 30, Township 25N, Range 5W

Jicarilla 123C #17 - Unit Letter E, Section 30, Township 25N, Range 5W


Jicarilla 123C #19 - Unit Letter D, Section 24, Township 26N, Range 3W

Jicarilla 123C #24 - Unit Letter O, Section 24, Township 26N, Range 3W

If there are any questions or concerns, please contact me at 505-324-4131.

Ju 123 Multiply Sincerely, COMPLETE THIS SECTION ON DELIVERY SENDER: COMPLETE THIS SECTION Complete items 1, 2, and 3. Also complete □ Agent item 4 if Restricted Delivery is desired. Print your name and address on the reverse □ Addresse so that we can return the card to you. C. Date of Deliver Ed Hasely Attach this card to the back of the mailpiece, Sr. Environmental Engineer or on the front if space permits. D. Is delivery address different from item 1? **Energen Resources** 1. Article Addressed to: If YES, enter delivery address below. 4 Vicerilla Apach Neutron EPO PO Box 507 Cc: Well Files Dulce NH 87528 3. Service Type Correspondence Certified Mail ☐ Express Mail Diram Sambara ☐ Registered ☐ Return Receipt for Merchandis ☐ C.O.D. ☐ Insured Mail 4. Restricted Delivery? (Extra Fee) ☐ Yes 2 Article Number 7007 1490 0000 5397 4707

(Transfer from su



<u>District 1</u> 1625 N French Dr , Hobbs, NM 88240 District II
1301 W Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

\neg	2 1 7		Release Notificati	ion	and Corre	ective Actio	n		
/	317				OPERATO.	R	[Initia	al Report 🛛 Final Repo	
Name of Company: Energen Resources, Inc			C	ontact: I	Ed Hasely				
Address: 2010 Afton Place, Farmington, NM 87401				elephone No:					
Facility Na	me: Jicarilla	a 123C #24		F	acility Type: C	Dil/Gas Well Site			
Surface Ov	ner: Tribal		Mineral Own	er:	Гribal		Lease N	0.	
			LOCATI	ON	OF RELEA	ASE			
Unit Letter G	Section 7	Township 25N	Range Feet from the 4W 1630	Nor Nor	th/South Line h	Feet from the 1525	East/West	Line County Rio Arriba	
			Latitude 36.41680		Longitude	<u>-107.28855</u>			
			NATUR	RE (OF RELEAS	SE			
Type of Rele	ase: NO REI	LEASE			Volume of Release: Volume Recovered:			ecovered:	
Source of Re	lease:				Date and Hour	of Occurrence:	Date and	Hour of Discovery:	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required			ed	Date and Hour: If YES, Volume Impacting the Watercourse. Officers of the Constant of the Con			(2)		
By Whom?					Date and Hour	:	/m	100 2/1/2 201	
Was a Watercourse Reached? Yes No				If YES, Volume	e Impacting the V	/atercourse. \ຜູ້ ໃດ	IL CONS. DIV.		
THERE WAS	S NO PROBL ATISFY 19 1	LEM OR REM 5 17 13 E(4)	lial Action Taken.* EDIAL ACTION TAKEN T	HIS	FORM IS FILLE	D OUT TO SERV	E AS A COV	TER FOR LAB ANALYSES -	
2 33 37 12 2		О. С Р .							
regulations al public health should their cor or the environ	I operators are or the enviro operations have ment. In add	re required to r nment The ac ve failed to ade	n above is true and complete to eport and/or file certain releast ceptance of a C-141 report by quately investigate and remed Discreptance of a C-141 reportions	se not the diate	ifications and pe NMOCD marked contamination the es not relieve the	rform corrective ac l as "Final Report" at pose a threat to operator of respon	does not release does not relia ground water, sibility for co	ases which may endanger eve the operator of liability surface water, human health impliance with any other	
Signature	50%	Hash		OIL CONSERVATION DIVISION					
Printed Name	Ed Hasel	у		A	pproved by Distr	rict Supervisor			
Title	Sr Envir	onmental Engi	neer	A	pproval Date		Expiration E	Pate	
E-mail Addre	ss <u>ed hasely</u>	• <u>@energen com</u>	<u> </u>	С	onditions of App	roval		Attached	
Date 2/14/1	l P	Phone 505-324	-4131 / 505-330-3584(cell)						

^{*} Attach Additional Sheets If Necessary