



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-20-11 Operator Union Energy API # 30-0 45-28553

Property Name REBU Middle Mesa Well # 2 Location Unit M Sec 11 Twn 3 Rge 7

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒ _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____ DIST. 3
Int. Casing Pres. _____

Pressured annulus up to 408 psi. for 30 mins. Test passed failed
OIL CONS. DIV.

REMARKS.

Packer Set 8192
top Seal 8276
Bottom 9099
TD 9240

RCVD OCT 20 '11

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

LEASE OPERATOR Tech
(Position)

Revised 02-11-02