submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

5. **Lease Number**
   SF-078835

1. **Type of Well**
   GAS

6. **If Indian, All. or Tribe Name**

2. **Name of Operator**

   ConocoPhillips

7. **Unit Agreement Name**
   SAN JUAN 28-7 UNIT

3. **Address & Phone No. of Operator**

   PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. **Well Name & Number**
   SAN JUAN 28-7 UNIT 253N

9. **API Well No.**
   30-039-31032

4. **Location of Well, Footage, Sec., T, R, M**

   Unit H (SENE), 2394' FNL & 1099' FEL, Section 7, T27N, R7W, NMPM

10. **Field and Pool**
    Blanco MV/Basin DK

11. **County and State**
    Rio Arriba, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action		
___ Notice of Intent	___ Abandonment	___ Change of Plans	X Other – SPUD REPORT
	___ Recompletion	___ New Construction	
X Subsequent Report	___ Plugging	___ Non-Routine Fracturing	
	___ Casing Repair	___ Water Shut off	
___ Final Abandonment	___ Altering Casing	___ Conversion to Injection	

13. Describe Proposed or Completed Operations

9/27/11 MIRU MOTE 212. Spud w/ 12 1/4" bit @ 10·30 hrs on 9/27/11 Drilled ahead to 356'. Circ. hole.
9/28/11 TIH w/ 11 jts., 9 5/8", 32 3#, H-40, ST&C csgs, set @ 351'. RU to cmt. Pre-flush w/ 20 bbls gel pre-flush & 25 bbls FW spacer. Pumped 176 sx (224cf-40bbls=1.27 yld) Type III cmt., w/ 0.2% CACL2 & .25 pps cello-flakes Drop plug and displaced w/ 24 bbls FW. Bump plug @360# Circ 12 bbls cmt to surface. WOC. ND BOPE. RD RR @ 15.00 hrs on 9/28/11.

PT will be conducted by Drilling Rig. Results will appear on next report
APD/ROW

14. I hereby certify that the foregoing is true and correct.

Signed _____ Denise Journey Title Staff Regulatory Technician Date 9/30/11

(This space for Federal or State Office use)
APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

NMOCD