



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-2011 Operator Manana Gas API #30-0 45-26771

Property Name Cook Well No. #1E Location: Unit D Section 22 Township 29N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 206 Intermediate NA Casing 240 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>240</u>	<u>NA</u>	<u>NA</u>
10 min	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
15 min	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
20 min	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>Nothing</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

This is a plunger well, pressure taken half way through off time. The BH opened with a three second wisper of dry gas.

By

Lease Operator
(Position)

Witness _____

E-mail address _____

