



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-2011 Operator Mamana Gas API #30-0 45-26772

Property Name Tam Redding Well No. #1 Location: Unit D Section 22 Township 22N Range 11W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 182 Intermediate NA Casing 255 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>G</u>	<u>NA</u>	<u>255</u>	<u>NA</u>	<u>NA</u>	Steady Flow	
10 min	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	Surges	
15 min	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	Down to Nothing	
20 min	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	Nothing <u>Nothing</u>	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Well is stopclocked and producing tubing.

By

[Signature]
Lease Operator
(Position)

Witness _____

E-mail address _____