



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-2011 Operator Manana Gas API #30-0 45-27361

Property Name Laura Kelly Well No. #1 Location: Unit F Section 27 Township 29N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 381 Intermediate NA Casing NA Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
10 min	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
15 min	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
20 min	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
25 min	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>Nothing</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

This is a slimhole completion. There is
no casing valve to check

By

[Signature]
Lease Operator

Witness

E-mail address _____

