



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-19-2011 Operator Thompson E&P API #30-0 45-34116

Property Name Martin Well No. 34 Location: Unit 4 Section 3 Township 29N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate NA Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	BRADENHEAD			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>6</u>		
10 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
15 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
20 min	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>Nothing</u>	<u>Nothing</u>
25 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
30 min					
				Steady Flow	
				Surges	
				Down to Nothing	
				Gas	
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

This is a Rod pumped well with a compressor pulling on the casing. BH opened to a two second wisper of dry gas.

By Sgt H. Reb
lease operator
(Position)

Witness _____

E-mail address _____