District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Part of Devon Clean-up Program

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application								
Type of action: Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method								
Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request								
Please be advised that approval of this request does not relieve the operator of <u>liability</u> should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.								
Operator: DEVON ENERGY PRODUCTION COMPANY, L.P. OGRID #: 6137								
Address: c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401								
Facility or well name: NEBU #353								
API Number: 30-045-34647 OCD Permit Number:								
U/L or Qtr/Qtr C Section 5 Township 30-N Range 07-W County: San Juan								
Center of Proposed Design: Latitude <u>36.84621</u> Longitude <u>-107.59637</u> NAD: ☐1927 ☐ 1983								
Surface Owner: Federal State Private Tribal Trust or Indian Allotment								
Pit: Subsection F or G of 19.15.17.11 NMAC								
☐ Lined ☐ Unlined Liner type: Thicknessmil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other Liner Seams: ☐ Welded ☐ Factory ☐ Other								
Below-grade tank: Subsection I of 19.15.17.11 NMAC Subsection I of 19.15.17.11 NMA								
5. Alternative Method:								

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)	hospital,					
Signs: Subsection C of 19.15.17.11 NMAC 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers Signed in compliance with 19.15.3.103 NMAC						
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	office for					
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approach Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pabove-grade tanks associated with a closed-loop system.						
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No					
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No					
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA					
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA					
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No					
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No					
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No					
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No					
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No					
Within a 100-year floodplain FEMA map	☐ Yes ☐ No					

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC
Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan API Number:(Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System
☐ Alternative Proposed Closure Method: ☐ Waste Excavation and Removal
 ☐ Waste Removal (Closed-loop systems only) ☐ On-site Closure Method (Only for temporary pits and closed-loop systems)
In-place Burial On-site Trench Burial
Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: (19.15.17.13.D Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings. Use attachment if facilities are required.								
Disposal Facility Name: Disposal Facility Permit Number:	•							
Disposal Facility Name: Disposal Facility Permit Number:								
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and operations? Yes (If yes, please provide the information below) No								
Required for impacted areas which will not be used for future service and operations: Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	С							
17. <u>Siting Criteria (regarding on-site closure methods only)</u> : 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable south provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate disting considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Just demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	trict office or may be							
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA							
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA							
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA							
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No							
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	Yes No							
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No							
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No							
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☐ No							
Within a 100-year floodplain FEMA map	☐ Yes ☐ No							
18. On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan by a check mark in the box, that the documents are attached. □ Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC □ Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC □ Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.11 NMAC □ Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19. □ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC □ Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cann □ Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	15.17.11 NMAC							

Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.
Name (Print): Title:
Signature: Date:
e-mail address:Telephone:
20. OCD Approval: Permit Application (including closure plan) Closure Plan (only) COD Conditions (see attachment)
OCD Representative Signature: Approval Date:
Title: Compliance Offices OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.
Closure Completion Date: 10/20/08
22. Closure Method: ☐ Waste Excavation and Removal ☐ On-Site Closure Method ☐ Alternative Closure Method ☐ Waste Removal (Closed-loop systems only) ☐ If different from approved plan, please explain.
23. Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized.
Disposal Facility Name: Disposal Facility Permit Number:
Disposal Facility Name: Disposal Facility Permit Number:
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations? Yes (If yes, please demonstrate compliance to the items below) No
Required for impacted areas which will not be used for future service and operations: Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique
24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. □ Proof of Closure Notice (surface owner and division) □ Proof of Deed Notice (required for on-site closure) □ Plot Plan (for on-site closures and temporary pits) □ Confirmation Sampling Analytical Results (if applicable) □ Waste Material Sampling Analytical Results (required for on-site closure) □ Disposal Facility Name and Permit Number □ Soil Backfilling and Cover Installation □ Re-vegetation Application Rates and Seeding Technique □ Site Reclamation (Photo Documentation) ○ On-site Closure Location: Latitude N36.84621 Longitude W-107.59637 NAD: □1927 □ 1983
Operator Closure Certification:
I hereby certify that the information and attachments submitted with this closure report is true, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.
Name (Print): Mike Pippin Title: Petroleum Engineer
Signature: Date: June 23, 2009
e-mail address: mike@pippinllc.com Telephone: 505-327-4573

DEVON ENERGY PIT CLOSURE NEBU #353

Block #24, Box #4

The attached analytical data was taken by Blagg Engineering & analyzed by Envirotech Laboratories and passed all the State criteria.

Block #24, Box #6

All liquids were hauled to one of the following company disposal wells:

Middle Mesa SWD #2 SWD-441
Middle Mesa SWD #1 SWD-365
Simms Mesa SWD #1 SWD-339
Pump Mesa SWD #1 SWD-366

Block #24, Box #7

The liner was removed above "mud level" after stabilization. Pit contents were mixed with clean soil. After solidification and testing, the pit was backfilled with compacted, non-waste containing, soil. The pit was filled with clean excavated dirt and covered with 1 foot of top soil.

Block #24, Box #8

The area where the temporary drilling pit has been buried in place was seeded on 10/26/08 with 56 lbs of BLM seed mix for precipitation less than 10". The total acreage was 3.0 acres. The seed rate was 20 lbs PLS/acre for mechanical and 35 lbs PLS/acre for hand/broadcast and Harrow.

Submit To Appropriate District Office Two Copies District I				State of New Mexico Energy, Minerals and Natural Resources							Form C-105 July 17, 2008									
1625 N French Dr. District II												1. WELL API NO. 30-045-34647								
1301 W Grand Ave			'	Oil Conservation Division								2. Type of Lease								
1000 Rio Brazos Re District IV			,	1220 South St. Francis Dr. Santa Fe, NM 87505							3. State Oil & Gas Lease No									
WELL COMPLETION OR RECOMPLETION REPORT AND LOG															F igure 1					
4. Reason for filing:										5. Lease Nai	ne or U	nit Agre	ement N		eagroups relative to a common party of a					
COMPANIES DEPONDE (D. 11.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.									Northeast 6. Well Nun			t	`							
7. Type of Comp		WORKO	VER 🔲	DEEPE	NING	□PLUGBACE	ι 🗆 Ι	DIFFERE	NT RESE	ERVOIF	R OTHER									
NEW WELL											-									
10. Address of O	perator:										11. Pool nam	e or W	ildcat:			···				
12.Location	Unit Ltr	Sectio	n	Towns	hip	Range	Lot		Feet fro	m the	N/S Line	Feet	from th	e E/W	Line	County				
												1								
13. Date Spudded	1 14. Dat	te T.D. Rea	ached	15. D 8/13/		Iling Rig Releas	ed	16	. Date Co	mpleted	d (Ready to Pro	duce		17. Elev: RT, GR,		and RKB,				
18. Total Measur	ed Depth o	f Well		19. P	lug Bac	ck Measured De	pth	20	. Was Di	rection	al Survey Made	€?	21. Ty	pe Elect	tric and O	ther Logs Run				
22. Producing Int	terval(s), of	this comp	letion - T	Top, Bot	tom, Na	ame			, ,						' 					
23						ING REC	ORI													
CASING SI	ZE	WEIGI	HT LB./F	/FT. DEPTH SET HOLE SIZE						CEMENTING RECORD AMOUNT PULLED										
																				
24			•		1.00	ED DECORD				25		TIDI	NG RE	CORD						
SIZE	TOP		ВОТ	ТОМ	LIN	ER RECORD SACKS CEM		SCREE	N	ZE	ER SET									
26.	<u> </u>					<u> </u>		27. 40	ID SHO	YT ED	RACTURE, CEMENT, SQUEEZE, ETC.									
20.									ID, SHO		ACTURE, C									
								DUC												
Date First Produc	ction		Producti	ion Meth	iod <i>(Fla</i>	owing, gas lift, p	oumpin	ıg - Size a	nd type p	ump)	Well Statu	is (Pro	d. or Shi	ıt-ın)						
Date of Test	Hours	Tested	Cho	ke Size		Prod'n For		Oil - Bb	1	Ga	s - MCF	w	ater - Bl	i.	Gas - C	Oil Ratio				
Flow Tubing Press.	Casing	Pressure		culated 2 ir Rate	24-	Oil - Bbl.		Gas	- MCF	_ <u>:</u>	Water - Bbl.		Oil G	avity - 2	API - (Cor	r.)				
29 Disposition o	f Gas <i>(Sola</i>	l, used for	fuel, ven	ted, etc.,)	[i	<u>, </u>			30.	est Wit	nessed E	Ву:					
31 List Attachmo	ents							· ·				.l								
32. If a temporary	y pit was us	sed at the v	vell, attac	h a plat	with th	e location of the	tempo	orary pit.												
33. If an on-site b	ourial was u	ised at the	well, rep	ort the e	xact loc	cation of the on- Latitude		rial: 6.84621			Longitud	le -1	07.5963	7	NAD 19	27 1983 🖾				
I hereby certij	fy that the	e inform	ation sh	hown o		<i>h sides of this</i> Printed	form	is true		-	to the best	of my				f				
Signature	Me	ke t	yspi	M		Name Mik	e Pip	pin	Title	e: Peti	roleum Engi	neer	Da	te: 6/2	23/09					
E-mail Addres	ss: mike(a pippi $_{ m nl}$	lc.com																	

From: Castro, Melisa

Sent: Thursday, August 21, 2008 9:52 AM

To: BLM Land Notification

Subject: NEBU 353 Temporary Pit Closure Notification

Attachments: Pit Closure Plan.doc

Devon Energy Corporation 405 552 7917 Phone 20 North Broadway www.devonenergy.com Oklahoma City, OK 73102-8260

August 21, 2008

IN RE: NEBU 353 API # 30-045-34647 NE NW 970' FNL & 1,965' FWL Sec. 5, T30N, R7W San Juan County, New Mexico

VIA EMAIL:


Dear Mr. Kelly,

This submittal is pursuant to Rule 19.15.17.13 requiring operators to notify the surface owners of an on-site burial of a temporary pit. Devon Energy Production Company, L.P. is herby providing written documentation of our intention to close the temporary pit associated with the aforementioned location by means of in place on-site burial.

Please feel free to contact me with any questions or require further information. My contact information is listed below.

Respectfully,

Melisa S. Castro
Devon Energy Production Company, L.P.
Senior Staff Operations Technician
405-323-3184 - Cell.
405-323-1357 - Fax
Melisa.Castro@dvn.com



Towashin

Range

Los Ida

East/West line

Feet from the

RCVD SEP 25 '08 OIL CONS. DIV. DIST. 3

District I 1625 N. French Dr., Hobbs NM 88240

State of New Mexico

Form C-102 Revised October 12, 2005

District II

District III

UL or Lot No.

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87504-2088

Submit to Appropriate District Office State Lease - 4 Copies

1000 Rio Brazos Rd., Azicc, NM 87410 Dievica IV 1220 St. Francis Dr., Saraa Fe, NM 87505

Section

Fee Lease - 3 Copies

AMENDED REPORT

County

WELL LOCATION AND ACREAGE DEDICATION PLAT


API Number	1 19	of Code	Pool Namo
30-045-3460	17 7159	g Basin Dalcota	
* Property Code		1 Property Name	4 Well Number
19641	NEBU		353
OGRID No.		Operator Nama	*Elevatina
6137	Devon Ener	6322	
	 	10 Surface Location	

SAN JUAN WEST C 5 30 N 7 W 970 1965 NORTH "Bottom Hole Location If Different From Surface Pect from the SAN JUAN WEST F 5 30 N 7 W 1841 NORTH 1707 Joim or Infill 12319.52

Feet from the

North/South line

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED




09/18/2008 8:03AM (GMT-05:00)



.6310

PAD LAYOUT PLAN & PROFILE DEVON ENERGY PRODUCTION COMPANY, L.P.



08/20/2008 9:02AM (GMT-05:00)

Farmington, NM

CHAIN OF CUSTODY RECORD

Client: Project Name / Location: BLAGG / DEWN TEMPORARY PLT CLOSURES								•	ANALYSIS / PARAMETERS														
BLAGG DEWN TEMPORARY PLT CO									-	T 📻			1	I	l						[
onem Addioss.			ampier rvame.		•				8015)	1 802	8260	<u>s</u>											
Client Phone No.: -		C	Client No.: 94034 -	-010	10					BTEX (Method 8021)	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion		TCLP with H/P		TPH (418.1)	RIDE				Sample Cool	Sample Intact
Sample No./ Identification	Sample Date	Sample Time	Lab No.	_ N	ample fatrix	No./Volume of Containers	Prese	ervativ HCI	TPH (Method 8015)	BTEX	Voc (RCRA	Cation	교	TCLP	РАН	тРН (CHLORIDE				Sampl	Sampl
NEBU 37B S-Point Coup	10/2/53	1230	47708	Soil Solid	Sludge Aqueous	1-402			×	×							×	×				1	V
S-POINT COUP NEBU 421 A 5-POINT COMP NEBU 472 A		1500	47709	Soil) Solid	Sludge Aqueous	1-402			×	بد							×	٧				~	ν
5-00 T (.	10/3/03	1600	47770	Soil Solid	Sludge Aqueous	1-402			×	بر							Х	メ				<u> </u>	
NEBU 353 5-point comp	10/9/03	1400	47711	Soil Solid	Sludge Aqueous	1-402			بخ	بد							ン	メ				✓	1
				Soil Solid	Sludge Aqueous																		
				Soil Solid	Słudge Aqueous																		
				Soil Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous					2													
Relinquished by: (Signa Relinquished by: (Signa	ature) 299				Date 10/03	Time 1524	- 1	leceiv	ed by	(Sign	ature)	1	٦,		Ž.	-			•	0/1	ate C &	lS.	me 24
Relinquished by: (Signa	ature)						R	Receiv	ed by:	(Sign	ature))	J								T		
Relinquished by: (Signa	ature)						R	Receiv	ed by:	(Sign	ature)											
							<u> </u>	<u> </u>		10	<u>. </u>					•						<u> </u>	

ENVIROTECH INC.

5796 U.S. Highway 64 • Farmington, NM 87401 • Tel 505-632-0615



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	Blagg/Devon	Project #:	94034-0010
Sample ID:	NEBU 353	Date Reported:	10-23-08
Laboratory Number	47711	Date Sampled:	10-09-08
Chain of Custody No:	5538	Date Received:	10-10-08
Sample Matrix:	Soil	Date Extracted:	10-15-08
Preservative:	Cool	Date Analyzed.	10-16-08
Condition.	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	52.5	0.1
Total Petroleum Hydrocarbons	52.5	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996

Comments:

Temporary Pit Closures, 5-Point Comp.

Analyst

Review

5796 U.S. Highway 64 • Farmington, NM 87401 • Tel 505-632-0615 • Fax 505-632-1865



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Blagg/Devon	Project #:	94034-0010
Sample ID:	NEBU 353	Date Reported:	10-23-08
Laboratory Number:	47711	Date Sampled:	10-09-08
Chain of Custody:	5538	Date Received:	10-10-08
Sample Matrix:	Soil	. Date Analyzed:	10-16-08
Preservative:	Cool	Date Extracted:	10-15-08
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	1.9	0.9	
Toluene	8.4	1.0	
Ethylbenzene	4.4	1.0	
p,m-Xylene	16.3	1.2	
o-Xylene	8.3	0.9	
Total BTEX	39.3		

ND - Parameter not detected at the stated detection limit

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	98.0 %
	1,4-difluorobenzene	98.0 %
	Bromochlorobenzene	98.0 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Temporary Pit Closures, 5-Point Comp.

Analyst

Review



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	Blagg / Devon	Project #:	94034-0010
Sample ID:	NEBU 353 5-Point Comp	Date Reported:	10-27-08
Laboratory Number:	47711	Date Sampled:	10-09-08
Chain of Custody No:	5538	Date Received:	10-10-08
Sample Matrix:	Soil	Date Extracted:	10-16-08
Preservative:	Cool	Date Analyzed:	10-16-08
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

277

5.0

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Temporary Pit Closures.

Analyst

Mester of Walter Review



Chloride

Client: Blagg/Devon Project #: 94034-0010 Sample ID: NEBU 353 5-Point Comp Date Reported: 10-25-08 Lab ID#: 47711 Date Sampled: 10-09-08 Sample Matrix: Soil Date Received: 10-10-08 Preservative: Cool Date Analyzed: 10-20-08 Condition: Intact Chain of Custody: 5538

Parameter Concentration (mg/Kg)

Total Chloride

160

Mestre Welles Review

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Standard Method For The Examination of Water and Waste Water", 18th ed., 1992.

Comments:

Temporary Pit Closures.

Analyst



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client:	QA/QC	Project #:	N/A
Sample ID:	10-16-08 QA/QC	Date Reported:	10-23-08
Laboratory Number:	47704	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	10-16-08
Condition:	N/A	Analysis Requested:	TPH .

	I-Cal Date	I-Cal RF.	C-Cal-RF	% Difference	Accept Range
Gasoline Range C5 - C10	05-07-07	9.9761E+002		0.04%	0 - 15%
Diesel Range C10 - C28	05-07-07	9.9483E+002	9.9523E+002	0.04%	0 - 15%

Blank Conc. (mg/L - mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	ND ·	0.2
Diesel Range C10 - C28	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept. Range
Gasoline Range C5 - C10	ND	ND	0.0%	0 - 30%
Diesel Range C10 - C28	ND	ND	0.0%	0 - 30%

Spike Conc. (mg/Kg)	Sample	Spike Added	Spike Result	% Recovery	Accept Range
Gasoline Range C5 - C10	ND	250	245	98.0%	75 - 125%
Diesel Range C10 - C28	ND	250	249	99.6%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 47704 - 47711, and 47717.

Analyst

Review



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	N/A	Project #:	N/A
Sample ID:	10-16-BT QA/QC	Date Reported:	10-23-08
Laboratory Number:	47704	Date Sampled:	N/A
Sample Matrix:	Soil	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	10-16-08
Condition:	N/A	Analysis:	BTEX

Calibration and Detection Limits (ug/L)	l-Cal.RF:	C-Cal RF: Accept. Rand	%Diff je∙0 - 15%	Blank Conc	Detect Limit
Benzene	4.9879E+007	4 9979E+007	0.2%	ND	0.1
Toluene	3.3740E+007	3.3808E+007	0.2%	ND	0.1
Ethylbenzene	2.6762E+007	2'6815E+007	0.2%	ND	0.1
p,m-Xylene	6.0299E+007	6.0420E+007	0.2%	ND	0.1
o-Xylene	2.7778E+007	2 7834E+007	0.2%	ND .	0.1

Duplicate Conc. (ug/Kg)	Sample Di	uplicate	%Diff.	Accept-Range	Detect Limit
Benzene	4.9	4.9	0.0%	0 - 30%	0.9
Toluene	10.6	10.8	1.9%	0 - 30%	1.0
Ethylbenzene	14.3	14.4	0.7%	0 - 30%	1.0
p,m-Xylene	63.7	63.9	0.3%	0 - 30%	1.2
o-Xylene	21.8	21.5	1.4%	0 - 30%	0.9

Spike Conc. (ug/Kg)	Sample Amo	unt Spiked Spik	ked Sample	% Recovery	Accept Range
Benzene	4.9	50.0	53.9	98.2%	39 - 150
Toluene	10.6	50.0	55.6	91.7%	46 - 148
Ethylbenzene	14.3	50.0	62.3	96.9%	32 - 160
p,m-Xylene	63.7	100 👾	156	95.1%	46 - 148
o-Xylene	21.8	50. 0	68.8	95.8%	46 - 148

ND - Parameter not detected at the stated detection limit.

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 47704 - 47705, 47708 - 47711, and 47717.

Analyst

Review



EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT

			•
Client:	QA/QC	Project #:	N/A
Sample ID:	QA/QC	Date Reported:	10-27-08
Laboratory Number:	10-16-TPH.QA/QC 47710	Date Sampled:	N/A
Sample Matrix:	Freon-113	Date Analyzed:	10-16-08
Preservative:	N/A	Date Extracted:	10-16-08
Condition:	N/A	Analysis Needed:	TPH:
			en e

:Calibration :: Ca	il Date ::C	-Cal Date : :: I-Ca	al RF: C-Ca	al RF: % Diff	erence i	Accept, Range
10-0	06-08 1	0-16-08	1,770	1,790	1.1%	+/- 10%

prior contrat terrip it was a recommendation of a recommendation whereas a contration to a contrational and	*4***********************************	<i>የቀናቀነሚ የአካ</i> ለን እነተት፣እነኛውም (ፍላማራርርር የአስቀ <mark>ቀ</mark> ፉ ለ <mark>ነኛ አለስም የመጀመቸው የርፈንተርር ም</mark> ልት ለረዚ ፣	PROGRAMMENT CONTRACTOR OF THE CONTRACT OF THE CONTRACTOR OF THE CO
		A TOTAL STREET, THE STREET, TH	# ", FE KN"0";
- Wienvierence in aus das establishes	Concontration	STATE OF A PROPERTY OF A PROPE	CHARLE COST 100 CLASS (2000)
		CONTRACTOR DE LE CLION DE INTRACTOR DE LA CONTRACTOR DE L	COVERNO SERVICE
Blank Conc. (mg/Kg)	SECTION 100 1 (A. 187 PROPERTY LA CONTRACTOR OF THE PROPERTY AND ADDRESS AND A		THE RESERVE OF THE PROPERTY OF THE PARTY OF
A. Condemney and Control of the Cont	Market State Committee of the Committee		
TOU	NIP.	P 7	•
1 PH	ND	~ /	
11 11	110	0.7	,

Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept: Range
TPH	150	128	15.1%	+/- 30%

Spike Conc. (mg/Kg)	: Sample	Spike Added	Spike Resul	% Recovery	Accept Range
TPH	150	2,000	2,060	95.8%	80 - 120%

ND = Parameter not detected at the stated detection limit.

References: Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments: QA/QC for Samples 47699, 47701, 47706 - 47711, 47723 and 47724.

Analyst

Mustem on W

WELL SITE DOCUMENTATION

Company Name: DEVON ENERGY Well Name: NEBU 353

Legal Description: Section 5 TWNSHP 30N Range 7W

County: San Juan State: NM

Area Seeded: (See Attached Digital Photos) Dates of Seeding: 10/26/2008

Seed Mix: Southwest Colorado Seed less than 10 BLM NM/CO Certified Mix NOTE: Application rate is based upon pure live seed (PLS). BLM certified seed is delivered from Dolores, Colorado in 20 lb. sacks. 100% PLS PER BAG. Included in the cost to customer per acre is \$6.40 per PLS pound. BLM recommended seeding rate for mechanical application is 13.25 LBS PLS per acre and 26.50 LBS per acre for broadcast application. *Based upon BLM application rate chart dated May 5, 2006*

Seed Rate: Mechanical:

20.00 lbs PLS/acre

Hand/Broadcast and Harrow:

35.00 lbs PLS/acre

*Based upon BLM application rate chart

Note: An additional .50 acre charge for rocky topsoil conditions.

No-Till Drill Application Acreage:

Total: 3.0 Acres

Total Acreage Seeded:

Mechanical + Hand/Broadcast Harrow Application TOTAL: 3 Acres 56 Lbs

Seeding Process:

2006 John Deere 5205 MFW 56 HP Tractor 2004 Great Plains No-Till Drill Model 605 NT

2006 Land Pride Broadcast

2006 8 ft. Harrow

Topography: Dry clay top soil conditions with some evidence of small to medium sized rock. Very little tree debris. Some slope conditions on three sides of location. Preharrowed area followed by no-till drill application.

Comments: A separate invoice will be created for the following services rendered:


•	Operator Hourly Rate:	\$35.00 X 9.5 =	\$332.50
•	Tractor Hourly Rate:	\$75.00 X 4.5 =	\$337.50
•	Fuel/Milage Surcharge:	\$2.00 X 154 Miles =	\$308.00
•	Seeding Cost:	\$600.00 Per Acre X 3.0 acres =	\$1.800.00

NOTE: Cost includes the use of seeders and seed cost per acre.


• Total Invoice Cost: \$2,778.00


NOTE: There is a minimum charge of \$600.00 per acre for each well site.

ST Seeding and Tractor P.O. Box 551 Bloomfield, NM 87413 Ph: 505.793.0364



NEBU #353





DEVON ENERGY PRODUCTION COMPANY, L.P.

Mike Pippin 3104 N. Sullivan Avenue Farmington, NM 87401

505-327-4573 (phone) mike@pippinllc.com

October 27, 2011

NMOCD c/o Jonathan Kelly 1000 Rio Brazos Rd. Aztec, NM 87410

> Pit Closure Packages from 2008 and 2009, Form C-144 RE:

> > Northeast Blanco Unit

Dear Mr. Kelly,

I have reviewed the list of Northeast Blanco Unit wells you sent me on 10/26/11. As you indicated, many of the pit closure packages from 2008 and 2009 on these wells did not include proof that notice was given to the NMOCD within one week of the drilling pit closure, nor did they include proof of the pit inspections. Although we believe that both the notices and the pit inspections occurred, this was an oversight that the proof was not included in the pit closure packages. Unfortunately, this data is no longer available.

In the future, Devon will include proof of drilling pit closure notice and pit inspection logs in all drilling pit closure packages.

Please contact me at 505-327-4573 should you have any questions.

Very truly yours

Mike Pippin PE

Petroleum Engineer

FOND OUT of the

011 COMS. 019.

D#57 3