District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance

Form C-141

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

## **Release Notification and Corrective Action OPERATOR** Initial Report X Final Report Name of Company Enervest Operating LLC Contact Lee Gardner Address 2700 Farmington Ave. Bld - K. Suite #1. Telephone No. 505-325-0318 Ext 13 Farmington, NM 87401 Facility Name Apache 127 -131 - 4 Facility Type Oil well Surface Owner Jicarilla Apache Tribe Mineral Owner Jicarilla Apache Tribe Lease No. 127 LOCATION OF RELEASE Feet from the North/South Line Feet from the East/West Line Unit Letter Section Township Range County 24N 4W 660 1980 C 4 North West Rio Arriba **Latitude** N 36. 20.85 **Longitude** W 107.15.83 NATURE OF RELEASE Type of Release Oil Volume of Release Volume Recovered Estimated 15 barrels None Source of Release Rod packing Date and Hour of Occurrence Date and Hour of Discovery Unknown 9-20-2011 11:00 AM Was Immediate Notice Given? If YES, To Whom? If YES, To Whom? Dixon Sandoval Jicarilla Apache Tribal Oil and Gas Administrator 202526272829 Required By Whom? Bill Julian Date and Hour 9-20-2011 11:15 AM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes X☐ No If a Watercourse was Impacted, Describe Fully.\* Not Applicable Describe Cause of Problem and Remedial Action Taken.\* Rod packing leaked approximately 15 barrels of oil onto the ground. The oil flowed off of the location and down a slope to the west about 300 yards off of the location. The rod packing has been replaced. Describe Area Affected and Cleanup Action Taken.\* The soil on the well pad and the impact area were removed and transported to TNT land farm. Approximately twenty 20 yard loads of soil were removed. The area was contoured using soil from a dry pond located approximately 100 yards from the impacted slope. Erosion control weirs were installed per Jicarilla Apache Tribal instructions. The area will be reseeded per Jicarilla Apache Tribal instructions. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: 3 Approved by District Supervisor: 'Printed Name: Lee Gardner Approval Date: 10/18/1 Expiration Date: Title: Sr, HSE Specialist Conditions of Approval: E-mail Address: Wgardner@enervest.net Attached |

Phone: 505-325-0318 Ext 13

Date: 9-26-2011

<sup>\*</sup> Attach Additional Sheets If Necessary