

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

30-045-21786

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Co.	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Florance K29A	Facility Type: natural gas well API # 300452178600	
Surface Owner: federal	Mineral Owner: federal	Lease No. SF - 078385


#### LOCATION OF RELEASE

Unit Letter F	Section 25	Township 30N	Range 08W	Feet from the 1850	North/South Line North	Feet from the 1850	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.78503 Longitude 107.62985

#### NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 297 MCF	Volume Recovered: none
Source of Release: compressor	Date and Hour of Occurrence: 8/19/2011 at 12 pm to 8/20/2011 at 9 am	Date and Hour of Discovery: 8/22/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A hung suction scrubber dump valve/controller was source of release.		
Describe Area Affected and Cleanup Action Taken.* The valve would not reseal, so the compressor was blown down, the well shut-in and the dump controller replaced. All gas dissipated to the atmosphere, so no clean-up action was possible		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		



Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental Challenger	Approval Date: 10/11/11	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/29/2011 Phone: 505-326-9457		

\* Attach Additional Sheets If Necessary

NJK1129251562