

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-32038

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company	Dugan Production Corp.	Contact	Rodger Mullins (505-320-5443)
Address	P. O. Box 420, Farmington, NM 87499-0420	Telephone No.	(505)325-1821
Facility Name	Patriot # 93S	Facility Type	Coal Seam Well
Surface Owner	Federal	Mineral Owner	
		Lease No.	SF078091

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	26N	13W	790	South	790	East	San Juan

Latitude 36.45416 Longitude 108.21750

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release approx 240 bbls	Volume Recovered 240 bbls
Source of Release	Tank over flowed	Date and Hour of Occurrence 06/28/11 PM or 06/29/11 AM	Date and Hour of Discovery 06/29/11 0900
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Brandon Powell BLM-Report Hot Line & Bill Liess RCVD JUL 6 11 OIL CONS. DIV.	
By Whom?	Rodger Mullins	Date and Hour	06/30/11 1:00 PM
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. DIST. 3	
If a Watercourse was Impacted, Describe Fully.*			
Describe Cause of Problem and Remedial Action Taken.* An unknown person shut gas valve at a separator causing pressure to build in water pipeline, which in turn caused tank to over flow. Water was shut down & spilled water was sucked up.			
Describe Area Affected and Cleanup Action Taken.* Produced water made 10' wide path on north edge of location. Water then ran off location approximately 150' into a dry earth tank. Water was sucked out of earth tank. When area dries Gypsum will be raked into contaminated area.			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Rodger Mullins		Approved by District Supervisor: 	
Title: Environmental		Approval Date: 7/6/11	Expiration Date:
E-mail Address:		Conditions of Approval:	
Date: July 1, 2011 Phone: (505)325-1821		Attached <input type="checkbox"/> NJK 1122341485	

* Attach Additional Sheets If Necessary