District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

8148

Pit, Closed-Loop System, Below-Grade Tank, or oposed Alternative Method Permit or Closure Plan Application

rype or action:	Referrit of a pit, closed-loop system, below-grade tank, or proposed alternative method
Existing BGT	Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method
	Modification to an existing permit
	Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system,
below-grade tani	(or proposed alternative method

Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request

Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinance

XTO Energy, Inc. OGRID #: 5380	
#382 County Road 3100, Aztec, NM 87410	
rwell name: WF State 2#2	
ber: 3004531292 OCD Permit Number:	
tr/Qtr C Section 02 Township 30N Range 14W County: San Juan	
Proposed Design Latitude 36.84784 . Longitude 108.282397 NA	AD: 🔲 1927 🖾 1983
Owner: 🞵 Federal 🛣 State 🗌 Private 🔲 Tribal Trust or Indian Allotment	
)
Subsection F or G of 19.15.17.11 NMAC	
ry: Drilling Workover	
nnent	,
Unlined Liner type: Thicknessmil	
r-Reinforced	
ims: Welded Factory Other Volume: bbl Dimensions: L x	Wx D
d-loop System: Subsection H of 19.15.17.11 NMAC	
Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval o	f a permit or notice of
g Pad Above Ground Steel Tanks Haul-off Bins Other	1718100
Unlined Liner type: Thicknessmil	A 403
nms: Welded Factory Other	* E
v-grade tank: Subsection I of 19.15.17.11 NMAC	IPR 2011! §
95 bbl Type of fluid: Produced Water OIL Co	ONS. DIV. DIST. 3 🧳
nstruction material: Steel	ONS. DIV. DIST. 3
ndary containment with leak detection 🔲 Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off	1-150560
olc sidewalls and liner Visible sidewalls only Other Visible sidewalls, vaulted, automatic high-level shut off, no	liner
e: Thicknessmil	
native Method:	

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required of located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify Four foot height, steel mesh field fence (hogwire) with pipe top railing	hospital,							
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top`tanks) Screen Netting Other Expanded metal or solid vaulted top Monthly inspections (If netting or screening is not physically feasible)								
8. Signs: Subsection C of 19.15.17.11 NMAC ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers ☐ Signed in compliance with 19.15.3.103 NMAC	·							
9. Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau of consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.								
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying above-grade tanks associated with a closed-loop system.								
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ⊠ No							
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ⊠ No							
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ⊠ No ·							
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent puts)	☐ Yes ☐ No ☑ NA							
 Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site 	☐ Yes ⊠ No							
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ⊠ No							
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ⊠ No							
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ⊠ No							
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ☑ No							
Within a 100-year floodplain FEMA map	☐ Yes ☑ No							

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan API Number: (Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. □ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15 17 13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) □ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: (19.15.17.13.L Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings. Use attachment if n	NMAC) nore than two											
facilities are required. Disposal Facility Name: Disposal Facility Permit Number:												
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will not be used for future service and operations Yes (If yes, please provide the information below) No												
Required for impacted areas which will not be used for future service and operations: Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC												
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable soun provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate dist. considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justi demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	rict office or may be											
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA											
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA											
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No											
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No											
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No											
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database, Visual inspection (certification) of the proposed site	☐ Yes ☐ No											
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality, Written approval obtained from the municipality	☐ Yes ☐ No											
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No											
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No											
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	☐ Yes ☐ No											
Within a 100-year floodplain FEMA map	☐ Yes ☐ No											
On-Site Closure Plan Checklist: (19.15 17.13 NMAC) Instructions: Each of the following items must be attached to the closure ple by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.11 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cann Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	15.17.11 NMAC											

Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and co	omplete to the best of my knowledge and belief.
	tle: Environmental Representative
Signature: Kim Champlin	Date:11/24/08
•	ephone:(505) 333-3100
Closure Report (required within 60 days of closure completion): Subsection K of 19.1 Instructions: Operators are required to obtain an approved closure plan prior to implem The closure report is required to be submitted to the division within 60 days of the complete section of the form until an approved closure plan has been obtained and the closure act	enting any closure activities and submitting the closure report. etion of the closure activities. Please do not complete this
Closure Method: Waste Excavation and Removal ☐ On-Site Closure Method ☐ Alternative Clos☐ If different from approved plan, please explain.	ure Method Waste Removal (Closed-loop systems only)
Disposal Facility Name: Dispos Were the closed-loop system operations and associated activities performed on or in areas Yes (If yes, please demonstrate compliance to the items below) No	al Facility Permit Number: al Facility Permit Number: that will not be used for future service and operations?
Required for impacted areas which will not be used for future service and operations: Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	• 1
Closure Report Attachment Checklist: Instructions: Each of the following items must mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Longitude	be attached to the closure report. Please indicate, by a check NAD: 1927 1983
Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure report is t belief. I also certify that the closure complies with all applicable closure requirements and Name (Print): Signature: Tit	conditions specified in the approved closure plan.

<u>District I</u> 1625 N French Dr., Hobbs, NM 88240 <u>District II</u> District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fc, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141 Revised October 10, 2003

1220 South St. Francis Dr. side of form

			Kele	ease Nounca	atioi	n and Co	rrective A	ction						
						OPERA	ГOR	☐ In:	tial Report	\bowtie	Final Report			
Name of Co	mpany: X	TO Energy,	Inc.			Contact: James McDaniel								
Address: 382 Road 3100, Aztec, New Mexico 87410						Telephone N	No.: (505) 333-3	701						
Facility Nar	ne: WFS	tate 2 #2 (30	-045-312	92)		Facility Typ	e: Gas Well (Fr	uitland Coal)			-			
Surface Ow	ner: State			Mineral Ov	wner:		•	Lease	No.:					
				LOCA	TIO	N OF RE	LEASE							
Unit Letter C	Section 30	Township 27N	Range 11W			/South Line FNL	Feet from the 1450	County San Juan	County San Juan					
				Latitude: 36.8		-		,						
Torra of Dala	Duad			NATU	URE	OF RELI		1 3/-1	D 1	NIA				
Type of Rele		w Grade Tank					Release: Unknow		Recovered:		· Linknown			
Source of ite	icase. Delo	W Grade Tank				Unknown	our or occurrenc	c. Date at	id Hour of Di	scovery.	Cikilowii			
Was Immedia	ate Notice (Yes [] No 🛛 Not Req	quired	If YES, To	Whom?							
By Whom?	* *	·····				Date and F	lour							
Was a Water	course Read	ched?	Yes 🗵] No		If YES, Vo	lume Impacting t	he Watercourse.						
If a Watercou	ırse was Im	pacted, Descr	be Fully.	*										
The below g was collected BTEX via US and total BTI ranked a 0 pt	rade tank w I beneath th SEPA Meth EX, but abo Irsuant to th	e location of tood 8021, and we the total character of the NMOCD G	f service and on-site for total elloride startide startide startide startide startide startide for the starting of the startin	at the W F State 2 # BGT, and submitte hlorides. The samp ndard of 250 ppm a for the Remediatior 00 feet. This set the	ed for lole retu it 540 p n of Le	laboratory and urned results b ppm, confirmicaks, Spills an	dysis for TPH via below the 'Pit Rul- ng that a release I d Releases due to	USEPA Methode' spill confirmanas occurred at the depth to ground	1418.1 and 8 tion standard is location. dwater of ov	015, ben s for TPI The site er 100 fe	nzene and H, benzene was then eet, and a			
The NMOCE	Guideline:	and Cleanup A s for the Reme all constituent	diation of	ken.* f Leaks, Spills and l d. No further action	Releas n is ne	ses does not ci cessary. Ana	te a standard for c ytical results are	chlorides. The sa	imple returne reference.	d results	below the			
regulations a public health should their or the environment.	Il operators or the enviroperations homent. In a	are required to ronment. The nave failed to a	report ar acceptand dequately CD accep	is true and comple nd/or file certain rel ce of a C-141 repore investigate and rel tance of a C-141 re	lease n t by th mediat	notifications and ne NMOCD m te contaminati	nd perform correct arked as "Final Roon that pose a three the operator of the	tive actions for report" does not reat to ground waresponsibility for	eleases which elieve the op- ter, surface we compliance	h may en erator of vater, hur with any	ndanger Fliability man health			
Signature:			\angle				OIL CONS	SERVATIO	N DIVISI	<u>ON</u>				
Printed Name	e. James Mo	CDaniel	~			Approved by District Supervisor:								
Title: EH&S	Specialist					Approval Da	e:	Expiration	n Date:					
E-mail Addre	ess: James_	McDaniel@xt	oenergy.c	om		Conditions of	Approval:		Attache	d 🔲				
Date: 4/14/2	011		P	hone: 505-333-370	1_									

^{*} Attach Additional Sheets If Necessary

XTO Energy Inc. San Juan Basin Below Grade Tank Closure Report

Lease Name: W F State 2 #2 API No.: 30-045-31292

Description: Unit C, Section 2, Township 30N, Range 14W, San Juan County

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure requirements of below-grade tanks on XTO Energy Inc. (XTO) locations. This is XTO's standard procedure for all below-grade tanks. A separate plan will be submitted for any below-grade tank which does not conform to this plan.

General Plan

1. XTO will close below-grade tanks within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the division requires because of imminent danger to fresh water, public health or the environment.

Closure Date is January 3, 2011

2. XTO will close a below-grade tank that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofitted to comply with Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC.

Closure Date is January 3, 2011

3. XTO will close a permitted below-grade tank within 60 days of cessation of the below-grade tank's operation or as required by the transitional provisions of Subsection B of 19.15.17.17 NMAC in accordance with a closure plan that the appropriate division district office approves. The closure report will be filed on form C-144.

Required C-144 Form is attached to this document.

4. XTO will remove liquids and sludge from below-grade tanks prior to implementing a closure method and will dispose of the liquids and sludge in a division-approved facility. Approved facilities and waste streams include:

Envirotech Permit No. NM01-0011 and IEI Permit No. NM 01-0010B Soil contaminated by exempt petroleum hydrocarbons Produced sand, pit sludge and contaminated bottoms from storage of exempt wastes

Basin Disposal Permit No. NM01-005

Produced water

All liquids and sludge were removed from the tank prior to closure activities.

5. XTO will remove the below-grade tank and dispose of it in a division approved facility or recycle, reuse, or reclaim it in a manner that the appropriate division district office approves.

XTO has removed the below grade tank, and will dispose of it at a division approved facility, or recycle, reclaim or reuse it in a manner that is approved by the division.

6. XTO will remove any on-site equipment associated with a below-grade tank unless the equipment is required for some other purpose.

All equipment has been removed due to the plugging and abandoning of the W F State 2 #2 well site.

7. XTO will test the soils beneath the below-grade tank to determine whether a release has occurred. At a minimum 5 point composite sample will be collected along with individual grab samples from any area that is wet, discolored or showing other evidence of a release. Samples will be analyzed for BTEX, TPH and chlorides to demonstrate that the benzene concentration, as determined by EPA SW-846 methods 8021B or 8260B or EPA method that the division approves, does not exceed 0.2 mg/kg; total BTEX concentration, as determined by EPA SW-846 methods 8021B or 8260B or other EPA method that the division approves, does not exceed 50 mg/kg; the TPH concentration, as determined by EPA method 418.1 or other EPA method that the division approves, does not exceed 100mg/kg; and the chloride concentration, as determined by EPA method 300.1 or other EPA method that the division approves, does not exceed 250 mg/kg, or the background concentration, whichever is greater. XTO will notify the division of its results on form C-141.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Test Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	BDL mg/kg
BTEX	EPA SW-846 8021B or 8260B	50	BDL mg/kg
TPH	EPA SW-846 418.1	100	ND mg/kg
Chlorides	EPA 300.1	250 or background	540 mg/kg

8. If XTO or the division determines that a release has occurred, XTO will comply with 19.15.3.116 NMAC and 19.15.1.19NMAC as appropriate.

Due to a total chloride results of 540 ppm, it has been determined that a release has occurred at this location. The site was then ranked a 0 pursuant to the NMOCD Guidelines for the Remediation of Leaks, Spills and Releases due to a depth to groundwater of over 100 feet, and a distance to a significant watercourse of over 1,000 feet. This set the closure standard to 5,000 ppm TPH, 10 ppm benzene and 50 ppm total BTEX. No chloride standard is cited in the Guidelines for the Remediation of Leaks, Spills and Releases. The sample returned results below the regulatory standard for all constituents analyzed. No further action is necessary.

9. If the sampling program demonstrates that a release has not occurred or that any release does not exceed the concentrations specified in Paragraph (4) of Subsection E of 19.15.17.13 NMAC, XTO will backfill the excavation with compacted, non-waste containing, earthen material; construct a division prescribed soil cover; recontour and re-vegetate the site.

The pit cellar was backfilled using compacted, non-waste containing earthen material, with a division prescribed soil cover.

- 10. Notice of Closure operations will be given to the Aztec Division District III office between 72 hours and one week prior to the start of closure activities via email or verbally. The notification will include the following:
 - i. Operator's name
 - ii. Well Name and API Number
 - iii. Location by Unit Letter, Section, Township, and Range

Notification was provided to Mr. Brandon Powell with the Aztec office of the OCD via email on December 28, 2010; see attached email printout.

The surface owner shall be notified of XTO's proposal to close the BGT as per the approved closure plan using certified mail, return receipt requested.

The surface owner was notified on December 28, 2010; see attached letter and return receipt.

11. Re-contouring of location will match fit, shape, line, form and texture of the surrounding area. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be placed in areas where needed to prevent erosion on a large scale. Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The location has been recontoured to match the above specifications.

12. A minimum of 4 feet of cover shall be achieved and the cover shall include 1 foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

The site has been backfilled to match these specifications.

13. XTO will seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will be used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

The location has been reclamed pursuant to the BLM MOU.

- 14. All closure activities will include proper documentation and be available for review upon request and will be submitted in closure report form to OCD within 60 days of closure of the below-grade tank. Closure report will be filed on form C-144 and incorporate the following:
 - i. Proof of closure notice to division and surface owner; attached
 - ii. Details on capping and covering, where applicable; per OCD Specifications
 - iii. Inspection reports; attached
 - iv. Confirmation sampling analytical results; attached
 - v. Disposal facility name(s) and permit number(s); see above
 - vi. Soil backfilling and cover installation; per OCD Specifications
 - vii. Re-vegetation application rates and seeding techniques, (or approved alternative to re-vegetation requirements if applicable); **Per BLM MOU**
 - viii. Photo documentation of the site reclamation. attached
- 15. This closure report is being submitted after the 60 day deadline required by the 'Pit Rule' due to a unforeseen delay on final reclamation of this well site. This delay was due to the pipeline riser not being removed by the gathering company in a timely fashion.



COVER LETTER

Monday, January 03, 2011

James McDaniel XTO Energy 382 County Road 3100 Aztec, NM 87410

TEL: (505) 787-0519 FAX (505) 333-3280

RE: WF State 2-2

Dear James McDaniel:

Order No.: 1101002

Hall Environmental Analysis Laboratory, Inc. received 1 sample(s) on 1/3/2011 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. Below is a list of our accreditations. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites.

Reporting limits are determined by EPA methodology.

Please do not hesitate to contact HEAL for any additional information or clarifications.

Sincerely,

Andy Freeman, Laboratory Manager

NM Lab # NM9425 NM0901 AZ license # AZ0682

ORELAP Lab # NM100001

Texas Lab# T104704424-08-TX



Hall Environmental Analysis Laboratory, Inc.

Date: 03-Jan-11

CLIENT:

XTO Energy

Client Sample ID: BGT Closure Composite

Lab Order:

1101002

Collection Date: 1/3/2011 11:00:00 AM

Project:

WF State 2-2

Date Received: 1/3/2011

Lab ID:

1101002-01

Matrix: SOIL

Analyses Result		PQL Qua	l Units	DF	Date Analyzed
EPA METHOD 418.1: TPH					Analyst: JB
Petroleum Hydrocarbons, TR	ND	20	mg/Kg	1	1/3/2011

Qualifiers:

- Value exceeds Maximum Contaminant Level
- E Estimated value
- Analyte detected below quantitation limits
- NC Non-Chlormated
- PQL Practical Quantitation Limit

- Analyte detected in the associated Method Blank
- Holding times for preparation or analysis exceeded Н
- MCL Maximum Contaminant Level
- ND Not Detected at the Reporting Limit
- Spike recovery outside accepted recovery limits

QA/QC SUMMARY REPORT

Client:

XTO Energy

Project:

WF State 2-2

Work Order:

Date: 03-Jan-11

1101002

Analyte	Result	Units	PQL	SPK Val SF	PK ref	%Rec L	owLimit Hig	ghLimit	%RPD	RPDLimit	Qual
Method: EPA Method 418.1: T	РН										
Sample ID: MB-25070		MBLK				Batch ID:	25070	Analys	is Date:		1/3/2011
Petroleum Hydrocarbons, TR	ND	mg/Kg	20								
Sample ID: LCS-25070		LCS				Batch ID.	25070	Analys	is Date		1/3/2011
Petroleum Hydrocarbons, TR	96.62	mg/Kg	20	100	0	96 6	86 8	116			
Sample ID: LCSD-25070		LCSD				Batch ID	25070	Analys	is Date		1/3/2011
Petroleum Hydrocarbons, TR	95 36	mg/Kg	20	100	0	95.4	86 8	1 16	1.31	16.2	

Qualifiers:

E Estimated value

J Analyte detected below quantitation limits

ND Not Detected at the Reporting Limit

H Holding times for preparation or analysis exceeded

NC Non-Chlorinated

R RPD outside accepted recovery limits

Page 1

Hall Environmental Analysis Laboratory, Inc.

Sample Receipt Checklist

Client Name XTO ENERGY	oumpio ricocipi cii	Date Receive	ed:	1/3/2011
Work Order Number 1101002		Received b	y: MMG	Area
Checklist completed by Signature	. \ \ \ \ \ \ \ \ \ \ \ \ \	Sample ID	labels checked by	Initials
Matrix. Carrie	r name: <u>FedEx</u>			
Shipping container/cooler in good condition?	Yes 🗹	No 🗀	Not Present	
Custody seals intact on shipping container/cooler?	Yes 🗹	No 🗌	Not Present	Not Shipped
Custody seals intact on sample bottles?	Yes 🗌	No 🗌	N/A ☑	
Chain of custody present?	Yes 🗹	No 🗌		
Chain of custody signed when relinquished and received?	Yes 🔽	No 🗌		
Chain of custody agrees with sample labels?	Yes 🗹	No 🗌		
Samples in proper container/bottle?	Yes 🗹	No 🗌		
Sample containers intact?	Yes 🗹	No 🗌		
Sufficient sample volume for indicated test?	Yes 🗹	No 🗌		
All samples received within holding time?	Yes 🔽	No 🗌		Number of preserved
Water - VOA vials have zero headspace? No VOA v	rials submitted 🗹	Yes 🗌	No 🗌	bottles checked for pH
Water - Preservation labels on bottle and cap match?	Yes 🗌	No 🗌	N/A 🗹	
Water - pH acceptable upon receipt?	Yes 🗌	No 🖂	N/A ☑	<2 >12 unless noted
Container/Temp Blank temperature?	3.8°	<6° C Accepta		below
COMMENTS.		If given sufficier	nt time to cool	
	=====	====	=====	=======
Client contacted Date contact	ted:	Per	son contacted	
Contacted by: Regarding				
Comments:				
		-		
Corrective Action				
				

C	hain-	-of-Cu	stody Record	Turn-Around	Time:] "						_		. T -				—		
Client:	XTC		ergy	☐ Standard	Rush	24 have			H										NT.	AL RY	, .
			37	Project Name):													177	•	' E ~ I	
Mailing	Mailing Address: 382 Rd 3106			wf s	tate a-	- 2	www.hallenvironmental.com 4901 Hawkins NE - Albuquerque, NM 87109														
	Δ_	- 200 C	Nm 874/0	Project #: -			1)5-34				•	-		-410				
Phone:			87-0519				\$6.74														i Si
email o			s -mr doniel extremen	Project Mana	ger:		_	_													
QA/QC I	Package:	•	Cor C □ Level 4 (Full Validation)			·	TMB's (8021)	(Gas o	as/Die					PO4,S	PCB's						
Accredi		□ Othe	er	Sampler: J	ames Ma	Dave 1	+ TMB	+ TPH)15B (C	18.1)	04.1)	PAH)		J ₃ ,NO ₂	3 / 8082		()				or N
	(Type)			Sample Term	oerature e	2	E BE	BE)8 p	od 4	od 5	or F	etals	Ň,	ide	8					ح
Date	Time	Matrix	Sample Request ID	Container Type and #	Preservative Type	HEALING HOLOOT	BTEX + MTBE	BTEX + MTBE + TPH (Gas only)	TPH Method 8015B (Gas/Diesel)	TPH (Method 418.1)	EDB (Method 504.1)	8310 (PNA or	RCRA 8 Metals	Anions (F,CI,NO3,NO2,PO4,SO4)	8081 Pesticides / 8082	8260B (VOA)	8270 (Semi-VOA)				Air Bubbles (Y or N)
12/28/10	1100	30:1	BGT Clusure Composite	1-402	Cool	-1				X											Ţ
	1.00															·		\neg			
		<u> </u>					T											\neg	\neg		
																			\top	+	
	 						†						_					+	1	+	
	 																	_		+	\vdash
		-					†-											+	\dashv		
		<u> </u>					+				_							+	+	+-	\vdash
							\top											+	+	+	\vdash
							_											-	+		
	 						 											+	+	+	\vdash
		 					+-											+	+	+-	
Date:	Time: 13	Relinquish	1651	Received by:	the Wal	Date Time		nark:	s:	!	L		L]						!		L
Date:	Time:	Relinquish	ned by:	Received by:	hell C	Date Time		in the			tra etc	d dot-		ole -			41-				



12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est. 1970

James McDaniel XTO Energy - San Juan Division 382 Road 3100 Aztec, NM 87410

Report Summary

Tuesday January 04, 2011

Report Number: L495594
Samples Received: 12/30/10
Client Project:

Description: WF State 2-2

The analytical results in this report are based upon information supplied by you, the client, and are for your exclusive use. If you have any questions regarding this data package, please do not hesitate to call.

Entire Report Reviewed By:

Daphne Richards , ESC Representative

Laboratory Certification Numbers

A2LA - 1461-01, AIHA - 100789, AL - 40660, CA - I-2327, CT - PH-0197, FL - E87487 GA - 923, IN - C-TN-01, KY - 90010, KYUST - 0016, NC - ENV375/DW21704, ND - R-140 NJ - TN002,NJ NELAP - TN002, SC - 84004, TN - 2006, VA - 00109, WV - 233 AZ - 0612, MN - 047-999-395, NY - 11742, WI - 998093910, NV - TN000032008A, TX - T104704245, OK-9915

Accreditation is only applicable to the test methods specified on each scope of accreditation held by ESC Lab Sciences

Note The use of the preparatory EPA Method 3511 is not approved or endorsed by the CA ELAP

This report may not be reproduced, except in full, without written approval from ESC Lab Sciences Where applicable, sampling conducted by ESC is performed per guidance provided in laboratory standard operating procedures 060302, 060303, and 060304



12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859' Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

REPORT OF ANALYSIS

January 04,2011

James McDaniel XTO Energy - San Juan Division 382 Road 3100 Aztec, NM 87410

ESC Sample # L495594-01

Date Received

December 30, 2010 WF State 2-2

Description

Site ID

WF STATE 2-2

Sample ID

BGT CLOSURE COMPOSITE

Project #

Collected By Collection Date

James McDaniel 12/28/10 11 00

Parameter	Dry Result	Det Limit	Units	Method	Date	Dıl
Total Solids	80 4		Ŷ	2540G	12/31/10	1
Benzene	BDL	0 0031	mg/kg	8021/8015	12/30/10	5
Toluene	BDL	0 031	mg/kg	8021/8015	12/30/10	5
Ethylbenzene	BDL	0 0031	mq/kq	8021/8015	12/30/10	5
Total Xylene	BDL	0 0093	mg/kg	8021/8015	12/30/10	5
TPH (GC/FID) Low Fraction	BDL	0 62	mg/kg	GRO	12/30/10	5
Surrogate Recovery-%			3, 3			
a.a.a-Trifluorotoluene(FID)	97 7		% Rec	8021/8015	12/30/10	5
a,a,a-Trifluorotoluene(PID)	101		% Rec	8021/8015	12/30/10	5
TPH (GC/FID) High Fraction Surrogate recovery(%)	21	5 0	mg/kg	3546/DRO	12/30/10	1
o-Terphenyl	58 8		% Rec	3546/DRO	12/30/10	1

This report shall not be reproduced, except in full, without the written approval from ESC The reported analytical results relate only to the sample submitted Reported 01/04/11 10 38 Printed 01/04/11 10 45



12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

REPORT OF ANALYSIS

January 04,2011

James McDaniel XTO Energy - San Juan Division 382 Road 3100 Aztec, NM 87410

ESC Sample #

L495594-02

Date Received Description

December 30, 2010 WF State 2-2

Site ID

WF STATE 2-2

Sample ID

BGT CLOSURE COMPOSITE

Project #

Collected By Collection Date

James McDaniel 12/28/10 11 00

Parameter	Dry Result	Det Limit	Units	Method	Date	Dıl
Chloride	540	11	mg/kg	9056	12/31/10	1
Total Solids	87 4		8	2540G	12/31/10	1

Results listed are dry weight basis BDL - Below Detection Limit Det. Limit - Practical Quantitation Limit(PQL)

Note
This report shall not be reproduced, except in full, without the written approval from ESC
The reported analytical results relate only to the sample submitted
Reported 01/04/11 10 38 Printed 01/04/11 10 45



XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

Quality Assurance Report Level II

L495594

January 04, 2011

		Labor	atory Bla					
Analyte	Result	Unit	S	% Rec	Limit		Batch	Date Analyz
Benzene	< 0005	mg/k	α				WG515476	12/30/10 15
Ethylbenzene	< 0005	mg/k					WG515476	12/30/10 15
Toluene	< 005	mg/k					WG515476	12/30/10 15
TPH (GC/FID) Low Fraction	٠ ،< ` 1 "	mg/k			•	•		12/30/10 15
Total Xylene	< 0015	mg/k					WG515476	12/30/10 15
a,a,a-Trifluorotoluene(FID)		% Re		98 24	59-128		WG515476	12/30/10 15
a,a,a-Trifluorotoluene(PID)		% Re	С	102 0	54-144		WG515476	12/30/10 15
TPH (GC/FID) High Fraction	< 4	ppm					WG515358	12/30/10 20
o-Terphenyl		% Re	С	85 50	50-150		WG515358	12/30/10 20
Total Solids	< 1	8					WG515467	12/31/10 09
Chloride	< 10	mg/k	g				WG515496	12/31/10 11
		D	uplicate					
Analyte	Units	Result	Duplica	te RPD	Limit		Ref Samp	Batch
Total Solids	*	82 0	83 3	1 11	5		L495602-	04 WG515
Chloride	mg/kg	44 0	44 7	0 448	20		L495473-	37 WG515
Chloride	mg/kg	49 0	45 5	7 20	20		L495517-	02 WG515
		Laborator			e n		*	Datab
Analyte	Units	Known Va	<u> </u>	Result	% Rec		Limit	Batch
Benzene	mg/kg	05		0 0505	101		76-113	WG515
Ethylbenzene	mg/kg	05		0 0523	105		78-115	WG515
Toluene	mg/kg	05		0 0505	101		76-114	WG515
Total Xylene	mg/kg	15		0 153	102		81-118	WG515
a,a,a-Trifluorotoluene(PID)					102 1		54-144	WG515
TPH (GC/FID) Low Fraction	mg/kg	5 5		5 81	106		67-135	WG515
a,a,a-Trifluorotoluene(FID)					102 3		59-128	WG515
TPH (GC/FID) High Fraction	ppm	60		36 7	61 1		50-150	WG515
o-Terphenyl					69 49	e	50-150	WG515
Total Solids	ş	50		49 9	99 8		85-115	WG515
Chloride	mg/kg	200		197	98 5		85-115	WG515
	La	aboratory Con	trol Samp	ole Duplicate				
Analyte	Units F	Result Re	£	%Rec	Limit	RPD	Lin	nt Batch
Benzene	mg/kg (0 0499 0	0505	100	76-113	1 14	20	WG515
Ethylbenzene	mg/kg (0 0518 0	0523	104	78-115	1 01	20	WG515
Toluene	mg/kg (0502 0	0505	100	76-114	0 590		WG515
Total Xylene			153	101	81-118	1 01	20	WG515
a,a,a-Trifluorotoluene(PID)				102 6	54-144			WG515
TPH (GC/FID) Low Fraction	mg/kg (5 31 5	81	115	67-135	8 19	20	WG515
a,a,a-Trifluorotoluene(FID)	_			102 5	59-128			WG515

* Performance of this Analyte is outside of established criteria
For additional information, please see Attachment A 'List of Analytes with QC Qualifiers '



XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est 1970

Quality Assurance Report Level II

L495594

January 04, 2011

Analyte		Result	y Control : Ref	پېرې Rec Rec	biircaice	Limit	RPD	Limit	Batch
TPH (GC/FID) High Fraction o-Terphenyl	ppm	37 7.	, 36.7,	63 [°] 0 66 8		50-150 . 50-150	.2 71°	20 -	WG51535 WG51535
Chloride	mg/kg	196	197	98 0	·	85-115 ,	0 509	20	WG5154
			Matrıx S						
Analyte	Units	MS Res	Ref Re	s TV	% Rec	Limit		Ref Samp	Batch
Benzene	mg/kg	0 240	. 0	05	96 0	32-137	•	L495599-01	WG5154
Ethylbenzene	mq/kq	0 248	0	05	99 3	10-150		L495599-01	WG5154
Toluene	mq/kq	0 242	0	05	96 7	20-142		L495599-01	WG5154
Total Xylene	mg/kg	0 731	0 0	15 *	97 5	16-141	,	L495599-01	WG5154
a,a,a-Trifluorotoluene(PID)					102 5	54-144			WG5154
TPH (GC/FID) Low Fraction	mg/kg	26 2	0	5 5	95 2	55-109		L495599-01	WG5154
a,a,a-Trifluorotoluene(FID)		F	~ ·		, 101 9,	59-128			WG5154
TPH (GC/FID) High Fraction o-Terphenyl	, ppm	55 1	17 0	60	63 5 ~ 64 98	50-150 50-150		L495594-01	WG5153 WG5153
Chloride	mg/kg	572	51 9	500	104	80-120		L495473-34	WG5154
		5"	rıx Spike	D 1					
Analyte	Units	MSD Mac		%Rec	Limit	RPD	Limit	Ref Samp	Batch
7000 100 100 100 100 100 100 100 100 100									
Benzene [®]	mg/kg	0 234	0 240 ,	93 5	32-137	2 66, "	39	L495599-01 °	WG5154
Ethylbenzene	mg/kg	0 239	0 248	95 5	10-150	3 98	44	L495599-01	WG5154
Toluene	mg/kg	0 234	0 242	93 8	20-142	3 07	42	L495599-01	WG5154
Total Xylene	mq/kq	0 700	0 731	93 4	16-141	4 38	46	L495599-01 -	_WG5154
a,a,a-Trifluorotoluene(PID)			•	101 6	54-144				WG5154
TPH (GC/FID) Low Fraction	mg/kg	26 3		95 6	55-109		20	L495599-01	WG5154
a,a,a-Trifluorotoluene(FID)		,		101 5	59-128		***	~ * * * * * * * * * * * * * * * * * * *	WG5154
TPH (GC/FID) High Fraction	ppm	67 3	55 1	83 8	50-150	20 0	20	L495594-01	WG5153
o-Terphenyl	-,-			72 54	50-150	2 7 m	2	ж	WG5153
Chloride	mq/kq	546	572	98 8	80-120	4 65	20	L495473-34	WG5154

Batch number /Run number / Sample number cross reference

WG515476 R1521789 L495594-01 WG515358 R1521949 L495594-01 WG515467 R1522429 L495594-01 02 WG515496 R1523869 L495594-02

 ^{*} Calculations are performed prior to rounding of reported values
 * Performance of this Analyte is outside of established criteria
 For additional information, please see Attachment A 'List of Analytes with QC Qualifiers '



XTO Energy - San Juan Division James McDaniel 382 Road 3100

Aztec, NM 87410

Quality Assurance Report Level II

L495594

January 04, 2011

12065 Lebanon Rd Mt Juliet, TN 37122 (615) 758-5858 1-800-767-5859 Fax (615) 758-5859

Tax I D 62-0814289

Est. 1970

The data package includes a summary of the analytic results of the quality control samples required by the SW-846 or CWA methods. The quality control samples include a method blank, a laboratory control sample, and the matrix spike/matrix spike duplicate analysis. If a target parameter is outside the method limits, every sample that is effected is flagged with the appropriate qualifier in Appendix B of the analytic report

Method Blank - an aliquot of reagent water carried through the entire analytic process. The method blank results indicate if any possible contamination exposure during the sample handling, digestion or extraction process, and analysis. Concentrations of target analytes above the reporting limit in the method blank are qualified with the "B" qualifier.

Laboratory Control Sample - is a sample of known concentration that is carried through the digestion/extraction and analysis process. The percent recovery, expressed as a percentage of the theoretical concentration, has statistical control limits indicating that the analytic process is "in control". If a target analyte is outside the control limits for the laboratory control sample or any other control sample, the parameter is flagged with a "J4" qualifier for all effected samples

Matrix Spike and Matrix Spike Duplicate - is two aliquots of an environmental sample that is spiked with known concentrations of target analytes. The percent recovery of the target analytes also has statistical control limits. If any recoveries that are outside the method control limits, the sample that was selected for matrix spike/matrix spike duplicate analysis is flagged with either a "J5" or a "J6". The relative percent difference (%RPD) between the matrix spike and the matrix spike duplicate recoveries is all calculated. If the RPD is above the method limit, the effected samples are flagged with a "J3" qualifier

Company Name/Address			Alternate B	illing	.			Analys	is/Co	ntainer/Pre	servative			Chain of Custody Pageof	٦.
XTO Energy, Inc.			XTORNM	1031810S			(A) 1/2 (100 A.W.				E043	Page01	
382 County Road 3100							1		2.			Prep	pared by		
Aztec, NM 87410							0	0	. 3		į		ENVIRO	NMENTAL	
							U	7	0		İ	,	Science co	orp	
			Report to Jan	nes McDaniel					\supset				12065 Leb	anon Road	
			E-mail to Jan	nes_McDaniel@x	toenergy com		70/	405	N				Mt Juliet T	N 37122	
Project Description WF Stat	e 2-	-2		Farhage	State Collected	4	1-1	1	200				Phone (61:	5)758-5858	
	lient Project No.			Lab Project #				\downarrow					Phone (80	00) 767-5859	
FAX				_			(v)	7					FAX (6	315)758-5859	
Collected by James McDaniel S	ite/Facility ID#	· 2	-a	PO#			8015	80,	3			Ço	Code	(lab use only)	
Collected by/signed ire	Rush? (Lab	MUST be	Notified)	Date Result		110	,RO(<i>λ</i>	110			8 ₃₄ .	ORNM mplate/Prelogin	all the state of t	2 (1) (1) (2) (2) (2) (2) (2) (2) (2) (2) (2) (2
		O Day ee Day		Email?N FAX?N		of	2	111	0		***		ா ipned∜Viâ: Féd Éx	and the second of the second	
Packed on Ice NYX			<u> </u>		<u> </u>	Cotrs	CRO	1	2	14 % 45			<u></u>	T	<u> </u>
		Matrix	Depth	Date	Time 1/CC	1	1	8			79.5 · - 5	Rer	marks/contaminan	1 10 Crail	ol/
BGT Closure Composite	conf	<u>ss</u>		12/28/10	11,50	+-	X				- ;			475579 -2	-4
				-	1	-	-		<u>.</u>	140					\dashv
						╁			-	- 4					-
		-					ļ		6×	8	- Jan			4 *** ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;	
						<u> </u>	<u> </u>		· .						(6. \ ()
		_				 				**************************************					13,3
							<u> </u>		ه م ک						<u>;</u> `
						<u> </u>	;		√ ®						776
							,							-	
Matrix: SS-Soil/Solid GW-Groundwate	r WW-Waste	ewater Di	W-Drinking \	Nater OT-O	ther						Hq		Temp		
	4341 98			valor or o							Flow		Other		
Relinquisher by Signature		me 726	Received by (Signature)	m		Samp	les retur	ned via	FedEx_X_U	PSOther	Con	dition ,	(lab use only)	K
Rejuquisher by (Signature	7-7/10 C		Received by	(Signature)	S. No.		Temp		,g°i	Bottles	Received			Coxel	*
Relinquisher by (Signature	Date Ti	me.	Received for	lab by. (Signatur	e)		Date:		Sma "	Time"	30	pH (Checked	NCF-	

THE REPORT OF THE PARTY OF THE

京都をあるないまいまではない



James McDaniel:/FAR/CTOC 12/28/2010 08:58 AM To brandon.poweli@state.nm.us

CC

bcc

Subject W F State 2 #2 BGT Closure

Brandon,

Please accept this email as the required notification for BGT Closure Activities at the W F State 2 #2 well site (api # 30-045-31292) located in Unit C, Section 2, Township 30N, Range 14W, San Juan County, New Mexico. This tank-will no longer be used to to plugging and abandoning of this location. Thank-you for your time in regards to this project:





December 28, 2010

Scott Dawson, New Mexico State Land Office Oil, Gas and Minerals Division PO Box 1148 Santa Fe, New Mexico, 87504

Re:

W F State 2 #2-

Unit C, Section 2, Township 30N, Range 14W, San Juan County, New Mexico

Dear Mr. Dawson,

This submittal is pursuant to Rule 19.15.17.13 requiring operators to notify surface owners of the closure of a below grade tank pit. XTO Energy, Inc. (XTO) is hereby providing written documentation of our proposal to close the below grade tank pit associated with the above mentioned well site by waste excavation and removal.

Should you have questions or require additional information, please feel free to contact me at your convenience at (505) 333-3100. Thank you for your time in regards to this matter.

Respectfully Submitted,

James McDaniel

EH&S Specialist XTO Energy, Inc.

San Juan Division

U.S. Postal Service IM RECEIPT

(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.como.

Postage

Return Receipt Fee (Endorsement Required)

Restricted Delivery Fee (Endorsement Required)

Total Postagy

Scott Dawson

NM State Land Office

Street, Apt No or PO Box No.

PO Box No.

PO Box 1148

Santa Fe, NM 87504

PS Form 3800

XTO Energy, Inc. W F State 2 #2 Section 2, Township 30N, Range 14W Closure Date 1/3/2011




Photo 1: W F State 2 #2 after Reclamation (View 1)




Photo 2: W F State 2 #2 after Reclamation (View 2)

<u>WellName</u>	<u>APIWellNumber</u>	<u>Sec</u>	Twn	Rge	InspectorName	InspectionDate	InspectionTime	<u>PitLocation</u>	PitType '
WF STATE 02 02 (PA)	3004531292	2	30N	14W	bp	8/20/2008	4:00		
WF STATE 02 02 (PA)	3004531292	2	30N	14W	bp	9/6/2008	1:11		
WF STATE 02 02 (PA)	3004531292	2	30N	14W	bp	10/7/2008	11:21		
WF STATE 02 02 (PA)	3004531292	2	30N	14W	bp	12/15/2008	11:00		
WF STATE 02 02 (PA)	3004531292	2	30N	14W	bp	1/13/2009	8:44		
WF STATE 02 02 (PA)	3004531292	2	30N	14W	bp	2/18/2009	8:00		
WF STATE 02 02 (PA)	3004531292	2	30N	14W	Dustin Jensen	5/22/2009	1:00	Well Water Pit	Below Ground
WF STATE 02 02 (PA)	3004531292	2	30N	14W	Dustin Jensen	6/14/2009	11:35	Well Water Pit	Below Ground
WF STATE 02 02 (PA)	3004531292	2	30N	14W	Dustin Jensen	7/4/2009	2:30	Well Water Pit	Below Ground
WF STATE 02 02 (PA)	3004531292	2	30N	14W	Dustin Jensen	8/23/2009	12:55	Well Water Pit	Below Ground
WF STATE 02 02 (PA)	3004531292	2	30N	14W	Dustin Jensen	9/15/2010	2:10	Well Water Pit	Below Ground
WF STATE 02 02 (PA)	3004531292	2	30N	14W	Dustin Jensen	11/7/2010	10:00	Well Water Pit	Below Ground
WF STATE 02 02 (PA)	3004531292	2	30N	14W	Dustin Jensen	12/13/2010	10:15	Well Water Pit	Below Ground

•

,

.

<u>VisibleLinerTears</u>	<u>VisibleTankLeakOverflow</u>	CollectionOfSurfaceRun	Oil Layer	Visible Leak	<u>FreeboardEstFT</u>	<u>Notes</u>
No	No	No	No	No	5	new no liner
No	No	No	No	No	5	board-g no liner new
No	No	No	No	No	5	board-g no liner new
No	No	No	No	No	5	board-g no liner new
No	No	No	No	No	5	board-g no liner new
No	No	No	No	No	5	board-g no liner new
No	No	No	No	No	5	pit has 11" of fluid Dj
No	No	No	No	No	5	pit has 11" of fluid Dj
No	No	No	No	No	5	pit empty Dj
No	No	No	No	No	5	pit empty Dj
No	No	No	No	No	5	pit empty Dj
No	No	No	No	No	5	pit empty Dj
No	No	No	No	No	5	pit empty Dj

.

· ·