NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-3-2010 **Operator** Energen Resources **API #** 3003926307

Property Name CARRACAS UNIT 26 A 4 **Location:** Unit D Section 26 Township 32 Range 5

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 58 Intermediate ____ Casing 62 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	0	62			
10 minutes	0	62			
15 minutes	0	61			
20 minutes	0	63			
25 minutes	0	62			
30 minutes	0	62			
5 minute SI	0	62			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow	NO	
Surges	NO	
Down to Nothing	NA	
No Flow	NO	
Gas	NO	
Gas and Water	NO	
Water	NO	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear NA Fresh NA Salty NA Sulfur NA Black NA

5 Minute Shut-in Bradenhead 0 Intermediat ____

REMARKS: Bradenhead had 0 on it through the hole test

By ____ **Witness** ____

(Position)

NMOCD Test Area: C 75