



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/07/2011 Operator Burlington API #30-0 45-34807

Property Name Randlemon Well No. 1B Location: Unit ___ Section 26 Township 31 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 229 Intermediate 5 Casing 227 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	5	230	0	235
10 min	0	4	232	0	236
15 min	0	4	233	0	237
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Slight leak around threading on adapter for gauge > 2" to 1" fitting for Intermediate
Intermediate soft blow to nothing in 1min.

By Nick Horton
MSO
(Position)

Witness Jonathan D. Kelly

E-mail address _____

