

Oct 6 , 2011

Energen Resources  
2010 Afton Place  
Farmington , NM 87401



This letter is to certify that D & D Services LLC did run deviation surveys at the below listed depths on your Richardson # 103 in San Juan County

Richardson # 103      Sec 1 T 27N R 13 W

165'                      ½

665'                      ¾

1165'                    1 ¼

1525'                    1 ¼

To the best of my knowledge, I swear this information to be true.

Sincerely,

A handwritten signature in black ink, appearing to read "Glen Davis".

Glen Davis  
Drilling Manager

