10

k /4

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NOV 07 2011.

DIST.3

Sundry Notices and Reports of	n Wells		Farmington Field Office Bureau of Land Managemen.
		5.	Lease Number
1. Type of Well GAS		6.	SF-079403 If Indian, All. or Tribe Name
2. Name of Operator BURLINGTON		, 7.	Unit Agreement Name San Juan 27-5 Unit
RESOURCES OIL & GA	AS COMPANY LP	8.	Well Name & Number
3. Address & Phone No. of Operator			San Juan 27-5 Unit 117N
PO Box 4289, Farmington, NM 87499 (505) 326-9700			API Well No.
4. Location of Well, Footage, Sec., T,	P M		30-039-30960
Unit D (NWNW), 1007' FNL & 274' FWL, Section 22, T27N, R5W, NMPM			Field and Pool Blanco MV/Basin DK
	. 1 (12), Section 22, 1271, 120	11.	
13. Describe Proposed or Completed (Attached is a drawing for the placement of	-	nd cable for the subject wel	
		FARMINGTON FIELD	Figers
14. I hereby certify that the foregoing	is true and correct.		(100 100 100 10 10 10 10 10 10 10 10 10 10 10 10 10 10
Signed Into own!	Denise Journey	Title: Staff Regulatory	Technician Date -4-
(This space for Federal or State Office us APPROVED BY	se) Title		Date
CONDITION OF APPROVAL, if any: Title 18 U S C Section 1001, makes it a crime for any person know the United States any false, fictitious or fraudulent statements or rep		, of	RCUD NOV 16'11
	NMOCD		OIL CONS. DIV.



San Juan 27-5 117N

Section 22, T27N, R5W, N.M.P.M., Rio Arriba County, NM

	N	COPC Pipeline Negative Cable Positive Cable WFS Pipeline Separator Meter Run		
117N		☐ Rectifier		
	wellhead af install cable below: #117N Cab Negative: 1 Positive: 10	Drill ground bed approximately 130' northwest of #100s wellhead at staked location. Install single-well solar unit and install cables to #117N wellhead and ground bed at lengths below: #117N Cables: Negative: 130' Positive: 10' Total Ditch: 140'		

By: Scott Smith Date: 12/1/2010