



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-21-11 Operator Craig Watson API #30-0 45-07663

Property Name Callow Fal Well No. 1 Location: Unit I Section 33 Township 29 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 215 Intermediate Casing 215 Bradenhead 118

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	<u>TS1A</u>		<u>215</u>		
10 min	<u>TS1A</u>		<u>215</u>		
15 min	<u>TS1A</u>		<u>215</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>X</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

RCVD OCT 27 '11

OIL CONS. DIV.

DIST. 3

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 12 INTERMEDIATE

REMARKS:

Dile well, Packer down hole

By Cullan Keller

Witness

Switcher

(Position)

E-mail address Cullan@walsheng.net