



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-21-2011 Operator Kukul Operaty API #30-0 45-28492
Property Name Hardie Well No 25B#81 Location: Unit B Section 25 Township 22N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 1081 Intermediate NA Casing 111 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead		Csg	Int	Csg
	BH	Int			
5 min	<u>0</u>	<u>NA</u>	<u>111</u>		
10 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
15 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
20 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
25 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>Nothing</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

This is a flowing well, producing Tubing.

By L. J. Ruiz
Lease Operator
(Position)

Witness _____

E-mail address _____

RCVD NOV 14 '11

OIL CONS. DIV.

DIST. 3