District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office. For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office

	00
	~ 1 / 7
	$\boldsymbol{\wedge}$
	, v-
_	
<i>,</i> –	v
	_

Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances Operator: WILLIAMS PRODUCTION COMPANY, LLC OGRID #· 120782 Aztec, NM 87410 Address PO Box 640 Facility or well name: _____ ROSA UNIT #100B API Number 3003929547 OCD Permit Number: ____ Section 210 Township ____31N ____ Range 06W County RIO ARRIBA Latitude: 36 880000000000000 Longitude 107 46528000000001 NAD 1983 Surface Owner FEDERAL Pit: Subsection F or G of 19.15 17 11 NMAC RCVD DEC 9'11 Temporary.

Drilling Workover Permanent Emergency Cavitation P&A OIL CONS. DIV. ☐ Lined ☐ Unlined Liner type Thickness _____ mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other ____ DIST. 3 ☐ String-Reinforced Closed-loop System: Subsection H of 19 15 17 11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) ☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other ☐ Lined ☐ Unlined Liner type Thickness mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other Liner Seams: Welded Factory Other Below-grade tank: Subsection I of 19 15 17.11 NMAC Volume <u>120</u> bbl Type of fluid PRODUCED WATER Tank Construction material ______ DBL WALL STEEL Secondary containment with leak detection Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off ☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other _

Liner type: Thickness _____ mil HDPE PVC Other ____

Submittal of an exception request is required
Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval

Fencing: Subsection D of 19.15 17 11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)	
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, scho institution or church)	ol, hospıtal,
Four foot height, four strands of barbed wire evenly spaced between one and four feet	
Alternate. Please specify	
7.	
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	
 ✓ Screen ☐ Netting ☐ Other ☐ ☐ Monthly inspections (If netting or screening is not physically feasible) 	
Monthly hispections (if netting of selecting is not physically leastore)	
Signs: Subsection C of 19.15.17 11 NMAC	
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
⊠ Signed in compliance with 19.15.3 103 NMAC	
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required Please refer to 19 15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s). Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bure consideration of approval Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval	au office for
Siting Criteria (regarding permitting): 19 15 17 10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accommendation of accommendation of accommendation of accommendation of the application of the applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to a above-grade tanks associated with a closed-loop system.	propriate district of approval.
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank - NM Office of the State Engineer - iWATERS database search; USGS, Data obtained from nearby wells	☐ Yes ☐ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) - Topographic map, Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site, Aerial photo; Satellite image	Yes No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application (Applies to permanent pits) - Visual inspection (certification) of the proposed site, Aerial photo; Satellite image	Yes No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application - NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality, Written approval obtained from the municipality	Yes No
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map, Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area - Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources, USGS, NM Geological Society, Topographic map	Yes No
Within a 100-year floodplain - FEMA map	☐ Yes ☐ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17 9 NMAC
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19 15 17 9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15.17.9 NMAC Sting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC Design Plan - based upon the appropriate requirements of 19 15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC
and 19 15 17 13 NMAC Previously Approved Design (attach copy of design) API Number or Permit Number
12
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19 15 17 10 NMAC Design Plan - based upon the appropriate requirements of 19.15 17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan API Number:
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19 15 17 9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19 15.17 9 NMAC Sitting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19 15 17 11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19 15.17 11 NMAC Leak Detection Design - based upon the appropriate requirements of 19 15 17 11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19 15 17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15 17 13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System
Proposed Closure Method Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. □ Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC □ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC □ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) □ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC □ Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC □ Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Disposal Facility Permit Number	
	vice and operations?
requirements of Subsection H of 19 15 17 13 NMAC of 19 15 17 13 NMAC	C
administrative approval from the appropriate disti Bureau office for consideration of approval. Justi	rict office or may be
obtained from nearby wells	☐ Yes ☑ No ☐ NA
obtained from nearby wells	☐ Yes ☑ No ☐ NA
obtained from nearby wells	☐ Yes ☐ No ☑ NA
ficant watercourse or lakebed, sınkhole, or playa	☐ Yes ☒ No
	☐ Yes ⊠ No
ring, in existence at the time of initial application	☐ Yes ⊠ No
·	☐ Yes ☒ No
inspection (certification) of the proposed site	☐ Yes ☑ No
and Mineral Division	☐ Yes ☒ No
& Mineral Resources, USGS, NM Geological	☐ Yes ☑ No
	☐ Yes ⊠ No
prements of 19.15 17.10 NMAC Subsection F of 19.15.17 13 NMAC propriate requirements of 19.15 17 11 NMAC d) - based upon the appropriate requirements of 19 17 13 NMAC prements of Subsection F of 19.15.17.13 NMAC subsection F of 19.15 17 13 NMAC dill cuttings or in case on-site closure standards cannot of 19 15.17.13 NMAC of 19 15 17 13 NMAC	15 17 11 NMAC
	Control of the proposed site o

19	
Operator Application Certification:	two comments and consulate to the body Co. 1. 1.1. 1.1. C.
I hereby certify that the information submitted with this application is	true, accurate and complete to the best of my knowledge and belief
Name (Print)	Tıtle:
Signature	Date
e-mail address:	Telephone
OCD Approval: Permit Application (including dosure plan) OCD Representative Signature: Title:	Closure Plan (only) OCD Conditions (see attachment) Approval Date: 17/19/2011 OCD Permit Number:
Closure Report (required within 60 days of closure completion): Instructions: Operators are required to obtain an approved closure p The closure report is required to be submitted to the division within 6 section of the form until an approved closure plan has been obtained	plan prior to implementing any closure activities and submitting the closure report. 60 days of the completion of the closure activities. Please do not complete this
22	
Closure Method:	☐ Alternative Closure Method ☐ Waste Removal (Closed-loop systems only)
Instructions: Please indentify the facility or facilities for where the la	op Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: iquids, drilling fluids and drill cuttings were disposed. Use attachment if more than
two facilities were utilized.	'D IE I D AN I
	Disposal Facility Permit Number
Disposal Facility Name	
Yes (If yes, please demonstrate compliance to the items below)	rmed on or in areas that <i>will not</i> be used for future service and operations? No
Required for impacted areas which will not be used for future service of Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	and operations
	following items must be attached to the closure report. Please indicate, by a check
mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-sit Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude	te closure)Longitude NAD
25	
25	
Operator Closure Certification:	nis closure report is true, accurate and complete to the best of my knowledge and are requirements and conditions specified in the approved closure plan
Operator Closure Certification: I hereby certify that the information and attachments submitted with the belief—I also certify that the closure complies with all applicable closure.	
Operator Closure Certification: I hereby certify that the information and attachments submitted with the belief—I also certify that the closure complies with all applicable closure.	are requirements and conditions specified in the approved closure plan

Williams Production Co., LLC San Juan Basin: New Mexico Assets

Below-Grade Tank Removal Closure Report

Well: (Rosa Unit# 100B)
API No: 30-03929547

Location: O-S21-T31N-R06W, NMPM

In accordance with Rule 19.15.17.13 NMAC, the following report describes the general closure of the referenced below-grade tanks (BGT) on Williams Production Co, LLC (WPX) location in the San Juan Basin of New Mexico. The closure follows this WPX's standard closure procedure for all BGTs regulated under Rule 19.15.17 NMAC and operated by WPX. For those closures which do not conform to the standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

Pursuant to 19.15.17.13 (A) NMAC, WPX will initiate closure of any BGT should any one of these conditions occur:

- The Division requires closure because of imminent danger to fresh water, public health or the environment.
- The integrity of the BGT fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19.15.17.12 (A) (5) NMAC.
- WPX chooses to take the BGT out-of-service due to operational needs. Closure
 under these conditions will be initiated within 60 days of cessation of the BGT's
 operation.
- BGTs installed prior to June 16, 2008 that do not meet the requirements under 19.15.17.11.I(6) NMAC and WPX chooses not to retrofit or upgrade. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

Prior to initiating any BGT Closure except in the case of an emergency, WPX will review County Tax Records for the current landowner of record. The landowner of record will be notified of the intent to closure the BGT by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the landowner of record will be notified as soon as practical.

<u>Williams notified the SMA of its intent to clean close the BGT via Certified Mail on March 10, 2009 see attached. No return receipt required per BLM:FFO/NMOCD MOU dated 5/4/09.</u>

- 2. Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)

<u>Aztec District office was notified of Williams E&P intent to close on (10/11/2011). Email</u> attached.

3. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank, ...). The well will be temporarily shut-in until the rerouting is completed.

<u>Williams closed the BGT used by the Rosa Unit#100B separator and piped all liquids to the Produced Water Storage Tank.</u>

4. All produced water will be removed from the BGT following discharge-pipe rerouting. Produced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BGT site: Rosa Unit SWD #1

(Order: SWD-916, API: 30-039-27055), Rosa Unit #94 (Order: SWD-3RP-1003-0, API: 30-039-23035), Jillson Fed. SWD #001 (Order: R10168/R10168A, API: 30-039-25465), Middle Mesa SWD #001 (Order: SWD-350-0, API: 30-045-27004) and/or Basin Disposal (Permit: NM-01-0005).

<u>Produced water in the BGT prior to closures was removed by vacuum truck and hauled</u> to the Rosa Unit disposal wells listed.

5. Solids and sludges will be shoveled and /or vacuumed out for disposal at Envirotech (Permit Number NM-01-0011).

No solids or sludge required removal prior to excavation and removal of the tank.

6. Williams will obtain prior approval from NMOCD to dispose, recycle, reuse, or reclaim the BGT and provide documentation of the disposition of the BGT in the closure report. Steel materials will be recycled or reused as approved by the Division. Fiberglass tanks will be empty, cut up or shredded, and EPA cleaned for disposal as solid waste. Liners materials will be cleaned without soils or contaminated material for disposal as solid waste. Fiberglass tanks and liner materials will meet the conditions of paragraph 1 subsection D or 19.15.9.712 NMAC. Disposal will be at a licensed disposal facility, presently San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

The fiberglass tank and plastic liner was disposed of at the San Juan Regional Landfill.

- 7. Any equipment associated with the BGT that is no longer required for some other purpose, following the closure will be removed from the location.

 The fiberglass tank and plastic liner were removed offsite. All other piping and equipment remains in use. See attached photo.
- 8. Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and tested per 19.15.17.13(E)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is wet, discolored or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Form C-141.

Table	1:	Clo	sure	Criteria	for	BGTs

Components	Testing Methods	Closure Limits (mg/Kg)	Sample Results (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2	ND
BTEX	EPA SW-846 Method 8021B or 8260B	50	ND
TPH	EPA SW-846 Method 418.1(1)	100	60
Chlorides	EPA SW-846 Method 300.1(1)	250(2)	30

⁽¹⁾ Method modified for solid waste.

9. If the Division and/or Williams determine there is a release, Williams will comply with 19.15.3.116 NMAC and 19.15.1.19 NMAC.

No release detected.

10. Upon completion of the tank removal, and any necessary soil remediation, the excavation will be backfilled with non-waste earthen material compacted to native and covered with a minimum of one foot of top soil or background thickness. The surface will be recontoured to match the native grade.

<u>Pit area backfilled with clean earthen material following sample results. No contaminated soil taken off site. Backfill compacted to avoid settling and pit area remains in use for production operations.</u>

11. For those portions of the former pit area no longer required for production activities, WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of

 $^{^{(2)}}$ If background concentration of Chlorides greater than 250 mg/Kg, then higher concentration will be used for closure.

the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) APD are Division-approved methods unless notified by the Division of their unacceptability. If a landowner agreement requires reseeding or other surface restoration that does not meet the revegetation requirements of 19.15.17.13., I then WPX will submit the proposed alternative with written documentation that the landowner agrees to the alternative, for Division approval.

Pit area along with unused portions of well pad interim reclaimed and following P&A entire location to be reclaimed and recontoured in accordance with Surface Management Agency requirements in APD-COAs and per BLM:FFO/NMOCD MOU dated 5/4/09.

12. For those portions of the former pit area required for production activities, reseeding will be done at well abandonment, and following the procedure noted above.

See above notes

Closure Report:

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the BGT closure on a Closure Report using Division Form C-144. The Report will include the following:

- Proof of Closure Notice (surface owner & NMOCD)
- Backfilling & Cover Installation
- Site Diagram with coordinates
- Available Inspection reports

- Confirmation Sampling Analytical Results
- Disposal Facility Name(s) and Permit Number(s)
- Re-vegetation Application Rate & Seeding techniques
- Photo Documentation of Reclamation



Explanation & Fraduction F(18c> 640 Azica NM 61137 505/624 4719 505/634 4214 fox

March 10, 2009

Mr Mark Kelly Bureau of Land Management Farmington Field Office 1235 La Plata Hwy Farmington, NM 87401

Sent via Certified Mail

RE Notification of Production Pit Closure

Rule 19 15 17 13 NMAC

Production Pits associated Natural Gas Development

Operated by Williams Production Co. LLC

Pursuant to Rule 19 15 17 13 NMAC this correspondence is to notify the Bureau of Land Management. Farmington Field Office of Williams Production LLC's (Williams) intent to clean close all production pits on the attached list of wells operated with the District in San Juan County and Rio Arriba County. New Mexico. Closure will follow the plan included with this correspondence.

Thank you for your consideration. If there are any questions or additional information is requested, please contact me. at (505) 634-4209.

Respectfully submitted.

Holly C Perkins EH&S Specialist

Encl: Williams Production Pit Inventory List (Federal wells)

San Juan Basin - New Mexico Assets Below-Grade Tank Closure Plan

cc Environmental Fire

Williams Production Co., LLC San Juan Basin: New Mexico Assets

Below Grade Tank Kemoval Closure Flon

to accordance with Kule 19.14.17.13.NMAC. The following plan describes the general closure requirements of below grade tanks (BC-1) on Williams Fraduction Co. 110 (WFX) locations in the San Juan Basin of New Mexico. This is WEX estandard closure procedure for all BC-1s regulated under kule 19.15.17.NMAC and operated by WEX. For those closures which do not conform to this standard closure plan a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

Forsion to 1915 1713 (A) NMAC WEX will initiate closure of any BG1 should any one of these conditions occur.

- The Division requires closure because of imminent danger to tresh water public health or the
 environment.
- The integrity of the BGT fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19-15-17-12 (A)(5) NMAC.
- WEX chooses to take the BGT out of service due to operational needs. Closure under these conditions will be closed within 60 days of cessation of the BGT's operation.
- BC-1s installed prior to time 16, 2008 that do not meet the requirements under 1915 17 11 1(6).
 NMAC and WEX, hooses not to retrofit or approace. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

- First to initiating any BGTC losere except in the case of an emergency. WEX will review County lax Records for the current surface owner of record. The surface owner of record will be notified of the intent to close the PGT by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the surface owner of record will be notified as soon as practical.
- Abdice of Closure will be given to the Azte objinct office Letween 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following
 - a Operators Name (WEX)
 - b. Well Name and All Number
 - c tocotion (USTR)
- All piping will be rejouted to an alternative produced water storage /disposal location (e.g. surface tanks temporary fractank...). The well will be temporarily shut in until the rejouting is completed.
- All produced water will be removed from the BCT following discharge pipe rerouting Froduced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BGT site. Rosa Unit SWD #1 (Order SWD 916. API 30.039-27055). Rosa Unit #94 (Order SWD 3RP 1003.0, API 30.039-23035). Jillson Fed. SWD #001 (Order R10168/R10168A. AFI 30.039-25465). Middle Mesa SWD #001 (Order SWD 350.0. AFI 30.045-27004). and/or Basin Disposal (Pemit. NM.01-0005).

solids and sludges will be shoveled and roll validation to it for disposal at Envirotech (Fermit 12 in per 14M ()). ((c))

Who will of the provide on the provide of the provide documentation of the appointment of the $f(\cdot)$ in the closure report. Steem that has will be recycled one used as approximate the first properties. The rights tanks will be empty structure of the deed and $f(\cdot)$ decreased for apposition waster than materials with

be cleaned without sols or contaminated moterial for disposal as solid waste. The ralps tanks and line i materials will meet the conditions of paragraph 1 subsection D of 19.15.9.712 NMAC. Disposal will be at a licensed disposal facility, presently San Juan Regional randfill operated by Waste Management under NMED Femili SWM 052426.

- Any equipment associated with the RGI that is no longer required for some other purpose following the closure will be removed from the location.
- taken of the excavation and tested per 19.15.17.13(E)(4) NMAC as identified in Table 1. Crab samples will be collected from any area that is wet discolared or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Fami C. 141.

Table 1. Closure Criteria for BG1s

		Table 1: Closele Chiche to Dela		
	Components	Testing Methods	Closure Limits (mg/Kg)	-
1	Benzene	FF'A SW 846 Method 8021B or 8260B	() 2	
ł	BILX	FI'A SW 846 Method 8021B or 8260B	50	·
:	TFH	EFA SW 846 Method 418 1-1	100	1
į	Chlorides	EPA SW 846 Method 300 11	25()'-)	1

the the dimedified for solid waste

- 4 If the Division and/or WEX determine there is a release. WEX will comply with 19.15.3-116. UMAC and 19.15.1.19 NMAC.
- Open completion of the tank removal, the excavation will be backfilled with non-woste earthern material compacted and covered with a minimum of one, foot of top soil or trackground thickness whichever is greater and to existing grode. The surface will be reconforced to match the native arade and prevent ponding.
- For those portions of the former pit area no longer required for production activities. Whi will seed the disturbed areas the first growing scason after the pit is covered. Seeding will be accomplished via diffling on the contour whenever practical or by other Division approved methods. Vegetative cover will equal 70% of the notive perennial vegetative cover fun impacted) consisting of at least three native plant species, including at least one gross but not including no sious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or plantling will be continued until successful vegetative growth occurs. Here, if a surface owner agreement requires reseeding or other surface tests into in that ac not meet refrequency requirements of 19.15.17.13.11MAC then WEX will submit the proposed alternative with written documentation that the surface owner agrees to the often other for Division approval.
- For those portions of the former pit area required for production activities reseeding will be done at well abandonment, and following the procedure noted above.

Closure Report

All closure activities will include proper accumentation and will be submitted to OCD within 60 days of the PC-1 closure on a Closure February Division form C-144. The Report will include the following.

- Fig. (Control of the Control of the Co
- · Proceedings are the
- Site (mognor) of the second
- AVOING HERE AND ACT

- Commenter Som progressors in Fes
- · Lasposon for the recovery or off the farmers.
- · Frede December 1 mer of the common of

If the content of a content of a thomas greater than 200 max) and the orbigher a new mattern with ence of a content of a c

WELLS W/FEDERAL SURF MGT	API	FMT	SEC	TWN	RNG	PIT TYF	E CONSTRUCTION MATERIAL
	·		. 220				
COX CANYON UNIT #001	3004511397	PLANCO MV	16N	32N	111/	BG1	DBL WALL STEEL TIBERGLASS TANK w/BANDED 20 mil
COX CANYON UNIT #001A	3004522086	BLANCO MV	160	3211	11VV	BG1	HIDPE SECONDARY LINER
COX CANTON UNIT #001B	3004530791	PLANCO MV	161	32N	11W	BG1	FIBERGLASS TANK WBANDED 20 mil FIDPE SECONDARY LINER
COX CANYON UNIT #001C	3004532023	BLANCO MV	16 F	3211	11W	BG1	DBI WALL STEFF
COX CANYON UNIT #003	3004511495	BLANCO MV	91	32N	1 1 V√	861	FIRERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
COX CANYON UNIT #003A	3004522088	BLANCO MV	911	32N	1 1 VV	BG1	DBI WALL STEEL
COX CANYON UNIT #003B	3004530871	BLANCO MV	9,1	32N	1 1 W	BGT	DBI WALL STEEL
	3004330011	DI ANOCANIV			1 1 7 7	501	
COX CANYON UNIT #004	3004511368	BLANCO MV	21A	32N	11W	BG1	DBI WALL STEFI
COX CANYON UNIT #004A	3004522093	BLANCO MV	21F	32N	11W	BG1	DBI WALL STEEL
COX CANYON UNIT #004B	3004532186	BLANCO MV	218	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #005	3004511326	BLANCO MV	21K	32N	1 1 VV	BGI	DBI WALL STEEL
COX CANYON UNIT #005A	3004522094	BLANCO MV	210	32N	1 1 V V	BGT	DBL WALL STEEL
COX CANYON UNIT #005R	3004532142	BASIN DK / BLANCO MV	21N	3211	11W	BGT	DBI WALL STEEL
COY CANYON UNIT #005C	3004533493	BLANCO MV	21f	32N	1 1 VV	BGT	DBI WALL STEEL
COX CANYON UNIT #006	3004511463	BLANCO MV	16A	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #006A	3004522095	BLANCO MV	161	3211	1 1 W	BG1	DBI WALL STEEL
COX CANYON UNIT #006B	3004£32693	BLANCO MV	16B	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #006C	3004532733	BLANCO MV	16()	32N	1 1 VV	HG1	DBL WALL STEEL
COX CANYON UNIT #007	3004511455	BLANCO MV	176	32N	11W	FGF.	DBI WALL STEEL
COX CANYON UNIT #007A	3004522091	BLANCO MV	170	32N	11W	BG1	DBL WALL STEEL
COX CANYON UNIT #007C	3004533018	BASIN DK	17K	32N	11 V V	BG1	UBI WALL STEEL
COX CANYON UNIT #008	3004511492	BLANCO MV	81	32N	1 1 Vv	BG1	FIBERGLASS TANK W/BANDED 20 mill HDPE SECONDARY LINER
COX CANYON UNIT #008A							DBI WALL STEEL
	3004522096	BLANCO MV	1711	32N	11W	BG1	FIBERGLASS TANK w/BANDED 20 mil
OX CANYON UNIT #008B	3004532080	BLANCO MV	8P	32N	11W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20 mil
COX CANYON UNIT #008C	3004531187	BLANCO MV	17F'	3211	11W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDE() 20 mil
COM CANYON UNIT #009B	3004522092	BLANCO MV	20D	32N	11W	BGT	HDPE SECONDARY LINER
COM CANYON UNIT #009B	3004533926	BASIN DK / BLANCO MV	20B	32N	11W	BGT	DBL WALL STEEL
OX CANYON UNIT #009C	3003933851	BASIN DK / BLANCO MV	20F	3211	11W	BGT	DBI WALL STEEL
OX CANYON UNIT #013	3004521489	BLANCO PC	20A	32N	11W		FIBERGLASS TANK WBANDED 20 mil

WELLS W/FEDERAL	A.D.	The same		T 1444.	P1 10	m, 14	CONCEDICTION MATERIAL
SURF MGT	<u>API</u>	FMT	SEC	IWN	KNG	PITIY	FIBERGLASS TANK W/BANDED 20 mil
COX CANYON UNIT #023	2004600603	DI ANK A DO	45,	20.81	4 4 4 6 5	per	
CANIL CONTRACTOR OF THE CONTRA	3004522537	BLANCOPC	17(351/	111/	BG1	FIBERGLASS TANK WBANDED 20 mil
COX CANYON UNIT #025	3004522572	BLANCOPC	90	32N	111/	BG1	HDPE SECONDARY LINER
Con Containing Chair has	3004322372	DIMINOOTIC	90	3/1 V	t I VV	pol	FIBERGLASS TANK WBANDED 20 mil
COX CANYON UNIT #200	1004527878	BASINTIC	91	32N	1177	BG1	HDPE SECONDARY LINER
37. 37. 37. 37. 37. 37. 37. 37. 37. 37.	AMMUE FOFO	DUSHAL ()	स्म	JVIN	1177	DO1	FIBERGLASS TANK W/BANDED 20 mil
COX CANYON UNIT #200A	3004532126	BASINETC	4()	3211	1 I W	BG1	HDPE SECONDARY LINER
	300-032 120	OFFICIAL CO.	7(7	VICIN	1 (V V	(OC)	FIBERGLASS TANK W/BANDED 20 mil
COX CANYON UNIT #203	3004527872	BASINTIC	17A	32N	1 1 1 1 1 1 1 1	BGT	HDPE SECONDARY LINER
	3004027072	DAGINTIO	117	JZIV	1100	1000	THE CA COMMITTEE THE IT
MADDOX #001	3004511487	BLANCO MV	10N	32N	11VV	BG1	DBI WALL STELL
	200 W (170)	#11 11 4 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1	14/14	UZ IV	1 1 V V	OOT	Side tricks will be
MADDOX #001A	3004523539	BLANCO MV	100	32N	11W	BGI	DBL WALL STEFL
	DIO TOLINO	2117111000 1111	17/1	CALIT	1 1 4 4	DOT	DUR TITUL OTRET
NM 32 11 #001	3004511309	BLANCO MV	200	32N	11W	BGT	DBL WALL STEEL
	_ · · · · · ·	BASIN DK /					·
NM 32-11 #001B COM	3004532024	BLANCO MV	20J	32N	11W	BG1	DBL WALL STEEL
		BASIN DK /			. ,		
NM 32-11 #001C COM	3004532804	BLANCO MV	201	32N	11 VV	BGT	DBI, WALL STEEL
					-		FIBERGLASS TANK w/BANDED 20 mil
NM 32-11-#002-COM	3004511380	BLANCO MV	19A	32N	11W	BG1	HIDPE SECONDARY LINER
NM 32 11 #002A COM	3004529017	BLANCO MV	190	3211	11 <i>V</i> V	BGT	DBI WALL STEEL
NM 32 11 #002B COM	3004532670	BLANCO MV	191	3214	11\/	HGT	DBI WALL STEFI
NM 32-11 #002C COM	3004533077	BLANCO MV	196	32N	1 1 VV	BG1	DBI WALL STEFI
ROSA UNIT #001 SWD	3003927055	SWD	231	31N	06W	BGT	DBL WALL STEEL
		BASIN DK /					FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #001E	3003925411	BI ANCO MV	11P	31N	06W	BGI	HDPE SECONDARY LINER
		BLANCO MV /					
ROSA UNIT #005A	3003925407	ROSA PC	20F	31N	()(₎ VV	BG1	DBI WALL STEEL
		BASIN DK /					
ROSA UNIT #005B	3003926927	BLANCO MV	26B	3111	00M	BGI	DBL WALL STEEL
							FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #005Y	3003926076	BLANCO MV	26H	3114	()(;\V	BGT	HDPE SECONDARY LINER
		BLANCO MV /					FIBERGI ASS TANK W/BANDED 20 mil
ROSA UNIT #008	3003907944	ROSA PC	26M	31N	06W	BG1	HOPE SECONDARY LINER
400 h 1 h 117		BLANCO MV /					FIBERGLASS TANK W/BANDED 20 mil
KOSA UNIT #008	3003907944	ROSA PC	26M	31N	06W	BG1	HDPE SECONDARY LINER
2006 A 1 16117 19099 A		BLANCO MV /	4				FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #006A	3003925430	ROSA PC	26D	311/	06W	BG1	HDPE SECONDARY LINER
COCA LIBERT HOOM		0. 11.00					FIBERGLASS TANK W/BANDED 20 mil
COSA UNIT #008C	3003926944	BLANCO MV	26N	31N	06W	BGT	HDPE SECONDARY LINER
OCA LIBIT HOOF		DI MICO 101					FIBERGLASS TANK w/BANDED 20 mil
OSA UNIT #009	3003907975	BLANCO MV	11K	31N	06W	BGT	HDPE SECONDARY LINER
ACA HAIT MANA		BASIN DK /					
OSA UNIT #009A	3003925584	BLANCO MV	11C	31N	06W		DBI WALL STEEL
COCK THAIL AGO.		0.44.00			4		FIBERGLASS TANK w/BANDED 20 mil
OSA UNIT #009B	3003927042	BI ANCO MV	11E	31N	06W		HDPE SECONDARY LINER
COALLAND COALCA							FIBERGLASS TANK W/BANDED 20 mil
OSA UNIT #010B	3003926556	BI ANCO MV	1311	31N	06W	BG1	HDPE SECONDARY LINER
2007 14417 11117				_			
DSA UNIT #010C	3003926918	BLANCO MV	13N	31N	06W	BGT	DBL WALL STEEL
N 6 1151175		m1					
)SA UNIT #0101	3003926556	BLANCO MV	13N	31N	06W	BG1	DBL WALL STEEL

•

WELLS WIFEDERAL	na de la malamante mara de terre						The second is a second
SURF MGT	API	FMT	SEC	IWN	RNG	PITTY	PE CONSTRUCTION MATERIAL
ROSA UNIT #012A	3003925900	BLÂNCO MV / ROSA PC	15J	₹1N	oevv	BG1	
ROSA UNIT #012B	3003926556	BASIN DK / BLANCO MV	15F	31N	(161/	BGI	FIBERGLASS TANK WIBANDED 70 mil HDPF SECONDARY LINER
ROSA UNIT #012C	3003929486	BLANCO MV	15A	41N	0647	ار،1	SINGLE WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #013	3003907936	BLANCO MV	31G	3111	osw	861	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #013A	3003926298	BLANCO MV BASIN DK /	318	31N	05VV	FGI	HDPE SECONDARY LINER
ROSA UNIT #013B COM	3003929834	BLANCO MV	31A	31N	051/4	BGI	DBL WALL STEEL FIBERGLASS TANK w/BANDFD 20 mil
ROSA UNIT #014	3003907958	BLANCO MV	23B	31N	06W	BG1	HDPE SECONDARY LINER LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #014A	3003926280	BLANCO MV BASIN DK /	230	31N	06VV	BG1	HDPE SECONDARY LINER
ROSA UNIT #014(.	3003930132	BLANCO MV	2311	31N	06W	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #015	3003907946	BI ANCO MV	2911	31N	05W	BGI	HDPF SECONDARY LINER FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #016	3003907963	BLANCO MV	1411	31tJ	06VV	BGI	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #U1GA	3003925496	BLANCO MV	14(,	31N	06W	BGT	HDPE SECONDARY LINER HBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #016B	3003926218	BLANCO MV	14M	31N	06//	HGT	HDPE SECONDARY LINER LIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #01/A	3003926272	BLANCO MV BASIN DK /	200	RIN	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mill
ROSA UNIT #()17B	3003926971	BLANCO MV BLANCO MV /	20J	31N	05Vv	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #018	3003907960	ROSA PC BLANCO MV /	2211	3111	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #016A	3003925436	ROSA PC	221	31N	06/\	SG1	DBI WALL STEEL
ROSA UNIT #018B	3003927052	BLANCO MV	220	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #019	30(13907955				06W	HG1	FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #019B	3003926560	BLANCO MV	241	31N	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #019C	3003929625	BLANCO MV	24D	31N	06W	BGT	DBI WALL STEEL
ROSA UNIT #019C	3003929625	BLANCO MV	240	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #020	3003907969	BLANCO MV	14G	31N	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mill
ROSA UNIT #020A	3003925495	BLANCO MV	14()	31N	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #020B	3003926220	BI ANCO MV	14A	31N	06W	BGT	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #020C	3003926221	BLANCO MV	14J	31N	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #021A	3003926121	BL ANCO MV	23C	31N	06W	BGT	HDPE SECONDARY LINER
ROSA UNIT #021B	3003926554	BL ANCO MV	23K	31N	06W	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #UZİ	3003907971	BLANCO MV	18A	31N	05W	BG1	HDPE SECONDARY LINER

.

WELLS W/FEDERAL SURF MGT	API	FMT	SEC	TWN	RNG	אר ווק	E CONSTRUCTION MATERIAL
ROSA UNIT #022A	3003926390	BLANCO MY	180	1111	05VV	BGI	FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #021	3003907942	BLANCO MV	29M	31N	05Vv	BG1	FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #023F	3003926553	BLANCO MV	29[31N	06.VV	BGI	FIBERGLASS TANK w/BANDED 20 mil HDPE SECONDARY LINER
 ROSA UNIT #023C	3003927609	BASIN DK / BLANCO MV	291	31N	05W	BGT	FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #024							FIBERGLASS TANK WBANDED 20 mill HDPF SECONDARY LINER
	3003907933	BLANCO MV BASIN DK /	32M	11N	05W	BGI	
ROSA UNIT #024A	3003925568	BLANCO MV BASIN DK /	32E	31N	05W	SGI	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #024B	3003 926 630	BLANCO MV BASIN DK /	32N	31N	05W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #0240	3003926968	BLANCO MV BASIN DK /	32C	31N	05W	BGT	HOPE SECONDARY LINER
ROSA UNIT #026A	3003925580	BI ANCO MV	320	31N	05W	SGT	DBI WALL STEEL
ROSA UNIT #026B	3003926788	BASIN DK	32G	31N	05W	SG1	DBI WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #029	3004511136	BLANCO MV BASIN DK /	32H	32N	0677	BGI	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #029B	3004530709	BLANCO MV	32B	NSE.	0617	861	HDPE SECONDARY LINER
ROSA UNIT #029M	3004529584	BASIN DK / BLANCO MV	321	3211	(/oW	BGI	DBI WALL STEFI
ROSA UNIT #030 COM	3003925570	BASIN DK / BLANCO MV	120	31N	0674	BGI	FIBERGLASS TANK w/BANDE() 20 mil HDPE SECONDARY LINER
ROSA UNIT #030A	3003926068	BLANCO MV	1214	31N	OGVV	BGI	FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #03(IB	3003926601	BLANCO MV	12N	31N	06W	BGT	HIBERGLASS TANK W/BANDED 70 mil HDPE SECONDARY LINER
ROSA UNIT #030C	3003929842	BLANCO MV	1281	31N	06W	BGT	DBI WALL STEEL
ROSA UNIT #031	3003926279	BLANCO MV	17G	31N	05Vv	BGT	FIBERGLASS TANK W/BANDED 20 mill HDPE SECONDARY LINER
ROSA UNIT #031A	3003926346	BLANCO MV	171	31N	05W	BG1	FIBERGLASS TANK W/BANDED 20 mill HDPE SECONDARY LINER
ROSA UNIT #031F	3003926579	BASIN DK / BLANCO MV	17D	31N	05Vv	BG1	FIBERGLASS TANK WBANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #051C	3003926578	BI ANCO MV	17N	31N	05W		FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #032		BLANCO MV / ROSA PC					DBL WALL STEEL
··-	3003925389	BLANCO MV /	2111	31N	06W		
ROSA UNIT #032A	3003925417	ROSA PC BASIN DK /	211	31N	06W		DBL WALL STEFL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #032B	3003926771	BLANCO MV BASIN DK /	21G	31N	06W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #032C	3003927240	BI ANCO MV	21F	31N	06W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #034	3003907984	BLANCO MV	36B	3211	06W		HDPE SECONDARY LINER
ROSA UNIT #034A	3003926119	BI ANCO MV	361	32N	06W	BGI	DBL WALL STEEL
ROSA UNIT #034/4	3003926119	BI ANCO MV	361	32N	06W		DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil :
ROSA UNIT #034E	3003926629	BLANCO MV	363	3214	06W		HDPE SECONDARY LINER

WELLS W/FEDERAL SURF MG1	API	FMT	SEC	TWN	RNG	PIT TYP	
ROSA UNIT #1134(3003926969	BLANCO MV	36H	NSE	()6Vv	EG1	TIBERGLASS TANK W/BANDED 20 n HDPE SECONDARY LINER
ROSA UHIT #035X	3004510996	PLANCO MV	5K	3114	0674	BG1	DBL WALL STEEL FIBERGLASS TANK WRANDED 20 n
ROSA UNIT #036	3003907977	PLANCO MV	1111	3110	aevv	FGI	HDPE SECONDARY LINER HBERGLASS TANK WBANDED 20 n
ROSA UNIT #0360	3003930182	BLANCO MV	11(7	NIE	06\\	HG1	HDPF SECONDARY LINER FIBERGLASS TANK WBANDED 20 n
ROSA UNIT #041	3003207981	BLANCO MV BASIN DK /	5K	31N	05Vv	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 n
ROSA UNIT #041B	3003927014	BLANCO MV	લા	MIE	05Vv	BG1	HDPE SECONDARY LINER
ROSA UNIT #044	3003925873	BLANCO MV	35K	32N	W80	BGI	DBE WALL STEEL
ROSA UNIT #044A	3003926161	BLANCO MV	35 E	32N	00·W	SGI	SINGLE WALL STEEL
ROSA UNIT #044A	3003926161	BI ANCO MV	35E	32N	06W	SGI	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 n
ROSA UNIT #044B	3003926685	BLANCO MV	35C	32N	06VV		HDPF SECONDARY LINER FIBERGLASS TANK W/BANDED 20 m
ROSA UNIT #045	3003923013	BLANCO MV BASIN DK /	9M	31N	05W	BGT	HDPE SECONDARY LINER HBERGLASS TANK W/BANDED 20 n
ROSA UNIT #046A	3003926986	BLANCO MV	80	3111	05W		HDPE SECONDARY LINER
ROSA UNIT #051	3003920289	BASIN DK	23C	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 n
ROSA UNIT #053	3003 92 0293	BASIN DK	8B	31N	05W		HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20 n
ROSA UNIT #055	3003920923	BASIN DK	341	31N	05VV		HDPE SECONDARY LINER
ROSA UNIT #059 DF	3003923270	BASIN DK	25N	31N	06W		DBL WALL STEFL FIBLRGLASS TANK w/BANDED 20 m
ROSA UNIT #059 GL	3003923270	UNDES GL	25N	31N	06Vv	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-ni
ROSA UNIT #060	3004529798	BLANCO MV	41	31N	()6 V v		HDPE SECONDARY LINER
ROSA UNIT #064	3003921703	BASIN DK	29A	31N	05Vv	BGT	DBL WALL STEEL
ROSA UNIT #064	3003921703	BASIN DK BASIN DK /	29A	31N	05W	SGI	OBI WALL STEEL
ROSA UNIT #064M	3003925563	BLANCO MV	29F	31N	05W	-	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20-m
ROSA UNIT #065	3003921702	BASIN DK	17A	31N	05VV	BG1 I	HDPE SECONDARY LINER IBERGLASS TANK W/BANDED 20 no
OSA UNIT #066	3003921758	BASIN DK BASIN DK /	13L	31N	06//	BG1 I	HDPE SECONDARY LINER HBERGLASS TANK W/BANDED 20 mi
OSA UNIT #066M	3003925747	BI ANCO MV	13F	31N	06W	BGT I	HDPE SECONDARY LINER BERGLASS TANK W/BANDED 20 m
OSA UNIT #072	3003925509	BI ANCO MV	61	31N	05W	BG1	IDPE SECONDARY LINER IBERGLASS TANK W/BANDED 20 m
OSA UNIT #072A	3003925795	BI ANCO MV	6K	31N	05W	BG1 H	IDPE SECONDARY LINER IBERGLASS TANK W/BANDED 20 m
OSA UNIT #075	3004529895	BLANCO MV	10l	31N	06W	BG1 F	HDPE SECONDARY LINER HBERGLASS TANK W/BANDED 20 m
OSA UNIT #075A	3004529854	BLANCO MV	40	31N	06VV	BGT F	IDPE SECONDARY LINER
OSA UNIT #07 ²	3003922538	DK/UNDES GL/BLANCO	33L	31N	U5W		TIBERGLASS TANK W/BANDFD 20 m HDPE SECONDARY LINER

WELLS W/FEDERAL							
SURF MGT	API	FMT BASIN DK /	SEC	TWN	RNG	PITTY	E CONSTRUCTION MATERIAL
ROSA UNIT #079	3003922539	BLANCO MV BASIN DK	22K	3114	0614	BGT	DBL WALL STELL
ROSA UNIT #079	3003922539	BLANCO MV	22h	3114	06W	SGI	OBL WALL STEFL
ROSA UNIT #079A	3003925412	ROSA PC BASIN DK /	221	3114	06W	BG1	DBL WALL STEEL
ROSA UNIT #079B	3003926920	BLANCO MV	220	31N	06VV	BGT	DBL WALL STEEL
ROSA UNIT #0790	3003929902	BLANCO MV BASIN DK /	318	31N	05W	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #080	3003922537	BLANCO MV	вĸ	31N	05Vv	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #080A	3003926413	BLANCO MV	86	31N	05W	BG1,	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #085	3003922778	BASIN DK	20A	31N	05W	BGT	HUPE SECONDARY LINER LIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #085	3003922778	BLANCO MV	20A	31N	0517	BGI	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #085A	3003926314	BLANCO MV	20C	31N	05W	ВоТ	HDPE SECONDARY LINER
ROSA UNIT #085P	3003930130	BLANCO MV	20D	3111	05W	BGI	DBI WALL STEEL
ROSA UNIT #086	3003922766	UNDES GI BLANCO MV /	12W	31N	04W	SG1	SINGLE WALL STEEL
ROSA UNIT #086	3004525140	ROSA PC	-18	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK w'BANDED 20 mil
ROSA UNIT #089	3003922782	BLANCO MV	34A	32N	OΘVV	BGT	HDPE SECONDARY LINER FIBERGLASS TANK & BANDED 20 mil
ROSA UNIT #UR9A	. 3003925512	BLANCO MV	34()	32N	06W	HG1	HDPE SECONDARYLINER
ROSA UNIT #089P	3003926851	PLANCO MV	341	32N	06VV	BGI	DBI WALL STEEL
ROSA UNIT #089C	3003926674	BLANCO MV	34G	3211	OGVV	SG1	SINGLE WALL STELL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #090 COM	3004525370	BLANCO MV	33G	32 N	06VV	BGI	HDPE SECONDARY LINER
NOSA UNIT #090A COM	3004529259	BLANCO MV	33G	3214	06\\	BGT	()BL WALL STEEL FIBERGLASS TANK w/BANDE() 20 mil
ROSA UNIT #091	3003922780	BI ANCO MV	3511	32N	06W	BGT	HDPE SECONDARY LINER
KOSA UNIT #091A	3003925790	BLANCO MV	350	32N	06W	SG1	DBI WALL STEFL
ROSA UNIT #091B	3003926684	BI ANCO MV	35P	32N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #091C	3003926991	BI ANCO MV	35G	32N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
OSA UNIT #098	3003923265	BASIN DK / GL BASIN DK /	231	31N	06W	BG1	HDPF SECONDARY LINER
OSA UNFF #100B	3003929547	BLANCO MV	210	31N	06W	BGT	DBL WALL STEEL J
OSA UNIT #100C	3003929851	BLANCO MV	21K	31N	W60	BGT	DBL WALL STEEL
OSA UNIT #100E	3003925135	BLANCO MV / ROSA PC	211	31N	06W	SG1	SINGLE WALL STEEL
NHOL# TIMU ASC	3003925577	BLANCO MV	24F	31N	06W		DBL WALL STEEL
OSA UNIT #108	3003923506	BASIN DK / GL	7G	3111	U5W		FIBERGLASS TANK w/BANDED 20 mil HDPE SECONDARY LINER

. . .

WELLS W/FEDERAL SURF MGT	API	FMT	SEC	IWN	RNG	. <u>PII 1Y</u>	PE CONSTRUCTION MATERIAL
ROSA UNIT #119	30039/5143	PASIN DK	16N	31N	0; \%	BG1	DBL WALL STEEL FIBERGLASS TANK w BANDED 20 m
ROSA UNIT #125	3003925144	BLANCO MV	138	31N	Оь\/v	BGT	
ROSA UNIT #1250	3003929843	BLANCO MV BASIN DK /	136	31N	06W	BGT	DEL WALL STEEL FIBERGLASS TANK W/BANDED 20 mi
ROSA UNIT #125E	3003925526	BLANCO MV	13.J	3110	06W	BGT	HOPE SECONDARY LINER
ROSA UNIT #129	3003926304	BLANCO MV	34E	32N	(16W	BG1	DBL WALL STEEL
ROSA UNIT #129A	3003926297	BLANCO MV	34K	32N	06W	BGT	
ROSA UNIT #137	3003925410	BLANCO MV	31K	31N	05W	BG1	FIBERGLASS TANK WBANDED 20 mi HDPE SECONDARY LINER
ROSA UNIT #137A	3003926129	ROSA PC	311	31N	05W	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 nu
ROSA UNIT #137B	3003927002	BLANCO MV BLANCO MV	316	31N	05W	BGT	HDE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mg
ROSA UNIT #138	3004529147	ROSA PC BLANCO MV /	171	31N	06VV	BGT	HOPE SECONDARY LINER
ROSA UNIT #138A	3004529134	ROSA PC	1711	3111	06W	BGT	DBI WALL STEEL
ROSA UNIT #138B	3004532168	BLANCO MV	1711	3111	()6VV	BGT	DRI WALL STEFL
OSA UNIT #139A	3004529600	BLANCO MV	17M	3111	00W	HG1	DPL WALL STEEL
OSA UNIT #140	3003925435	ROSA PC	22K	3110	0677	BGT	DBL WALL STEFL
ROSA UNIT #144	3003925421	ROSA FC	26A	31N	06W	BGT	DBI WALL STEEL
COSA UNIT #145C	3004533086	BLANCO MV	16F	31N	06W	861	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
OSA UNIT #146A	3003925513	BLANCO MV	28N	31N	06W	BGT	HOPE SECONDARY LINER
OSA UNIT #1460	3003930187	BLANCO MV	28B	31N	05W	BG1	DBL WALL STEFF
OSA UNIT #148	3003925493	BASIN DK	20	31N	06W	BG1	DBI WALL STEFL
OSA UNIT #148A	3003925776	BL ANCO MV	2N	31N	OGW	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mit
OSA UNIT #148B	3003926985	BI ANCO MV	2P	31N	06Vv	HG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
OSA UNIT #149	3003925501	BI ANCO MV	12G	31N	06W	BG1	HDPE SECONDARY LINER
OSA UNIT #149A	3003925807	BLANCO MV	12f	31N	06 V V	BG1	DBI WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
OSA UNIT #149B	3003926599	BASIN DK / BLANCO MV	12E	31N	06VV	BG1	HOPE SECONDARY LINER
OSA UNIT #150	3004529229	BI ANCO MV	32F	32N	06W	BGI	FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
OSA UNIT #150A	3004529592	BI ANCO MV	32M	32N	06W	BG1	DBL WALL STEEL
OSA UNIT #150B	3004530874	BASIN DK / BLANCO MV	32D	32N	06W	BG1	DBL WALL STEEL
OSA UNIT #15()(3004532157	BI ANCO MV	32K	32N	06W	BGT	DBL WALL STEEL
OSA UNIT#15	3004529267	BLANCO MV	33C	32N	06W	BG1	DBL WALL STEEL

WELLS W/FEDERAL SURF MGT	API	FMT	SEC	IWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
KOSA UNIT #151A	3004529631	BLANCO MV	331	3211	06Vv	HG1	DBL WALL STEFT
ROSA UNIT #151C.	3004532196	BLANCO MV	3314	12N	061/v		DBI WALL STEEL FIBERGLASS TANK WBANDED 20 mi
ROSA UNIT #152	3003925494	BLANCO MV	368	32N	0617	PG1	HOPE SECONDARY LINER
ROSA UNIT #152A	3003925695	BLANCO MV	36N	3214	06W	BG1	DBI WALL SIFEL
ROSA UNIT #152B	3003926631	BLANCO MV	36C	32N	06W		DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 m
ROSA UNIT #1526	3003927635	BLANCO MV	361	32N	() (, VV	2	HDPE SECONDARY LINER FIBERGLASS TANK WIBANDED 20cm
ROSA UNIT #153	3003925524	BLANCO MV	17()	31N	05W		HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20 m
ROSA UNIT #153A	3003926329	BLANCO MV BASIN DK /	1//	311	05W	••••	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-m
ROSA UNIT #153B	3003927603	BLANCO MV	171	31N	05W		HDPE SECONDARY LINER
ROSA UNIT #164	3003925893	BLANCO MV	7N	31N	05VV		DBL WALL STEEL FIBERGLASS TANK WBANDED 20 m
ROSA UNIT #154A	3003926274	BLANCO MV	7F)	3111	05W		HDDE SECONDARY LINER FIBERGLASS TANK WBANDED 20 no
ROSA UNIT #156	3004529661	BLANCO MV	9A	3114	06W		HDDE SECONDARY LINER FIBERGLASS TANK WBANDED 20 m
ROSA UNIT #1564	3004529640	BLANCO MV BASIN DK	91	31N	OoW		HOPE SECONDARY LINER
ROSA LINIT #159 COM	3003925583	BI ANCO MV	190	31N	05W	_	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 m
COSA UNIT #159A	3003926273	BLANCO MV	19N	3110	05V/		HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 m
ROSA UNIT #15C	1003930111	BLANCO MV BLANCO MV /	29G	31N	05VV		HIDRE SECONDARY LINER
ROSA UNIT #160	3003925890	ROSA PC	25O	31N	0644		DBL WALL STEEL
AOSA UNIT #160A	3003925818	BLANCO MV BASIN DK /	25N	31N	Wau		DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 m
ROSA UNIT #160B	3003926962	BI ANCO MV	251	31N	06Vv		HDPE SECONDARY LINER
ROSA UNIT #160C	3003929778	BLANCO MV	25J	31N	06W		DBI WALL STEEL FIBERGLASS TANK W/BANDED 20 m
RUSA UNIT #162	3003926069	BLANCO MV	30K	31N	05W		HDPE SECONDARY LINER
ROSA UNIT #162B	3003929845	BLANCO MV	30P	31N	05W		DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 m
ROSA UNIT #163	3003926345	BLANCO MV	24G	31N	06W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 m
ROSA UNIT #163A	3003926336	BLANC() MV	240	31N	06W		HOPE SECONDARY LINER
ROSA UNIT #163B	3003929921	BLANCO MV	24B	31N	06W		DBL WALL STEEL
ROSA UNIT #163C	3003929611	BLANCO MV BASIN DK /	24J	31N	06W	-	SINGLE WALL STEEL FIBERGLASS TANK w/BANDED 20 m
ROSA UINIT #164	3003926151	BI ANCO MV	13	31N	W80		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 m
ROSA UNIT #164A	3003926080	BLANCO MV BASIN DK /	1 J	31N	06W		HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 m
!OSA UNIT #164E	3003927242	BLANCO MV	1J	31N	06W		HDPE SECONDARY LINER

WELLS W/FEDERAL						·	
SURF MGT	API	FM1	SEC	IWN	RNG	PITTY	PE CONSTRUCTION MATERIAL
ROSA UNIT #165	3003926070	BLANCO MV / ROSA PC	261	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 md
ROSA UNIT #16FA	3003926150	BLANCO MV BASIN DK /	25B	31N	OGVV	1:08	HOFE SECONDARY LINER
ROSA UNIT #165B	3003926557	BLANCO MV BASIN DK /	251	31N	OGVV	HG1	DBI WALL STEFL
ROSA UNIT #1650	3003926961	BLANCO MV	25G	31N	06W	BG1	DBI WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #166	3003926275	BLANCO MV	30A	11N	U5W	HGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #166A	3003926282	BLANCO MV	301	31N	05VV	BG1	HILLE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #167A	3004529886	BLANCO MV	8.8	31N	06Vv	BGT	HDPE SECONDARY LINER
ROSA UNIT#169	3003926130	BLANCO MV	. 3J	3111	06W	BG1	DBI WALL STEFF
ROSA UNIT #169A	3003926149	BLANCO MV	31	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #1690	3003927717	BLANCO MV	2M	3111	06Vv	BGI	HDFE SECONDARY LINER
ROSA UNIT #170	3003925851	BLANCO MV	21N	31N	0677	861	DBI WALL STEFT
ROSA UNII #171	3003926280	BLANCO MV	ιG	3111	0£W	BG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #171A	3003926389	BLANCO MV	76	31N	05W	HGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #171B	3003927013	BLANCO MV	615	31N	05W	BG1	HDF'E SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #180	3004529898	BLANCO MV	9N	31N	06W	ЬGТ	HDPE SECONDARY LINER
ROSA UNIT #180F	3004533134	BLANCO MV	91	3111	06W	BGT	DBL WALL STEFF
ROSA UNIT #1800	3004533191	BLANCO MV	96	31N	0674	BGI	DBI WALL STEFL
ROSA UNIT #181	3003926463	BLANCO MV	11K	31N	06VV	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #181A ROSA UNIT #181C (shared	3003926312	BLANCO MV	15A	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
w/169C)	3003927714	BLANCO MV	2M	31N	06W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #182	3003926283	BLANCO MV	18N	31N	(15W	8G1	HDDE SECONDARY LINER
ROSA UNIT #182A	3003926285	BLANCO MV	18P	31N	05W	5 61	DBI WALL STEEL
ROSA UNIT #1820	3003930180	BLANCO MV	18F	31N	05W	SG1	SINGLE WALL STEFL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #183	3003926387	BLANCO MV	19G	31N	05W	HG1	HOPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #183A	3003926386	BI ANCO MV	19f	31N	05W	BG1	HDPE SECONDARY LINER
ROSA UNIT #183B	3003930087	BLANCO MV BASIN DK /	19B	31N	05W	BGI	UBL WALL STEFL
ROSA UNIT #185B	3004532734	BLANCO MV	16F	31N	06W	RG1	DBL WALL STEFL
ROSA UNIT #1850	3004534484	BLANCO MV	16F	31N	06W	BGI	()BI WALL STEEL
ROSA UNIT #185	3003930186	BLANCO MV	21G	31N	05W	BG1	DBL WALL STEEL

SURF MG1	<u>API</u>	FMT .	<u>SEC</u>	IWN	RNG	PIT TYPE	CONSTR	UCTION	MATERIAL
ROSA UNIT #231	300 392444 1	RASIN1 10	11N	31N	05V/	561	SINGLE WALL	SHII	
COSA UNIT #335A	3003930222	BASIN FIC	05.1	3111	05VV	561	SINGLE WALL	SIEEL	

.

Fields, Vanessa

From:

Fields, Vanessa

Sent:

Tuesday, October 11, 2011 4:47 PM

To:

'Brandon Powell (Brandon Powell@state.nm.us)'

Cc:

Lane, Myke; Lucero, Christopher

Subject:

Closure Rosa Unit #100B

Brandon⁻

Williams has an approved closure plan for the Rosa Unit #100B from Brad. We have a drilling rig scheduled this week to commer the Rosa Unit# 260A but need to strip the Rosa Unit #100B to allow room for the drilling rig. William's request your approval to re grade tank from the Rosa Unit #100B on October 11, 2011. Please let me know if this is unacceptable. Thank you for your time

Well Site	API	FMT	SEC	TWN	RNG
Rosa Unit # 100B 06W	30-03929547	Mesa Verde	0 21	31N	

Thank You Vanessa Fields

Vanessa Fields



EH&S Coordinator Williams Production Office: 505-333-1880

Fax: Cell:

505-333-1850 505-419-6219

vanessa.fields@williams.com

<u>District I</u> 1625 N French Di , Hobbs, NM 88240 1301 W Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Di , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action												
						OPERA T	ΓOR	⊠ 1	nıtıal R	Report		Final Report
Name of Co	mpany V	WILLIAMS	PRODU	CTION, LLC	(Contact	HOLLY C. PEI					
Address		P.O. BOX 64	10, AZTE	EC, NM 87410]	Telephone No. (505) 634-4209						
Facility Nar	ne Rosa U	nit #100B			F	Facility Type Well Site						
Surface Ow	ner Federa	il		Mineral C	wner			Lea	se No.			
				LOCA	TION	OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North/S	South Line	Feet from the	East/West L	West Line County			
0	21	31N	06W									
			Latitude	e_36.880000003	3	Longitude	-107.46528	01				
	NATURE OF RELEASE											
Type of Rele	ase No Rele	ease Detected		71122	UILL		Release NA	Volu	ne Reco	overed N	A	
Source of Re						Date and I-	lour of Occurrence	e Date	and Ho	ur of Disc	covery	/ NA
Was Immedia	ate Notice (Yes [No 🛛 Not Re	equired	If YES, To NA	Whom?				·	
By Whom?						Date and F	lour					
Was a Watercourse Reached?					If YES, Vo	olume Impacting t	the Watercours	e				
☐ Yes ⊠ No						NA						
If a Watercou	If a Watercourse was Impacted, Describe Fully * NA											
Describe Cau	ise of Probl	em and Reme	dial Action	Taken *								
NA NA												
	a Affected	and Cleanup A	Action Tak	ken *								
NA												
I NA												
I hereby certi	fy that the	information gi	ven above	e is true and comp	lete to th	ne best of my	knowledge and u	inderstand that	pursuar	nt to NMO	OCD 1	rules and
regulations a	ll operators	are required t	o report ar	nd/or file certain r	elease no	otifications a	nd perform correc	ctive actions fo	r release	es which	may e	ndanger
				ce of a C-141 repo								
				investigate and rotance of a C-141								
		ws and/or regu		nance of a C-141	report at	oes not renev	e the operator of		or com	phanee w	itii aii	y other
1	<u> </u>	M	J_				OIL CON	SERVATION	ON D	IVISIO	<u>N</u>	
Signature	Jan	1 eace	حسه	<u> </u>								
Printed Name	e Vanessa	Fields			1	Approved by	District Supervis	or				
Title EH&S	Coordinate	or				Approval Da	te·	Expira	tion Dat	te [.]		
E-mail Addre	ess. Vaness	sa.ficlds@wıll	iams com		(Conditions o	f Approval			Attachad		
Date 12	2/8/2011		Phone.	(505) 333-1880		Conditions of Approval Attached						

^{*} Attach Additional Sheets If Necessary

Williams Production Co., LLC San Juan Basin: New Mexico Assets

Below-Grade Tank Removal
Closure Plan

In accordance with Rule 19 15 17 13 NMAC, the following plan describes the general closure requirements of below-grade tanks (BGI) on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard closure procedure for all BGIs regulated under Rule 19 15 17 NMAC and operated by WPX. For those closures which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized

Closure Conditions and Timing:

Pursuant to 19 15,17 13 (A) NMAC, WPX will initiate closure of any BG1 should any one of these conditions occur.

- The Division requires closure because of imminent danger to fresh water, public health or the
 environment
- The integrity of the BGT fails Notification will be within 48 hours to the Division and closure will be schedule as specified in 19.15 17.12 (A)(5) NMAC
- WPX chooses to take the BG1 out-of-service due to operational needs. Closure under these conditions will be closed within 60 days of cessation of the BG1's operation.
- BG1s installed prior to June 16, 2008 that do not meet the requirements under 19 15.17 11 1(6) NMAC and WPX chooses not to retrofit or upgrade. Closure under these conditions will be completed within five years (by June 16, 2013)

General Plan Requirements:

- Prior to initiating any BG1 Closure except in the case of an emergency. WPX will review County Tax Records for the current surface owner of record. The surface owner of record will be notified of the intent to close the BG1 by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the surface owner of record will be notified as soon as practical.
- Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following
 - a. Operators Name (WPX)
 - b Well Name and API Number
 - c Location (US1R)
- 3. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank, ...) The well will be temporarily shut in until the rerouting is completed.
- All produced water will be removed from the BG1 following discharge-pipe rerouting Produced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BG1 site: Rosa Unit SWD #1 (Order SWD-916, API 30-039-27055), Rosa Unit #94 (Order: SWD-3RP-1003-0, API: 30-039-23035), Jillson Fed. SWD #001 (Order: R10168/R10168A, API: 30-039-25465), Middle Mesa SWD #001 (Order: SWD-350-0, API, 30-045-27004) and/or Basin Disposal (Permit: NM-01-0005)
- Solids and sludges will be shoveled and for vacuumed out for disposal at Envirotech (Permit Number NM-01-0011)
- wPX will obtain prior approval from NMOCD to aispose recycle reuse, or reclaim the BG1 and provide documentation of the disposition of the BG1 in the closure report. Siee materials will be recycled or reused as approved by the Division. Fiberglass tanks will be empty cut up or shredded, and EPA cleaned for disposal as solid waste. Tiner materials will

be cleaned without soils or contaminated material for disposal as solid waste. Fiberglass tanks and liner materials will meet the conditions of paragraph 1 subsection D of 19 15 9 712 NMAC. Disposal will be at a licensed disposal facility, presently San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

- 7. Any equipment associated with the BG1 that is no longer required for some other purpose, following the closure will be removed from the location
- Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and fested per 19.15.17 13(E)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is wet, discolored or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Form C-141.

Table 1. Closure Criteria for BGTs

Components	Testing Methods	Closùrè Limits (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2
B1EX	EPA SW-846 Method 8021B or 8260B	50
TPH	EPA SW-846 Method 418.1(1)	100
Chlorides	EPA SW-846 Method 300 1(!)	250(2)

⁽¹⁾ Method modified for solid waste

- 9 If the Division and/or WPX determine there is a release WPX will comply with 19 15 3 116 NMAC and 19 15.1.19 NMAC
- Upon completion of the tank removal, the excavation will be backfilled with non-waste earlhen material compacted and covered with a minimum of one foot of top soil or background thickness whichever is greater and to existing grade. The surface will be recontoured to match the native grade and prevent ponding.
- For those portions of the former pit area no longer required for production activities. WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via diffling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un impacted) consisting at at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: If a surface owner agreement requires reseeding or other surface restoration that do not meet re-vegetation requirements of 19.15.17.13.I NMAC then WPX will submit the proposed alternative with written documentation that the surface owner agrees to the alternative for Division approval.
- For those portions of the former pit area required for production activities, reseeding will be done at well abandonment, and following the procedure noted above

Closure Report.

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the BG1 closure on a Closure Report using Division Form C-144. The Report will include the following

- Proof of Closure Notice (surface owner ENMOCE)
- Backfilling & Cover instaliano
- Site Diagram with coordinate
- Available Inspection report

- Contimution Sampling Analytical Results
- Disposal facility Name (s) and Fermit Number (s)
- Application Rate & Seeding techniques
- Photo Documentation of Reclamation

If background concentration of Chlorides greater than 250 mg/Kg, then higher concentration will be used for closure



Rose M. +# 2000 100B



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

WPX	Project #:	04108-0136
Rosa #100B	Date Reported:	10-17-11
59960	Date Sampled:	10-12-11
12271	Date Received:	10-13-11
Soil	Date Extracted:	10-17-11
Cool	Date Analyzed:	10-17-11
Intact	Analysis Requested:	8015 TPH
	Rosa #100B 59960 12271 Soil Cool	Rosa #100B Date Reported: 59960 Date Sampled: 12271 Date Received: Soil Date Extracted: Cool Date Analyzed:

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid

Waste, SW-846, USEPA, December 1996.

Comments:

Rosa #100B

5796 US Highway 64, Farmington, NM 87401

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com

Review



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client:	QA/QC	Project #:	N/A
Sample ID:	10-13-11 QA/QC	Date Reported:	10-17-11
Laboratory Number:	59992	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	10-13-11
Condition:	N/A	Analysis Requested:	TPH

	I <u>:</u> Cal Date	[‡] ⁄ l <u>÷</u> Cal(RF	C:Cal(RE	6 Difference	Accept Range
Gasoline Range C5 - C10	40829	9.971E+02	9.975E+02	0.04%	0 - 15%
Diesel Range C10 - C28	40829	9.996E+02	1.000E+03	0.04%	0 - 15%

Blank Conc. (mg/L⇒ mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	4.2	0.2
Diesel Range C10 - C28	2.8	0.1

Duplicate Conc. (mg/Kg)	Sample	: > Duplicate :-	% Difference	Range &
Gasoline Range C5 - C10	ND	ND	0.0%	0 - 30%
Diesel Range C10 - C28	ND	ND	0.0%	0 - 30%

Spike Conc. (mg/Kg)	\$ Sample :	Spike Addedi.	Spike Result	% Recovery	Accept Range
Gasoline Range C5 - C10	ND	250	254	101%	75 - 125%
Diesel Range C10 - C28	ND	250	253	101%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid

Waste,

SW-846, USEPA, December 1996.

Comments: QA/QC for Samples 59992, 59994, 59953-59960, 59984 and 59985

5796 US Highway 64, Farmington, NM 87401

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc com

Ŕeview



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client.	WPX	Project #:	04108-0136
Sample ID:	Rosa #100B	Date Reported:	10-17-11
Laboratory Number:	59960	Date Sampled ⁻	10-12-11
Chain of Custody:	12271	Date Received:	10-13-11
Sample Matrix:	Soil	Date Analyzed:	10-17-11
Preservative:	Cool	Date Extracted:	10-17-11
Condition:	Intact	Analysis Requested:	BTEX
		Dilution:	10

		Det.	
	Concentration	Limit	
Parameter	(ug/Kg)	(ug/Kg)	

Benzene	ND	0.9
Toluene	ND	1.0
Ethylbenzene	ND	1.0
p,m-Xylene	ND	1.2
o-Xylene	ND	0.9
Total BTEX	ND	

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	86.9 %
	1,4-difluorobenzene	92.2 %
	Bromochlorobenzene	91.6 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Rosa #100B

Review



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	N/A	1	Project #:		N/A
Sample ID:	1017BBLK QA/QC		Date Reported:		10-17-11
Laboratory Number:	59992		Date Sampled:		N/A
Sample Matrix:	Soil		Date Received.		N/A
Preservative:	N/A		Date Analyzed:		10-17-11
Condition:	N/A		Analysis:		BTEX
			Dilution:		10
	AND THE REPORT OF THE PROPERTY		Total miles All 1		1 . 1 J # 177 1
Calibration and Detection Limits (ug/L)	7 I-Cal RE	C-Cal RE Accept Rang	%Diff. ie 0 ≆ 15%	Blank Conc.	Detect:
Detection Limits (ug/L)	3.4245E+006		%Diff. ie 0	Blanky Conc.	Detect Limit
Detection Limits (ug/L)	3.4245E+006 3.5896E+006	Accept Rang	a stranger diene de la constitución de la constituc	Blank Conc ND ND	L'Imit
Detection Limits (ug/L) Benzene Toluene		Accept Rang 3.4313E+006	0.2%		Limit 0.1
Carried and State Albert State Comment of the first for it is	3.5896E+006	Accept Rang 3.4313E+006 3.5968E+006	0.2% 0.2%	ND	0.1 0.1

Duplicate Conc. (ug/Kg)	Sample: Du	plicate	% %Diff:	Accept Range/	Detect Limit
Benzene	ND	ND	0.0%	0 - 30%	0.9
Toluene	ND	ND	0.0%	0 - 30%	1.0
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0
p,m-Xylene	ND	ND	0.0%	0 - 30%	1.2
o-Xylene	ND	ND	0.0%	0 - 30%	0.9

Spike Conc. (ug/Kg)	Sample Amo	unt Spiked Spik	ed Sample ::: //%	Recovery.	Accept Range, 466
Benzene	ND	500	482	96.4%	39 - 150
Toluene	ND	500	481	96.3%	46 - 148
Ethylbenzene	ND	500	482	96.4%	32 - 160
p,m-Xylene	ND	1000	959	95.9%	46 - 148
o-Xylene	ND	500	476	95.2%	46 - 148

ND - Parameter not detected at the stated detection limit

Dilution: Spike and spiked sample concentration represent a dilution proportional to sample dilution

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments: QA/QC for Samples 59901-59903, 59905-59910, 599<u>59-599</u>60, 59992--59995



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	WPX	Project #:	04108-0136
Sample ID:	Rosa #100B	Date Reported:	10/20/11
Laboratory Number:	59960	Date Sampled:	10/12/11
Chain of Custody No:	12271	Date Received:	10/13/11
Sample Matrix:	Soil	Date Extracted:	10/20/11
Preservative:	Cool	Date Analyzed:	10/20/11
Condition:	Intact	Analysis Needed.	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

60.3

12.6

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Rosa #100B

Analyst

Review

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS **QUALITY ASSURANCE REPORT**

Client:

QA/QC

Project #:

N/A

Sample ID:

QA/QC

Date Reported:

10/20/11

Laboratory Number:

10-20-TPH QA/QC 59960

Date Sampled:

N/A

Sample Matrix: Preservative:

Freon-113 N/A

Date Analyzed: Date Extracted: 10/20/11 10/20/11

Condition:

N/A

10/18/11

Analysis Needed:

TPH

Calibration (Ecal Date

©:CallDate Accept Range

10/20/11

1,750

1,720

1.7%

+/- 10%

Blank Conc. (mg/Kg)

Concentration

Detection Limit

TPH

TPH

TPH

ND

12.6

Duplicate Conc. (mg/Kg)

......Sample 60.3

Duplicate Mange 63.1

4.6%

+/- 30%

Spike Conc. (mg/Kg)

Sample. 60.3

Spike Added Spike Result % Recovery Accept Range 2,000

1,890

91.7%

80 - 120%

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

QA/QC for Samples 59960 and 59997

Review

14



Chloride

WPX Project #: 04108-0136 Client: 10/18/11 Sample ID: Rosa #100B Date Reported: 10/12/11 Lab ID#: 59960 Date Sampled: Date Received: 10/13/11 Sample Matrix: Soil Preservative: Cool Date Analyzed: 10/18/11 Condition: Intact Chain of Custody: 12271

Concentration (mg/Kg) **Parameter**

Total Chloride 30

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Reference:

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Rosa #100B Comments:

Review

CHAIN OF CUSTODY RECORD

12271

Client:		*	Project Name /	Location	n:				T					ANAL	YSIS	/ PAF	RAME	TERS					
Wex			Rusa #	100	YS					_				,									
Client Address:			Sampler Name.	,	,				2	121)	g												
Client Address: Myke Lane Client Phone No.: Client No.					Sample No. Volume Preservative of				TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	<u>s</u>	_		۵								
Client Phone No.: Client No.									β	E P	힏	leta	DE		至		-	ш				8	tact
330-3192	Y		04	10	7-013	36			Met	S S	Met	RCRA 8 Metals	Cation / Anıon		TCLP with H/P		TPH (418.1)	CHLORIDE		ĺ		Sample Cool	Sample Intact
Sample No./	Sample	Samp	e Lab No.		Sample	No./Volume of	Pres	ervative	E E	ŭ)	J. A.	tion	75	다.	PAH	Ĭ,	2				E	lmp
Identification	Date	Time		j	Matrix	Containers	Containers HgCl, HCl		<u> </u>	<u> E</u>		<u> </u>	ပ္မ	PG.	F	₹_	<u> </u>	흐			19	<u>%</u>	
Rusa #100B	13/12	1234	5996	(Soil) Solid	Sludge Aqueous	1452			X	X							X	X				Y	/
				Soil Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous							_		-									
				Soil Solid	Sludge Aqueous																		
				Soil	Sludge Aqueous																		
				Soil	Sludge																		
				Solid	Aqueous Sludge			+													+	1	
				Solid	Aqueous Sludge			1														+	
				Solid Soil	Aqueous Sludge			-											\dashv		-	\dashv	-
				Solid	Aqueous			_															
		7		Soil Solid	Sludge Aqueous																		
Relinquished by: Signa	ture				Date / 3/13/11	Time フシフ	Re	Ceive L/	d by:	(Signa	ature).	nt	RA							Date 0 - 3-	11 -	Tim J: (j	
Relinquished by: (Signa	iture)					/ - /	Re	ceive	d by:	(Signa	ature)	<i></i> -	<u></u> ~				_						
Relinquished by: (Signa	iture)						Re	ceive	d by:	(Signa	iture)							<u></u>					
						env														•			
				(F)		And	alyi	ical	Lat	ora	tory												

5796 US Highway 64 • Farmington, NM 87401 • 505-632-0615 • lab@envirotech-inc com

						Liner	Leak detection		Pit	Comments / Repairs needed
Date	WellName	Run	Formation	Construction		Banded Plastic liner,	Y/N	level	level	
2008	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Bottom Plastic Liner	N			Dirt work repair to location needs to be
9/19/2008	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Bottom Plastic Liner	N		_	
10/20/2008	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	NO			
12/30/2008	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		27"_	ОК
1/14/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		44"	
2/17/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		27"	
3/17/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		27"	
4/30/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		29	
5/26/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		32	
6/30/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		16	
8/28/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		35	
9/1/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		9	
12/31/2009	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		13	
1/19/2010	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		22	
2/18/2010	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		32	
3/18/2010	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No		38	

•

4/27/2010	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No	22	
	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No	17	
7/22/2010	ROSA UNIT #100B	04-63	Mesa Verde	STEEL	SGT	Yes	No	26	

211/2