District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office. () For permanent pits, and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District of the submit of the submi

2354

Proposed Alternative Method Permit or Closure Plan Application

Type of action: Existing BGT

Form C-144

Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit

Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system,

below-grade tank, or proposed alternative method

Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request

Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

Operator: XTO Energy, Inc.	OGRID #:	5380
Address: #382 County Road 3100, Aztec, NM 87410		
Facility or well name:AZTEC COM 4 #1E	<u></u>	
API Number: 30-045-30273 OCD Permit Nu	mber:	
U/L or Qtr/QtrMSection16Township30NRange	_11 <u>W</u> County:	San Juan
Center of Proposed Design: Latitude 36.80778 Longitude 108.00	222	_ NAD: □1927 □ 198 3
Surface Owner: Federal State Private Tribal Trust or Indian Allotment		NAD: ☐1927 ☐ 1982 ☐ 12 3 4 5 6 > 6 3
Pit: Subsection F or G of 19.15.17.11 NMAC Temporary: Drilling Workover Permanent Emergency Cavitation P&A Lined Unlined Liner type: Thickness mil LLDPE HDPE String-Reinforced Liner Seams: Welded Factory Other Volume:		PECEIVED NOV 2011 NOV
Closed-loop System: Subsection H of 19.15.17.11 NMAC Type of Operation: P&A Drilling a new well Workover or Drilling (Applies intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other Lined Unlined Liner type: Thickness mil LLDPE HD Liner Seams: Welded Factory Other		quire prior approval of a permit or notice of
4.	s, vaulted, automatic	high-level shut off, no liner
s. Alternative Method: Submittal of an exception request is required. Exceptions must be submitted to the Sant	a Fe Environmental E	Bureau office for consideration of approval.

Oil Conservation Division

Page 1 of 5

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify Four foot height, steel mesh field fence (hogwire) with pipe top railing	hospital,
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Expanded metal or solid vaulted top Monthly inspections (If netting or screening is not physically feasible)	
8. Signs: Subsection C of 19.15.17.11 NMAC ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers ☐ Signed in compliance with 19.15.3.103 NMAC	
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15 17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	office for
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accept material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying above-grade tanks associated with a closed-loop system.	priate district pproval.
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☒ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	⊠ Yes □ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☑ No ☐ NA
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☑ NA
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes 🏻 No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	⊠ Yes □ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☑ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☑ No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	☐ Yes ⊠ No
Within a 100-year floodplain FEMA map	☐ Yes ☑ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:	
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: Previously Approved Operating and Maintenance Plan API Number: (Applies only to closed-loop system that use above ground steel tanks or haul-off bins and propose to implement waste removal for closure)	
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems)	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. ☐ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC ☐ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC ☐ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) ☐ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC ☐ Re-vegetation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC	

Waste Removal Closure For Closed-loop Systems That Utilize Above Ground S Instructions: Please indentify the facility or facilities for the disposal of liquids, a facilities are required.		
•	Disposal Facility Permit Number:	
	Disposal Facility Permit Number:	
Will any of the proposed closed-loop system operations and associated activities occurring. Yes (If yes, please provide the information below) \(\sigma\) No		
Required for impacted areas which will not be used for future service and operation Soil Backfill and Cover Design Specifications based upon the appropriate Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection	requirements of Subsection H of 19.15.17.13 NMAC of 19.15.17.13 NMAC	
17. Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the considered below. Requests regarding changes to certain siting criteria may require considered an exception which must be submitted to the Santa Fe Environmental demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for	administrative approval from the appropriate distr Bureau office for consideration of approval. Justij	ict office or may be
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data	obtained from nearby wells	Yes No
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data	obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data	obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other sign lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	ificant watercourse or lakebed, sinkhole, or playa	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church - Visual inspection (certification) of the proposed site; Aerial photo; Satellite		☐ Yes ☐ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less watering purposes, or within 1000 horizontal feet of any other fresh water well or sp. NM Office of the State Engineer - iWATERS database; Visual inspection (e.g., 1900).	oring, in existence at the time of initial application.	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approve	•	Yes No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visua	I inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining	and Mineral Division	☐ Yes ☐ No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology Society; Topographic map 	& Mineral Resources; USGS; NM Geological	☐ Yes ☐ No
Within a 100-year floodplain FEMA map		Yes No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Construction/Design Plan of Temporary Pit (for in-place burial of a drying part of Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of United Sampling Plan - based upon the appropriate requirements of Disposal Facility Name and Permit Number (for liquids, drilling fluids and described Soil Cover Design - based upon the appropriate requirements of Subsection Re-vegetation Plan - based upon the appropriate requirements of Subsection Site Reclamation Plan - based upon the appropriate requirements of Subsection	prirements of 19.15.17.10 NMAC Subsection F of 19.15.17.13 NMAC propriate requirements of 19.15.17.11 NMAC ad) - based upon the appropriate requirements of 19.15.17.13 NMAC uirements of Subsection F of 19.15.17.13 NMAC Subsection F of 19.15.17.13 NMAC rill cuttings or in case on-site closure standards cannot for 19.15.17.13 NMAC Tof 19.15.17.13 NMAC	15.17.11 NMAC

19. Operator Application Certification:		
I hereby certify that the information submitted with this application is true, accu	rate and complete to the	e best of my knowledge and belief.
Name (Print): Kim Champlin	Title:	Environmental Representative
Signature: Kim (hamplin	Date:	11.21.08
e-mail address: kim_champlin@xtoenergy.com		(505) 333-3100
20,		
OCD Approval: Permit Application (including closure plan) Closure	Van (only)	Conflitions (see attachment)
OCD Representative Signature:	pad III	2023/2012 11 (O) 12-11
Title: Environmental Environmental	OCD Permit Numb	er:
Closure Report (required within 60 days of closure completion): Subsection Instructions: Operators are required to obtain an approved closure plan prior The closure report is required to be submitted to the division within 60 days of section of the form until an approved closure plan has been obtained and the complete the comple	to implementing any c the completion of the c losure activities have b	losure activities and submitting the closure report. losure activities. Please do not complete this
2. Cl.4		
Closure Method: N Waste Excavation and Removal ☐ On-Site Closure Method ☐ Altern ☐ If different from approved plan, please explain.	ative Closure Method	☐ Waste Removal (Closed-loop systems only)
23. Closure Report Regarding Waste Removal Closure For Closed-loop System Instructions: Please indentify the facility or facilities for where the liquids, dri two facilities were utilized.		
Disposal Facility Name:	Disposal Facility Per	rmit Number:
Disposal Facility Name:	Disposal Facility Per	
Were the closed-loop system operations and associated activities performed on o Yes (If yes, please demonstrate compliance to the items below) No	r in areas that will not b	e used for future service and operations?
Required for impacted areas which will not be used for future service and operated Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	ions ·	
Closure Report Attachment Checklist: Instructions: Each of the following is mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits)	tems must be attached	to the closure report. Please indicate, by a check
☐ Confirmation Sampling Analytical Results (if applicable) ☐ Waste Material Sampling Analytical Results (required for on-site closure)		
 ✓ Disposal Facility Name and Permit Number ✓ Soil Backfilling and Cover Installation 		(
Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation)		
On-site Closure Location: LatitudeLongi	tude	NAD: □1927 □ 1983
Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure belief. I also certify that the closure complies with all applicable closure requires Name (Print): Name (Print): Ames McDanie CHMM #156	report is true, accurate a ments and conditions sp 276 Title: ENG	pecified in the approved closure plan.
Signature:	Date:	3/11
e-mail address: James M. Daniel Oxtoenergy.com	ATARADONA	505-333-3701
Form C-144 Oil Conservation	Sh Division MAN 16, 2016	Page 5 of 5

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003
Submit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company: XTO Energy, Inc. Contact: James McDaniel Address: 382 Road 3100, Aztec, New Mexico 87410 Telephone No.: (505) 333-3701 Facility Name: Aztec COM 4 #1E (30-045-30273) Facility Type: Gas Well (Dakota) Surface Owner: Private Mineral Owner: Lease No.: Fee LOCATION OF RELEASE Unit Letter North/South Line Section Township Range Feet from the Feet from the East/West Line County 30N 11W 1050 **FWL** M 16 FSL. San Juan Latitude: 36.80770 Longitude: -108.00222 NATURE OF RELEASE Type of Release: Produced Water Volume of Release: unknown Volume Recovered: None Source of Release: Below Grade Tank Date and Hour of Occurrence: Date and Hour of Discovery: NA Unknown Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No ☒ Not Required By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully * Describe Cause of Problem and Remedial Action Taken.* The below grade tank was moved at the Aztec COM 4 #1E well site due to maintenance upgrades at the facility. The BGT was closed and brought above grade. The BGT cellar beneath the BGT was sampled for TPH via USEPA Method 8015 and 418.1, for BTEX via USEPA Method 8021, and for total chlorides. The sample returned results below the 'pit rule' standards of 0.2 ppm benzene, 10 ppm total BTEX and 250 ppm chlorides, but above the 100 ppm TPH standard at 210 ppm via USEPA Method 418.1, confirming that a release had occurred. Describe Area Affected and Cleanup Action Taken.* A release has been confirmed for this location. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations OIL CONSERVATION DIVISION Signature: 4 Approved by District Supervisor: Printed Namé: James McDaniel, CHMM #15676 Title: EH&S Supervisor Approval Date: Expiration Date: E-mail Address: James McDaniel@xtoenergy.com Conditions of Approval: Attached

Phone: 505-333-3701

Date: 11/2/2011

* Attach Additional

XTO Energy Inc. San Juan Basin Below Grade Tank Closure Report

Lease Name: Aztec COM 4 #1E API No.: 30-045-30273

Description: Unit M, Section 16, Township 30N, Range 11W, San Juan County

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure requirements of below-grade tanks on XTO Energy Inc. (XTO) locations. This is XTO's standard procedure for all below-grade tanks. A separate plan will be submitted for any below-grade tank which does not conform to this plan.

General Plan

1. XTO will close below-grade tanks within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the division requires because of imminent danger to fresh water, public health or the environment.

Closure Date is October 19, 2011

- 2. XTO will close a below-grade tank that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofitted to comply with Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC.
 - Closure Date is October 19, 2011
- 3. XTO will close a permitted below-grade tank within 60 days of cessation of the below-grade tank's operation or as required by the transitional provisions of Subsection B of 19.15.17.17 NMAC in accordance with a closure plan that the appropriate division district office approves. The closure report will be filed on form C-144.

Required C-144 Form is attached to this document.

4. XTO will remove liquids and sludge from below-grade tanks prior to implementing a closure method and will dispose of the liquids and sludge in a division-approved facility. Approved facilities and waste streams include:

Envirotech Permit No. NM01-0011 and IEI Permit No. NM 01-0010B

Soil contaminated by exempt petroleum hydrocarbons

Produced sand, pit sludge and contaminated bottoms from storage of exempt wastes

Basin Disposal Permit No. NM01-005 Produced water

All liquids and sludge were removed from the tank prior to closure activities.

5. XTO will remove the below-grade tank and dispose of it in a division approved facility or recycle, reuse, or reclaim it in a manner that the appropriate division district office approves.

XTO has removed the below grade tank, inspected it for integrity, and will reuse the tank at this location.

6. XTO will remove any on-site equipment associated with a below-grade tank unless the equipment is required for some other purpose.

All equipment will remain on location for the continued production of oil and gas.

7. XTO will test the soils beneath the below-grade tank to determine whether a release has occurred. At a minimum 5 point composite sample will be collected along with individual grab samples from any area that is wet, discolored or showing other evidence of a release. Samples will be analyzed for BTEX, TPH and chlorides to demonstrate that the benzene concentration, as determined by EPA SW-846 methods 8021B or 8260B or EPA method that the division approves, does not exceed 0.2 mg/kg; total BTEX concentration, as determined by EPA SW-846 methods 8021B or 8260B or other EPA method that the division approves, does not exceed 50 mg/kg; the TPH concentration, as determined by EPA method 418.1 or other EPA method that the division approves, does not exceed 100mg/kg; and the chloride concentration, as determined by EPA method 300.1 or other EPA method that the division approves, does not exceed 250 mg/kg, or the background concentration, whichever is greater. XTO will notify the division of its results on form C-141.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Test Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	< 0.05 mg/kg
BTEX	EPA SW-846 8021B or 8260B	50	< 0.25 mg/kg
TPH	EPA SW-846 418.1	100	210 mg/kg
Chlorides	EPA 300.1	250 or background	27 mg/kg

8. If XTO or the division determines that a release has occurred, XTO will comply with 19.15.3.116 NMAC and 19.15.1.19NMAC as appropriate.

Based on TPH results of 210 ppm via USEPA Method 418.1, a release has been confirmed for this location. All remediation activities are outlined in the attached Final C-141 Release Notification and Corrective Action form.

9. If the sampling program demonstrates that a release has not occurred or that any release does not exceed the concentrations specified in Paragraph (4) of Subsection E of 19.15.17.13 NMAC, XTO will backfill the excavation with compacted, non-waste containing, earthen material; construct a division prescribed soil cover; recontour and re-vegetate the site.

The pit cellar was backfilled using compacted, non-waste containing earthen material, with a division prescribed soil cover.

10. Notice of Closure operations will be given to the Aztec Division District III office between 72 hours and one week prior to the start of closure activities via email or verbally.

The notification will include the following:

- i. Operator's name
- ii. Well Name and API Number
- iii. Location by Unit Letter, Section, Township, and Range

Notification was provided to Mr. Brandon Powell with the Aztec office of the OCD via email on October 12, 2011; see attached email printout.

The surface owner shall be notified of XTO's proposal to close the BGT as per the approved closure plan using certified mail, return receipt requested.

The surface owner was notified on October 14, 2011; see attached letter and return receipt.

11. Re-contouring of location will match fit, shape, line, form and texture of the surrounding area. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be placed in areas where needed to prevent erosion on a large scale. Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The location has been recontoured to match the above specifications.

12. A minimum of 4 feet of cover shall be achieved and the cover shall include 1 foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

The site has been backfilled to match these specifications.

13. XTO will seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will be used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

The location will be reclaimed pursuant to the surface use agreement upon the plugging and abandoning of this well location.

- 14. All closure activities will include proper documentation and be available for review upon request and will be submitted in closure report form to OCD within 60 days of closure of the below-grade tank. Closure report will be filed on form C-144 and incorporate the following:
 - i. Proof of closure notice to division and surface owner; attached
 - ii. Details on capping and covering, where applicable; per OCD Specifications
 - iii. Inspection reports; attached
 - iv. Confirmation sampling analytical results; attached
 - v. Disposal facility name(s) and permit number(s); see above
 - vi. Soil backfilling and cover installation; per OCD Specifications
 - vii. Re-vegetation application rates and seeding techniques, (or approved alternative to re-vegetation requirements if applicable); **NA**
 - viii. Photo documentation of the site reclamation. attached



COVER LETTER

Thursday, October 20, 2011

James McDaniel XTO Energy 382 County Road 3100 Aztec, NM 87410

TEL: (505) 333-3100 FAX (505) 333-3280

RE: Aztec Com 4 IE

Dear James McDaniel:

Order No.: 1110745

Hall Environmental Analysis Laboratory, Inc. received 1 sample(s) on 10/14/2011 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. Below is a list of our accreditations. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. All samples are reported as received unless otherwise indicated.

Please do not hesitate to contact HEAL for any additional information or clarifications.

Sincerely,

Andy Freeman, Laboratory Manager

NM Lab # NM9425 NM0901

AZ license # AZ0682

Andy Freeman

Laboratory Manager

Hall Environmental Analysis Laboratory, Inc.

Date: 20-Oct-11 Analytical Report

CLIENT:

XTO Energy

Lab Order:

1110745

Client Sample ID: BGT Closure

Collection Date: 10/13/2011 10:23:00 AM

Project:

Aztec Com 4 IE

Date Received: 10/14/2011

Lab ID:

1110745-01

Matrix: SOIL

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed
EPA METHOD 8015B: DIESEL RANG	GE ORGANICS					Analyst: JB
Diesel Range Organics (DRO)	1600	100		mg/Kg	10	10/14/2011 1:52:30 PM
Surr: DNOP	. 0	73.4-123	S	%REC	10	10/14/2011 1.52:30 PM
EPA METHOD 8015B: GASOLINE RA	ANGE					Analyst: RAA
Gasoline Range Organics (GRO)	ND	5.0		mg/Kg	1	10/14/2011 12:10:25 PM
Surr: BFB	103	75.2-136		%REC	1	10/14/2011 12:10:25 PM
EPA METHOD 8021B: VOLATILES						Analyst: RAA
Benzene	ND	0.050		mg/Kg	1	10/14/2011 12:10:25 PM
Toluene	ND	0.050		mg/Kg	1	10/14/2011 12:10:25 PM
Ethylbenzene	ND	0.050		mg/Kg	1	10/14/2011 12:10:25 PM
Xylenes, Total	ND	0.10		mg/Kg	1	10/14/2011 12:10:25 PM
Surr: 4-Bromofluorobenzene	96.5	80-120		%REC	1	10/14/2011 12:10:25 PM
EPA METHOD 300.0: ANIONS						Analyst: SRM
Chloride	27	7.5		mg/Kg	5	10/14/2011 2:42:50 PM
EPA METHOD 418.1; TPH						Analyst: LRW
Petroleum Hydrocarbons, TR	210	19		mg/Kg	1	10/14/2011

Qualifiers:

- Value exceeds Maximum Contaminant Level
- Estimated value E
- Analyte detected below quantitation limits
- NC Non-Chlorinated
- PQL Practical Quantitation Limit

- Analyte detected in the associated Method Blank В
- Н Holding times for preparation or analysis exceeded
- MCL Maximum Contaminant Level
- ND Not Detected at the Reporting Limit
- Spike recovery outside accepted recovery limits

Date: 20-Oct-11

QA/QC SUMMARY REPORT

Client:

XTO Energy

Project:

Aztec Com 4 IE

Work Order:

1110745

Analyte	Result	Units	PQL	SPK Va	SPK ref	%Rec L	owLimit His	ghLimit %RPD	RPDLimit Qual
Method: EPA Method 300.0: An	nions								
Sample ID: 1110745-01BMSD		MSD				Batch ID:	28904	Analysis Date:	10/14/2011 3:52:28 PM
Chloride Sample ID: MB-28904	38.31	mg/Kg <i>MBLK</i>	7.5	15	26.91	76.0 Batch ID:	79.6 28904	112 8.66 Analysis Date:	20 S 10/14/2011 2:08:00 PM
Chloride Sample ID: LCS-28904	ND	mg/Kg <i>LCS</i>	1.5			Batch ID:	28904	Analysis Date:	10/14/2011 2:25:25 PM
Chloride Sample ID: 1110745-01BMS	14.22	mg/Kg <i>MS</i>	1.5	15	0	94.8 Batch ID:	90 28904	110 Analysis Date.	10/14/2011 3:35:03 PM
Chloride	41.77	mg/Kg	7.5	15	26.91	99.1	79.6	112	
Method: EPA Method 418.1: TP	 РН								
Sample ID: MB-28900		MBLK				Batch ID:	28900	Analysis Date:	10/14/2011
Petroleum Hydrocarbons, TR Sample ID: LCS-28900	ND	mg/Kg LCS	20			Batch ID:	28900	Analysis Date:	10/14/2011
Petroleum Hydrocarbons, TR Sample ID: LCSD-28900	98.20	mg/Kg LCSD	20	100	8	90 2 Batch ID:	87.8 28900	115 Analysis Date:	10/14/2011
Petroleum Hydrocarbons, TR	100.8	mg/Kg	20	100	8	92.8	87.8	115 2.61	8.04
Method: EPA Method 8015B: D	iesel Range	Organics							
Sample ID: MB-28901		MBLK				Batch ID:	28901	Analysis Date.	10/14/2011 10:57:19 AM
Diesel Range Organics (DRO) Sample ID: LCS-28901	ND	mg/Kg LCS	10			Batch ID:	28901	Analysis Date:	10/14/2011 11:32:16 AM
Diesel Range Organics (DRO)	55.57	mg/Kg	10	50	0	111	66.7	119	

Qualifiers:

E Estimated value

J Analyte detected below quantitation limits

ND Not Detected at the Reporting Limit

H Holding times for preparation or analysis exceeded

NC Non-Chlorinated

R RPD outside accepted recovery limits

Page 1

Hall Environmental Analysis Laboratory, Inc.

Sample Receipt Checklist

Client Name XTO ENERGY			1	Date Receive	d:	10/14/2011
Work Order Number 1110745				Received by	: AT	
Checklist completed by: Signature Checklist	h	C	/ <i>5/1</i> Date	Sample ID la	ibels checked by	r. Amiliars
Matrix:	Carrier name:	FedEx				
Shipping container/cooler in good condition?		Yes 🗹		No 🗌	Not Present	
Custody seals intact on shipping container/coole	r?	Yes 🗹		No 🗀	Not Present (Not Shipped
Custody seals intact on sample bottles?		Yes 🗹		No 🗆	N/A [
Chain of custody present?		Yes 🗹		No 🗆		
Chain of custody signed when relinquished and i	received?	Yes 🗹		No 🗀		
Chain of custody agrees with sample labels?		Yes 🗹		No 🗆		
Samples in proper container/bottle?		Yeş 🗹		No 🗆		
Sample containers intact?		Yes 🗹		No 🗌		
Sufficient sample volume for Indicated test?		Yes 🗹		No 🗆		
All samples received within holding time?		Yes 🗹		No 🗆		Number of preserved bottles checked for
Water - VOA vials have zero headspace?	No VOA vials subn	nitted 🗹	•	Yes 🗌	No 🗆	pH:
Water - Preservation labels on bottle and cap ma	atch?	Yes 🗌		No 🗌	N/A 🗹	
Water - pH acceptable upon receipt?		Yes 🗌		No 🗌	N/A 🗹	<2 >12 unless noted below.
Container/Temp Blank temperature?		2.0°		° C Acceptab		33,011.
COMMENTS:			It (given sufficient	t time to cool.	
=======================================	=====	= ==	==	====	== ==	
Client contacted	Date contacted:			Pers	on contacted	
Contacted by:	Regarding.	-				
Comments:				••••••••		
			****	····		
Corrective Action						

C	hain-	-of-Cι	istoc	ly Record	Turn-Around	Time:	- 10/1	4-								NI SA			ni s	A E	BIT	-41	
Client:	TX	0			Turn-Around Time: - 10/14 - 5cme □ Standard Rush Project Name:																	TAL DR	
													ww	w.hal	llenv	i r onr	nent	al.co	om				
Mailing Address: 382 7000 3100 AZTEL Con 4					AZTEL Con 4 1E					49	01 H	lawk	ins 1	۷E -	Alb	uque	erqu	e, NI	M 87	′109			
		·			Project #:					Τe	el. 50)5-34	45-3	975	F	ax :	505-	345-	4107	7			
		5-78		5/9	BLT	CLOSUPE			19												1	S A W	建 (注)
email o	r Fax#: \	emes.	wd	an iela Non enem	Project Mana	ger:					_												
QA/QC	Package:	-11-03		an i elle 水力 energ へい el 4 (Full Validation)	9sm	es McI	Jan Er	- -	TMB's (8021)	+ TPH (Gas only)	as/Dies					OS' [†] Oc	PCB's						-
Accred				or r (r un r undanon)	_1_				/B's) H	Ö					02,1	982			. [l		
□ NEL		□ Othe	er		Sampler: Bi	Aryes-	T- (1- (1) (1)		É	T	15B	8.1	14.1	AH)		Ň.,	787		7	J			Z Z
	(Type)				Sample Tem	perature	70		发	3E 4	80	d 41	d 5(r P,	als	S,	des		0	Ŵ			ح ا
Date	Time	Matrix	Sar	mple Request ID		Preservative Type			BTEX + MTBE	BTEX + MTBE	TPH Method 8015B (Gas/Diesel)	TPH (Method 418.1)	EDB (Method 504.1)	8310 (PNA or PAH)	RCRA 8 Metals	Anions (F,CI,NO3,NO2,PO4,SO4)	8081 Pesticides / 8082	8260B (VOA)	8270 (Semi-VOA)	CHLORIDES			Air Bubbles (Y or N)
10/13	0906	Sou	BLIT	Cosifé	2 402	Cool	- And Control	-1	X		χ									X		\top	
<u> </u>			<u>""</u>	-0,51 -							-	-									\neg	\top	
							 		-					<u> </u>						\vdash	\dashv	+	+
			ļ						-											┟╼┤	_	_+	_ _
							<u> </u>														_		
														l						i		ĺ	
									-												1	+	
			ļ <u>.</u>						-	├										\vdash		-	
			 		 								-	-						\vdash		+	
							 														\dashv		
			<u> </u>						_						<u> </u>						\dashv	\perp	
			<u> </u>		<u> </u>	<u></u>	<u> </u>		<u> </u>		L												
Date:	Time:	Relinquish	ed by:		Received by:		Date ≀o∕ i	Time	Rer	nark	s:												
10/13	1200	Be	6/1	yr_	Mistre	Malter	113/11	1200															i
Date:	Time:	Relinquish	ea by: *		Received by	()	Dáte /0/14//	Time															
9/13/11	1360	1/hr	ute	e Waller	1////	u SL		<u> 1000 </u>	L														
i	f necessary,	samples sub	mitted to H	lali Environmental may be sub	contracted to other a	ccredited laboratori	es. This serve	s as notice of this	possi	bility.	Any sı	n∞-dı	tracte	d data	will be	dearl	y nota	ted on	the ar	nalytica	al repor	t.	



James McDaniel /FAR/CTOC

10/12/2011-04:34:PM

To brandon.powell@state.nm.us-

CC

bcc.

Subject BGT Closure Aztec COM 4#1E

Brandon.

Please accept this email as the required notification for BGT closure activities at the Aztec COM 4 #1E: well site (30-045-30273) located in Unit M, Section 16; Township 30N, range 11W; San Juan County, New Mexico. This BGT is being closed due to location maintenance. Thanks very much for your time in regards to this matter.



James McDaniel, CHMM #15676

EH&S Supervisor XTO Energy, Inc. onice#505333-3701

Cell # 505-787-0519 James Mcdanlel oxtoenergy.com



October 13, 2011.

Sam Blue Trust PO Box 176 Aztec, New Mexico 87410

Re:

Aztec COM 4 #1E - API # 30-045-30273

Unit M, Section 16, Township 30N, Range 11W, San Juan County, New Mexico

Dear Sir,

This submittal is pursuant to Rule 19.15.17.13 requiring operators to notify surface owners of the closure of a below grade tank pit. XTO Energy, Inc. (XTO) is hereby providing written documentation of our proposal to close the below grade tank pit associated with the above mentioned well site by excavation and removal.

Should you have questions or require additional information, please feel free to contact me at your convenience at (505) 333-3100. Thank you for your time in regards to this matter.

Respectfully Submitted,

James McDaniel, CHMM #15676

EH&S Supervisor XTO Energy, Inc. San Juan Division

a: 	Domestic Man City)
	For delivery information visit our website at www.usps.como
ם ה ה ני	Certified Fee Postmatic
C (Restricted Delivery Fee (Endorsement Required)
; (Sent To Sum Blue Trust Siried, Apt. No.; p. 0 Box 176 Total Box No. p. 0 Box 176 Total State ZiP14 Arth. NM 8 7410
	PS Form 3800. August 2006 See Reverse for Instructions
:	

SENDER: COMPLETE THIS SECTION	ON	COMPLETE THIS SECTION	ON DELIVERY	144.6
 Complete items 1, 2, and 3. Also ditem 4 if Restricted Delivery is des Print your name and address on the so that we can return the card to your attach this card to the back of the or on the front if space permits. Article Addressed to: Sam Blw Trust P.O. Box 17k Article, Nm 87910 	ired. ne reverse /ou. mailpiece,	3. Service Type Certified Mail	triom item, 17	ressee
Article Number (Transfer from service label)	7010 1870	0003 3184 0	539	-@~

XTO Energy, Inc. Aztec COM 4 #1E Section 16, Township 30N, Range 11W Closure Date: 10/19/2011



Photo 1: Aztec COM 4 #1E after backfill (View 1)




Photo 2: Aztec COM 4 #1E after backfill (View 2)



Well Below Tank Inspection Report

RouteName	StopName	Pumper	Foreman	WellName		APIWellNumber		Section	Range	Township	
FAR NM Run 54A	AZTEC COM 4 001E	Breadmont, Tony	Steiner, Geoffrey	AZTEC COM 04 01E			3004530273		16	11W	30N
InspectorName Inspection	n Inspection Visible Time LinerTeal	VisibleTankLeak s Overflow	Collection OfSurfaceRun	Visible LayerOil		Freeboard EstFT	PitLocation	PıtType	Notes		
j rodgers 11/18/20	08 03:00 N o	No	No	No	No	6	Well Water Pit	Below Ground	new pit	new tan	ks jr.
j rodgers 12/31/20	08 03:00 No	No	No	No	No	6	Well Water Pit	Below Ground	new pit	new tan	ks jr
j rodgers 02/21/20	09 08.30 N o	No	No	No	No ,	6	Well Water Pit	Below Ground	new pit	new tan	ks jr.
j rodgers 04/23/20	09 01 [.] 45 N o	No	No	No	No	6	Well Water Pit	Below Ground	new pit	new tani	ks jr.
j rodgers 07/27/20	09 02 35 N o	No	No	No	No	6	Well Water Pit	Below Ground	new pit	new tan	ks jr.
j rodgers 08/25/20	09 09.45 N o	No	No	No	No	6	Well Water Pit	Below Ground	new pit	new tan	ks jr.
j rodgers 09/30/20	09 02 45 No	No	No	No	No	6	Well Water Pit	Below Ground	new pit	new tanl	ks jr.
j rodgers 11/27/20	09 08 [.] 00 N o	No	No	No	No	6	Well Water Pit	Below Ground	new pit	new tanl	ks jr.
j rodgers 02/07/20	10 10.08 N o	No	Yes	No	No	6	Well Water Pit	Below Ground	6' snow o	on loc. jr	•
j rodgers 03/22/20	10 10 [.] 44 N o	No	No	No	No	6	Well Water Pit	Below Ground	dry		
j rodgers 04/06/20	10 12 [.] 20 No	No	No	No	No	5	Well Water Pit	Below Ground	dry		
j rodgers 05/19/20	10 07:51 No	No	No	No	No	5	Well Water Pit	Below Ground	dry		
j rodgers 06/28/20	10 10:13 No	No	No	No	No	5	Well Water Pit	Below Ground	dry		
j rodgers 07/28/20	10 12:55 No	No	No	No	No	5	Well Water Pit	Below Ground	dry		
j rodgers 08/09/20	10 08:12 No	No	No	No	No	5	Well Water Pit	Below Ground	dry		
j rodgers 10/06/20	10 08:12 N o	No	No	No	No	5	Well Water Pit	Below Ground	dry		
j rodgers 11/03/20	10 07·12 N o	No	No	No	No	5	Well Water Pit	Below Ground	dry		