



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-3-11 Operator Conoco Phillips API #30-0 39-24807
Property Name San Juan 29-664 S10D Well No. 301 Location: Unit Section 2 Township 29 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 360 Intermediate 0 Casing 3.8 Bradenhead 138

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min	0	0	4	0	52
10 min	0	0	4.3		
15 min	0	0	4.7		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	☒	
Surges		
Down to Nothing		☒
Nothing		
Gas	☒	DIST. 3
Gas & Water		OIL CONS. DIV.
Water		RCVD AUG 3 '11

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1.4 INTERMEDIATE

REMARKS: BH Hard blow first 5 seconds to Med. blow to light
blow at 5 minutes - light - little whisper at 15.
Retest in 6 months. (January 2012) Gas analysis.

By David Aguirre Witness Monica Kuchling

(Position)

E-mail address

Int. bleed in 3 seconds