



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-11-11 Operator ConocoPhillips API #30-0 39-29751

Property Name San Juan 29664 Well No. 8M Location: Unit Section 1 Township 29 Range 6

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 135 Intermediate 211 Casing 142 Bradenhead 79

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges


Down to Nothing

Nothing

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

BH 8 seconds to blowdown
does it suggest well head leak 118 in 30 minutes
pumper blowing down then well call for test

By

Witness

(Position)

E-mail address