





Schematic Regulatory
SAN JUAN 29-6 UNIT #60M

District NORTH	Field Name MV/DK COM	County RIO ARRIBA	State/Province NEW MEXICO	API / UWI 3003930497	
Original Spud Date 4/21/2008	Surface Legal Location 018-029N-006W-F	East/West Distance (ft) 1,920.00	East/West Reference FWL	North/South Distance (ft) 2,170.00	North/South Reference FNL

Well Config: DEVIATED - Original Hole, 8/25/2011 7 12 00 AM



**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/23/2011 Operator ConocoPhillips API # 3003930497
Property Name SAN JUAN 29-6 UNIT Well No. 60M Location: Unit F Section 18 Township 029N Range 006W
Well Status Flowing Initial PSI: Tubing 179 Intermediate 179 Casing 179 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	BRADENHEAD			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	179	180	15	180
10 min	0	179	180	2	180
15 min	0	179	180	3	181
20 min				2	181
25 min				2	181
30 min				1	181

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	Y
Nothing	
Gas	
Gas & Water	
Water	



If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE Bradenhead 0 Intermediate 139

REMARKS:

Puff on BH. INT had hard blow first 8 seconds to meduim blow first 20 minutes softer blow last 10 minutes

Tested By hemphsk Witness Monica Kuehling