


NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)



Date of Test 11/07/2011 Operator Burlington API # 30-045-30468

Property Name Cooper Well # 2R Location: Unit M Sec 7 Twn 29 Rge 11

Land Type:

State _____
Federal ☒
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: 11/07/2016

Casing Pres. 0
Crownhead Pres. 0
Tubing Pres. NA
Int. Casing Pres. NA

Tbg. SI Pres. _____ Max. Inj. Pres. _____
Tbg. Inj. Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: Tubing is out of hole. Patch Bridge plug set at 1772 ft. top perf 1822 ft.
Pressured to 560 psi, 5 min & dropped to 520 psi, Bumped back to 560 psi, 2nd 5 min - 545 psi, OBT,
10 min 539 psi BHO, 15 min 529 psi OBT 20 min 540 BHO, 25 min 540 psi BHO
30 min 541 psi BHO

By [Signature] (Operator Representative)

Witness [Signature] (NMOCD)

(Position)

Revised 02-11-02