



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX. (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3ddistrict.htm](http://emnr.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-17-11 Operator DS Simmons API #30-0 45 29980

Property Name LV Hamner Well No. B1B Location: Unit ___ Section 21 Township 29N Range 9W

Well Status (Shut-In or Producing) Initial PSI: Tubing 16 Intermediate 455 Casing 42 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>455</u>	<u>42</u>	<u>455</u>	<u>42</u>
10 min	<u>0</u>	<u>455</u>	<u>42</u>	<u>455</u>	<u>42</u>
15 min	<u>0</u>	<u>455</u>	<u>42</u>	<u>455</u>	<u>42</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>X</u>
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	<u>X</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 3

REMARKS: Intermediate - Steady flow low Volume

By Scott Elmen
Field Tech.
(Position)

Witness _____

E-mail address _____

