## RECEIVED

DEC 19 2011

Form 3160-5 / (February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Farmington Field Office OMB No 1004-0137
Bureau of Land Managemer. Expires March 31, 2007

SUNDRY NOTICES AND	5. Lease Serial No. SF-078766						
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No. Rosa Unit				
1 Type of Well	8. Well Name and No.						
Oil Well Gas Well	Rosa Unit #79B						
Name of Operator     Williams Production Company, LLC	9. API Well No 30-039-26920						
3a. Address PO Box 640 Aztec, NM 87410	de area code)	10 Field and Pool or Exploratory Area Blanco Mesaverde/Basin Dakota					
4. Location of Well (Footage, Sec., T.,R.,M., or Surve 975' FNL & 2600' FWL, Section 22, T31N, R6W	505-333-1806 y Description)		11. Country or Parish, State Rio Arriba, NM				
12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent  Acidize  Alter Casing	Deepen Fracture Treat New Construct	Production (Sta	Well Integrity				
Subsequent Report  Casing Repair Change Plans	Other <u>Commingle</u>						
Final Abandonment Notice Convert to Injection	Plug Back Water Disposal						
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)  10/24/11 – MIRU Hurricane #6							
10/25/11 – POOH 178 jts of 2-1/16" IJ 3.25#	J-55 Tbg (MV Strin	g). Pull on long (DK) strir	ng, did not come free.				
10/26/11 - RIH w/ chemical cutting tool. Cut	tbg 6' Above Packe	r @ 5948'. TOH 182 jts o	f 2-1/16" tbg (DK). OIL CONS. [	MV.			
10/27/11 thru 10/28/11 - TIH with jars and o	vershot tool. Set Jar	s, TOH with 6' jt which ca	ime out of seal assembly DIST. 3	i 1			
10/31/11 – Jar on fish. TOH with remaining 58 jts of 2-1/16" tbg (DK).							
14. I hereby certify that the foregoing is true and correct.  Name ( <i>Printed/Typed</i> )  Ben Mitchell		Title Regulatory Specialist					
Signature & MM	Date 12/19/11						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by							
Conditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

(Instructions on page 2)

ASSEPTED FOR RECORD

NMOCD A

DEC 2 0 2011

## Rosa Unit 79B Continued

11/1/11 thru 11/2/11 - Mill on packer @ 5950'. Tried to move packer, moved up to 5930'. Mill on packer @ 5930'. TOH packer became stuck. Lost packer off tbg. Spear broke on the bottom piece of threads, Left 200 Series Spear & 2.688" Grapple in hole.

11/3/11 - TIH and mill packer at 5875'. Packer fell free. Clean out well.

11/4/11 - Tagged packer at 7912', milled 2'.

11/7/11 - TIH with overshot. Tag packer at 7912'. Get overshot on packer. POH with paker in overshot.

11/8/11 - Clean out well to 7943'

11/9/11 – Land well at 7847' as follows bottom up: 1/2 M/S expandable check, one Jt of 2-3/8" 4.70# J-55 8RD EUE, 1.78" Seat Nipple, 244 Jts of 2-3/8" 4.70# J-55 8RD EUE, Seat Nipple @ 7814', (245 Total Jts). RDMO Hurricane #6.

## ROSA UNIT #79B BLANCO MV/BASIN DK

**Location:** 975' FNL, 2600' FWL NE/4 NW/4 Section 22(C), T31N, R6W

Rio Arriba Co., NM


**Elevation:** 6269' GR **API #:** 30-039-26920

Tops	Depth	
Kirtland	2441'	
Pictured Cliffs	3116`	
Cliff House	5296'	
Point Lookout	5560'	
Mancos	5876'	
Dakota	7820'	

<u>CliffHouse/Menefee</u> 5066' - 5509' (17, 0 33" holes) 80,000# of 20/40 sand in 1806 BBI's slick water

Point Lookout 5562' - 5783' (28, 0 33" holes) 80,720# of 20/40 sand in 1933 BBI's slick water.

<u>Dakota</u> 7822' - 7880' (11, 0 46'' holes) 85,400# of 20/40 Ottawa sand & 6000# 14/30 Flex sand carried in 20Q Vistar foam



HOLE SIZE	CASING	CEMENT	CU. FT.	CMT TOP
14 3/4"	10 3/4"	425 s x	595 cu.ft.	surface
9 7/8"	7 5/8"	780 s x	1472 cu.ft.	surface
6 3/4"	5 1/2"	285 s x	574 cu.ft.	3500'

PBTD @ 7943'