

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-045-33367 Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: XTO Energy, Inc.	Contact: James McDaniel
Address: 382 Road 3100, Aztec, New Mexico 87410	Telephone No.: (505) 333-3701
Facility Name: Fred Feasel H #1F (30-045-33367)	Facility Type: Gas Well

Surface Owner: Federal	Mineral Owner:	Lease No.:
------------------------	----------------	------------

LOCATION OF RELEASE

Unit Letter B	Section 33	Township 28N	Range 10W	Feet from the 665	North/South Line FNL	Feet from the 1965	East/West Line FEL	County San Juan
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	--------------------

Latitude: 36.62420 Longitude: -107.89873

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 BBL.	Volume Recovered: ~10
Source of Release: Leaking Water Tank	Date and Hour of Occurrence: 12/26/11 - 12:30	Date and Hour of Discovery: 12/26/11 - 12:30
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD DEC 30 '11	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV.	

If a Watercourse was Impacted, Describe Fully.*

DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

On December 26, 2011, a leak was discovered in the above ground water tank at the Fred Feasel H #1F well site. Approximately 10 bbls of produced water was leaked into the lined berm that contained the produced water tank. The leak was stopped, and the tank will be repaired and put back into service.

Describe Area Affected and Cleanup Action Taken.*

On December 26, 2011, approximately 10 bbls of produced water was recovered from inside the lined berm using a water truck. No produced water left the lined bermed area. No further action is required regarding this release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: James McDaniel, CHMM #15676	Approved by District Supervisor: 	
Title: EH&S Supervisor	Approval Date: 1/09/2012	Expiration Date:
E-mail Address: James_McDaniel@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/28/2011	Phone: 505-333-3701	

nJK 1200948963

